Office	2:10 PM	State of New Me	xico	Form <i>C-103</i>			
<u>District I</u> – (575) 393-6161	Energy,	Energy, Minerals and Natural Resources			Revised July 18, 2013		
1625 N. French Dr., Hobbs, NM 8824	10			WELL API NO. 30-025-09197			
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CO	OIL CONSERVATION DIVISION			T		
<u>District III</u> – (505) 334-6178	12	1220 South St. Francis Dr.			Lease FEE ⊠		
1000 Rio Brazos Rd., Aztec, NM 874 District IV – (505) 476-3460	10	Santa Fe, NM 87505			Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM	I	Santa 1 6, 1 111 0 7 3 0 5			Dease 140.		
87505 SUNDRY N	NOTICES AND REI	PORTS ON WELLS		7. Lease Name or U	Unit Agreement Name		
(DO NOT USE THIS FORM FOR PEDIFFERENT RESERVOIR. USE "A	ENCENTAL VIDEO GE						
PROPOSALS.)	EMERY KING SE 8. Well Number #004						
V 1	Gas Well	Other			#004		
2. Name of Operator				9. OGRID Number			
FAE II Operating LLC				329326	7'1 1		
3. Address of Operator 11757 Katy Freeway, Suite 1000, Houston, TX 77079				10. Pool name or W	/ildcat ATTIX; 7 RVRs-Q-GB		
	700, Houston, 1 X //	0/9		[3/240] LANGLIE M.	ATTIX; / KVKS-Q-GD		
4. Well Location	000 6 6	1 0011771	1' 1 165	0 0 0 1	D. C. II		
Unit Letter O	: <u>990</u> feet from				<u>EAST</u> line		
Section 01		Township 23S	Range 36		LEA County		
	11. Elevation GL 3400	(Show whether DR,	RKB, RT, GR, etc.,)			
12. Chec	k Appropriate B	ox to Indicate Na	ture of Notice, F	Report or Other Da	ta		
NOTICE OF	F INTENTION 1	ΓΟ:	SUB	SEQUENT REP	ORT OF:		
PERFORM REMEDIAL WORK	_		REMEDIAL WOR		LTERING CASING		
TEMPORARILY ABANDON	☐ CHANGE PL		COMMENCE DRI	_			
PULL OR ALTER CASING	☐ MULTIPLE C		CASING/CEMEN	T JOB	_		
DOWNHOLE COMMINGLE							
CLOSED-LOOP SYSTEM							
OTHER:			OTHER:				
					ncluding estimated date		
13. Describe proposed or co of starting any proposed proposed completion or		7 19.15.7.14 NMAC.	Tor Multiple Com	pietions. Attach went	oore diagram of		
of starting any proposed proposed completion or MIRU. Hot oil w/ paraffin disper BTD @ 3753'. Acidize w/ 500 % KCL water. TIH w/ 112 jts 2 N @ 3654'. EOT @ 3691'. RIF	rsant. POOH w/ rods gals Xylene, 5000 g -3/8" 4.7# J-55 tbg, H w/ 2" x 1-1/4" x 16	s, pump & tbg. TIH v als 15% NEFE acid, 2- 6' subs, TAC, 3 jt	w/ 4-3/4" mill tooth 1500# rock salt in is 2-3/8" tbg, SN, 4	bit. Tag fill @ 3687'. 16 bbls of brine water ' perf sub, MA w/ bull	Clean out scale to & flush w/ 800 bbls plug. TAC @ 3559'.		
of starting any proposed proposed completion or MIRU. Hot oil w/ paraffin disper BTD @ 3753'. Acidize w/ 500 % KCL water. TIH w/ 112 jts 2 N @ 3654'. EOT @ 3691'. RIF	rsant. POOH w/ rods gals Xylene, 5000 g -3/8" 4.7# J-55 tbg, H w/ 2" x 1-1/4" x 16	s, pump & tbg. TIH v als 15% NEFE acid, 2- 6' subs, TAC, 3 jt	w/ 4-3/4" mill tooth 1500# rock salt in is 2-3/8" tbg, SN, 4	bit. Tag fill @ 3687'. 16 bbls of brine water ' perf sub, MA w/ bull	Clean out scale to & flush w/ 800 bbls plug. TAC @ 3559'.		
of starting any proposed proposed completion or MIRU. Hot oil w/ paraffin disper PBTD @ 3753'. Acidize w/ 500 2% KCL water. TIH w/ 112 jts 2 SN @ 3654'. EOT @ 3691'. RIFMRG per rod, 2' sub & PR w/ lir	recompletion. rsant. POOH w/ rods gals Xylene, 5000 g 1-3/8" 4.7# J-55 tbg, H w/ 2" x 1-1/4" x 16 ner. RTP.	s, pump & tbg. TIH v als 15% NEFE acid, 2- 6' subs, TAC, 3 jt	w/ 4-3/4" mill tooth 1500# rock salt in is 2-3/8" tbg, SN, 4 10' GA, 3/4" x 2' L	bit. Tag fill @ 3687'. 16 bbls of brine water ' perf sub, MA w/ bull	Clean out scale to & flush w/ 800 bbls plug. TAC @ 3559'.		
of starting any proposed proposed completion or MIRU. Hot oil w/ paraffin disper PBTD @ 3753'. Acidize w/ 500 % KCL water. TIH w/ 112 jts 2 N @ 3654'. EOT @ 3691'. RIFMRG per rod, 2' sub & PR w/ lir	recompletion. rsant. POOH w/ rods gals Xylene, 5000 g 1-3/8" 4.7# J-55 tbg, H w/ 2" x 1-1/4" x 16 ner. RTP.	s, pump & tbg. TIH vals 15% NEFE acid, 2- 6' subs, TAC, 3 jt 5-4 RHBC pump w/	w/ 4-3/4" mill tooth 1500# rock salt in is 2-3/8" tbg, SN, 4 10' GA, 3/4" x 2' L	bit. Tag fill @ 3687'. 16 bbls of brine water ' perf sub, MA w/ bull S, 8- 1.5" K sinker bar	Clean out scale to & flush w/ 800 bbls plug. TAC @ 3559'.		
of starting any proposed proposed completion or MIRU. Hot oil w/ paraffin disper PBTD @ 3753'. Acidize w/ 500 2% KCL water. TIH w/ 112 jts 2 SN @ 3654'. EOT @ 3691'. RIFMRG per rod, 2' sub & PR w/ lir	rsant. POOH w/ rods gals Xylene, 5000 g 1-3/8" 4.7# J-55 tbg, H w/ 2" x 1-1/4" x 16 ner. RTP.	s, pump & tbg. TIH vals 15% NEFE acid, 2- 6' subs, TAC, 3 jt 5-4 RHBC pump w/	w/ 4-3/4" mill tooth 1500# rock salt in is 2-3/8" tbg, SN, 4 10' GA, 3/4" x 2' L	bit. Tag fill @ 3687'. 16 bbls of brine water ' perf sub, MA w/ bull S, 8- 1.5" K sinker bar	Clean out scale to & flush w/ 800 bbls plug. TAC @ 3559'.		
of starting any proposed proposed completion or MIRU. Hot oil w/ paraffin disper PBTD @ 3753'. Acidize w/ 500 2% KCL water. TIH w/ 112 jts 2 SN @ 3654'. EOT @ 3691'. RIEMRG per rod, 2' sub & PR w/ lin	rsant. POOH w/ rods gals Xylene, 5000 g 1-3/8" 4.7# J-55 tbg, H w/ 2" x 1-1/4" x 16 ner. RTP.	Rig Release Date	w/ 4-3/4" mill tooth 1500# rock salt in is 2-3/8" tbg, SN, 4 10' GA, 3/4" x 2' L	bit. Tag fill @ 3687'. 16 bbls of brine water ' perf sub, MA w/ bull S, 8- 1.5" K sinker bar 1/9/2021	Clean out scale to & flush w/ 800 bbls plug. TAC @ 3559'.		
of starting any proposed proposed completion or MIRU. Hot oil w/ paraffin disper PBTD @ 3753'. Acidize w/ 500 2% KCL water. TIH w/ 112 jts 2 SN @ 3654'. EOT @ 3691'. RIFMRG per rod, 2' sub & PR w/ lin	recompletion. rsant. POOH w/ rods gals Xylene, 5000 g y-3/8" 4.7# J-55 tbg, H w/ 2" x 1-1/4" x 16 ner. RTP.	Rig Release Date TITLE Sr	w/ 4-3/4" mill tooth 1500# rock salt in 1500# rbg, SN, 4 10' GA, 3/4" x 2' La t of my knowledge	bit. Tag fill @ 3687'. 16 bbls of brine water ' perf sub, MA w/ bull S, 8- 1.5" K sinker bar /9/2021 and belief.	Clean out scale to & flush w/ 800 bbls plug. TAC @ 3559'. s, 134- 0.75" rods w/ 3		

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 50478

CONDITIONS

Operator:	OGRID:
FAE II Operating LLC	329326
11757 Katy Freeway, Suite 725	Action Number:
Houston, TX 77079	50478
	Action Type:
	[C-103] Sub. Workover (C-103R)

CONDITIONS

Created By		Condition Date
kfortner	None	7/24/2024