Received by OCD 5/20/2025 1:46:39 PM

State of New Mexico

Phone: (505) 476-3441	Energy, Minerals and Natural Resource	ces Revised July 18, 201
General Information Phone: (505) 629-6116	Energy, witherais and reactar resource	WELL API NO. 30-007-20213
Online Phone Directory Visit:	OIL CONSERVATION DIVISIO	N
https://www.emnrd.nm.gov/ocd/contact-us/	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE X
	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
	ES AND REPORTS ON WELLS LS TO DRILL OR TO DEEPEN OR PLUG BACK TO .	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICA"	TION FOR PERMIT" (FORM C-101) FOR SUCH	VPR D
PROPOSALS.) 1. Type of Well: Oil Well G	8. Well Number 33	
2 Name of Operator	_	9. OGRID Number 328741
Wapiti Operation	ang LLC	
3. Address of Operator 1251 Lumpkin Rd, Houston TX	77043	10. Pool name or Wildcat Castle Rock Park - Vermejo Gas
4. Well Location	//043	Castle Rock Park - Verifiejo Gas
Unit Letter D:	1244 feet from the NORTH line as	nd 1019 feet from the WEST line
Section 17	Township 30N Range 18I	
17	11. Elevation (Show whether DR, RKB, RT,	<u> </u>
	8313' (GL)	
40 01 1		
12. Check Ap	propriate Box to Indicate Nature of N	otice, Report or Other Data
NOTICE OF INT	ENTION TO:	SUBSEQUENT REPORT OF:
	PLUG AND ABANDON 🗌 REMEDIAI	
 -		CE DRILLING OPNS. P AND A
	MULTIPLE COMPL CASING/C	EMENT JOB
DOWNHOLE COMMINGLE		
CLOSED-LOOP SYSTEM OTHER:	RECOMPLETION X OTHER:	
13. Describe proposed or complet		ails, and give pertinent dates, including estimated da
		ple Completions: Attach wellbore diagram of
proposed completion or recon	ipietion.	
Plan to add additional po	erforations and fracture stimulate zones from	349' to 1,906'.
•		

Detailed perforations are: $349-354+359-360 \mid 421-427 \mid 457-459 \mid 559-562 \mid 626-628 \mid 698-701 \mid 739-742 \mid 797-799 \mid 909-912 \mid 943-944 \mid 1389-1390 \mid 1453-1455 \mid 1482-1484 \mid 1522-1524+1540-1542 \mid 1557-1559 \mid 1905-1906$

Gas is produced up the casing, water up the tubing, and commingled in central facilities. NO need for onsite separation.

This well is currently connected to Wapiti's current gathering system which has sufficient pipeline, processing, storage, sales, and disposal capacity for the added volumes.

_			
Spud Date:	3/7/2001	Rig Release Date: 3/9/200	01
I hereby certif	y that the information above is true an	d complete to the best of my knowledg	e and belief.
SIGNATURE _.	Ed Skrljac	TITLE Raton Ops Manager	DATE 5-20-2025
Type or print r For State Use		E-mail address: eskrljac@wapit	ienergy.com PHONE: 713-365-8506
APPROVED I	BY:Approval (if any):	TITLE	DATE



Vermejo Park Ranch D-33

S-T-R: 17-T30N-R18E Colfax County, New Mexico API #: 30-007-20213

AFE: TBD

CURRENT

The D-33 is currently producing 18 mcfd and 3 bwpd. The well was originally spud in March of 2001 and completed between 1,847' and 2,137' in four stages using plug and perf and frac'd with N2 and a 30# linear gel. The well has cumulative production of 442 MMCF and 53 MBW.

OBJECTIVE

Move in a workover rig and pull the rods and tubing on this well. Afterwards we will perforate various coal seams throughout the wellbore then fracture stimulate utilizing coiled tubing and an isolation tool to individually treat the zones throughout the wellbore.

WELLBORE (see attached WBD)

SURFACE CASING: 8-5/8" 24# J-55 casing set at 305'. Cemented with 100 sx. Circulated 5 bbls cmt to surface.

PRODUCTION CASING: 5-1/2" 15.5# J-55 LTC @2,198'. Cemented with 345 sx cement. PBTD is 2,181'. Circ 24 bbls to surf. TOC is at surface. Burst of 5-1/2" csg is 4,810 psi.

Tubing string: 2-7/8" 6.5# J-55 tubing. EOT at 2,165'.

Current Perforations: 1,847' to 2,137' (overall). See WBD for exact perforations.

Proposed Recompletion Intervals

349-354 + 359-360 | 421-427 | 457-459 | 559-562 | 626-628 | 698-701 | 739-742 | 797-799 | 909-912 | 943-944 | 1389-1390 | 1453-1455 | 1482-1484 | 1522-1524 + 1540-1542 | 1557-1559 | 1905-1906

PROCEDURE

ISOLATE LOWER ZONES THEN PERFORATE NEW ZONES

- 1. Check all equipment is function tested and rated to appropriate working pressure. Pull test ground anchors prior to workover rig moving on location. Plan to perform daily JSA's.
- 2. MIRU workover rig. Unhang rods. POOH standing back.
- 3. ND wellhead. Screw on 7-1/16" X 5M BOPE. Pressure test BOPS to 4,000 psi.
- 4. POOH standing back tubing.
- 5. P/U 4.75" bit and scraper and rbih to 2,165'. POOH.
- 6. Top connection on lwr master valve is 5-1/2" 8rd/LTC. MIRU e-line. RIH and perforate the following intervals:
 - a. 349-354 + 359-360
 - b. 421-427
 - c. 457-459
 - d. 559-562
 - e. 626-628
 - f. 698-701
 - g. 739-742
 - h. 797-799
 - i. 909-912
 - j. 943-944
 - k. 1389-1390
 - l. 1453-1455
 - m. 1482-1484
 - n. 1522-1524 + 1540-1542
 - o. 1557-1559
 - p. 1905-1906
 - q. ALL 3 SPF / 120 DEG PHASING WITH 3-1/8" GUN
- 7. RDMO e-line.
- 8. RBIH with tubing and bit and scraper to 2,165'.
- 9. POOH laying down tubing. ND BOPE, NU 5-1/2" lwr master valve. RDMO workover rig and all auxiliary equipment to make room for frac equipment.

FRACTURE STIMULATE VIA STRADDLE PACKER SYSTEM

- 10. Spot frac tanks (# determined by total estimated fluid volume for job) and sand king.
- 11. MIRU 2-7/8" CTU with straddle packer isolation tool. MIRU frac pumps, nitrogen unit, chem add and frac van. Get on depth by tagging btm and adjusting counter.
- 12. Fracture stimulate all additional perforations in pre-determined stages based on perforation proximity.
- 13. Once all stages have been pumped, RIH to PBTD and circulate well clean. POOH with CTU and close in master valve. RDMO CTU and all auxiliary equipment.

RUN TUBING AND RODS AND RETURN TO PRODUCTION

- 14. MIRU workover rig. ND lower master, NU bope.
- 15. RBIH mill to 2,165'. Then run rods and tbg to same depths as prior to workover.
- 16. N/D BOPE, N/U wellhead/flow tee. RIH with pump and rods and space out as needed.
- 17. Load tubing with FSW. Verify pump action. Open well up as per flowback program.



Vermejo Park Ranch D-33

1,244' FNL & 1,019' FWL Sec 17-T30N-R18E Colfax Co, NM

15" hole /

11" hole /

API: 30-007-20213 WI: 1.0000000 NRI: 0.9300000

Cmt'd w/ 100 sx cement. Cmt'd with 100 sx. Circulated 5 bbls to surface.

CURRENT

12-3/4" conductor pipe set at 17'

8 5/8" 24# J-55 surface casing set at 305'

CURRENT WELLBOERE SCHEMATIC

GL: 8,313'
RKB: 8,313'
Spud: 3/7/2001
TD date: 3/8/2001
Completed: 6/19/2001
Last workover: 3/24/2004
Last mod:

PROD TUBING DETAIL (3/24/2004)

KB elevation: 0.0'
68 joints of 2-7/8" tubing 2,125.9
2-7/8" seat nipple 2,127.0
2-7/8" m tubing 2,158.5
2-7/8" x 2-3/8" x-over 2159.0
2-3/8" sub 2,165.1
End of Tubing 2165.1


ROD AND PUMP DETAIL (3/24/2004)

16' x 1-1/4" polish rod (2) 3/4" x 8' ponys (74) 3/4" rods (10) 7/8" rods 7/8" x 4' guide pony

SLICKLINE AND OTHER INFORMATION:

5-1/2" 23# M-50 CASING SPECS

ID - 4.950" Drift - 4.825" Burst - 4,810 psi Collapse - 4,040 psi





Vermejo Park Ranch D-33

1,244' FNL & 1,019' FWL Sec 17-T30N-R18E

30-007-20213 WI: 1.0000000

CURRENT WELLBOERE SCHEMATIC

GL: 8,313' RKB: 8,313' Spud: 3/7/2001 TD date: 3/8/2001 Completed: 6/19/2001 Last workover: 3/24/2004 Last mod:

PROD TUBING DETAIL (3/24/2004)

0.0' KB elevation: 68 joints of 2-7/8" tubing 2,125.9 2-7/8" seat nipple 2,127.0 2-7/8" m tubing 2.158.5 2159.0 2-7/8" x 2-3/8" x-over 2-3/8" sub 2.165.1 **End of Tubing** 2165.1


ROD AND PUMP DETAIL (3/24/2004)

16' x 1-1/4" polish rod (2) 3/4" x 8' ponys (74) 3/4" rods (10) 7/8" rods 7/8" x 4' guide pony

SLICKLINE AND OTHER INFORMATION:

5-1/2" 23# M-50 CASING SPECS

ID - 4.950" Drift - 4.825' Burst - 4,810 psi Collapse - 4,040 psi



348 bbls & 285,000 scf 72Q WF30

ISIP - 485 psig

4 SPF (05/18/2001)

TD - 2,370 TVD - 2,370'

7-7/8" hole PBTD - 2,181" 5-1/2" 15.5 J-55 set at 2198'. Cmt'd with 345 sx. Circluated 24 bbls to surface.

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 465349

CONDITIONS

Operator:	OGRID:
Wapiti Operating, LLC	328741
1251 Lumpkin Rd	Action Number:
Houston, TX 77043	465349
	Action Type:
	[C-103] NOI Recompletion (C-103E)

CONDITIONS

Created By	Condition	Condition Date
ward.rikala	Notify the OCD inspection supervisor via email 24 Hours Prior to beginning operations.	5/22/2025
ward.rikala	All conducted logs shall be submitted to the OCD as a [UF-WL] EP Well Log Submission (WellLog).	5/22/2025
ward.rikala	A C-104 packet is required if, a pool is added, or perforations are added above or below existing perfs.	5/22/2025
ward.rikala	Down Hole Commingle order is required prior to commingling of production.	5/22/2025