| eceined by Copy to Spent pride David 2:25 P    | <sup>M</sup> State of New Mexico   | Form C-103 <sup>1 of</sup>           |
|--|--|--------------------------------------|
| Office<br>District I – (575) 393-6161          | Energy, Minerals and Natural Resources   | Revised July 18, 2013                |
| 1625 N. French Dr., Hobbs, NM 88240            |  | WELL API NO.                         |
| District II $-$ (575) 748-1283                 |  | 30-015-27096                         |
| 811 S. First St., Artesia, NM 88210            | OIL CONSERVATION DIVISION  | 5. Indicate Type of Lease            |
| <u>District III</u> - (505) 334-6178           | 1220 South St. Francis Dr.   | STATE FEE                            |
| 1000 Rio Brazos Rd., Aztec, NM 87410           | Santa Fe, NM 87505   |                                      |
| <u>District IV</u> $-$ (505) 476-3460          | Sana 10, 1001 87505  | 6. State Oil & Gas Lease No.         |
| 1220 S. St. Francis Dr., Santa Fe, NM<br>87505 |  |                                      |
|  | ES AND REPORTS ON WELLS  | 7. Lease Name or Unit Agreement Name |
| DIFFERENT RESERVOIR. USE "APPLICA              | LS TO DRILL OR TO DEEPEN OR PLUG BACK TO A<br>TION FOR PERMIT" (FORM C-101) FOR SUCH | POKER LAKE 32 STATE                  |
| PROPOSALS.)<br>1. Type of Well: Oil Well       | as Well 🗌 Other  | 8. Well Number                       |
| 2. Name of Operator                            |  | 9. OGRID Number                      |
| OXY USA INC                                    |  | 16696                                |
| 3. Address of Operator                         |  | 10. Pool name or Wildcat             |
| P.O. BOX 4294 HOUSTON,                         | TX 77210   | [53815] SAND DUNES;DELAWARE, WEST    |
| 4. Well Location                               |  | -                                    |
| Unit Letter F: 19                              | 980 feet from the NORTH line and 19  | 80feet from the <u>WEST</u> line     |
| Section 32                                     | Township 23S Range 31E   | NMPM County EDDY                     |
|  | 11. Elevation (Show whether DR, RKB, RT, GR, etc.                                    |                                      |
|  |  |                                      |

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

| NOTICE OF INTENTION TO:   |                  | SUBSEQUENT REPORT OF: |                                 |   |
|---|------------------|-----------------------|---------------------------------|---|
| PERFORM REMEDIAL WORK   | PLUG AND ABANDON |                       | REMEDIAL WORK ALTERING CASING   | ] |
| TEMPORARILY ABANDON   | CHANGE PLANS     |                       | COMMENCE DRILLING OPNS. P AND A | ł |
| PULL OR ALTER CASING  | MULTIPLE COMPL   |                       | CASING/CEMENT JOB               |   |
| DOWNHOLE COMMINGLE  |                  |                       |                                 |   |
| CLOSED-LOOP SYSTEM  |                  |                       |                                 |   |
| OTHER:  |                  |                       | OTHER:                          | ] |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date |                  |                       |                                 |   |

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

THE FINAL WELLBORE AND PA JOB NOTES ARE ATTACHED. THE CUT AND CAP WAS COMPLETE ON 5/6/2025.

| Spud Date:   | Rig Release Date:                               |                     |
|--|---|---------------------|
| I hereby certify that the information above is true and co | omplete to the best of my knowledge and belief. |                     |
| SIGNATURE Atepher Janaah                                   | _TITLE_REGULATORY ENGINEER                      | _DATE 5/21/2025     |
| Type or print name STEPHEN JANACEK<br>For State Use Only   | E-mail address: <u>STEPHEN_JANACEK@OXY.COM</u>  | PHONE: 713-493-1986 |
| APPROVED BY:<br>Conditions of Approval (if any):           | _TITLE  | _DATE               |

## POKER LAKE 32 STATE #006 30-015-27096





•

## POKER LAKE 32 STATE #006 30-015-27096 PA JOB NOTES

| Start Date | Remarks  |
|------------|--|
| 4/3/2025   | Road rig & all equipment to location   |
| 4/3/2025   | Spot in equipment. Rig up pulling unit.  |
| 4/3/2025   | Rig up all plugging equipment  |
| 4/3/2025   | 0 PSI on TBG, 150 PSI on CSG, 0 PSI on Surface                                     |
| 4/3/2025   | Took 2 BBLs, PSI test TBG to 1000 PSI & held good                                  |
| 4/3/2025   | Un-seat pump & remove polish rod   |
| 4/3/2025   | Lay down 14-1" rods  |
| 4/3/2025   | Install hanging tool. Close all valves. Secure location                            |
| 4/4/2025   | Crew travel to location  |
| 4/4/2025   | Crew HTGSM. Discuss hand & finger placement  |
| 4/4/2025   | 100 PSI on TBG, 250 PSI on CSG, 0 PSI on Surface CSG                               |
| 4/4/2025   | Operator set COFO (high & low setting)   |
| 4/4/2025   | Pump 20 BBLs of BW down TBG. Bled down CSG to tank                                 |
|            | Lay down 80-1" Rods. Begin to lay down 7/8 rods. 7/8 rods H.D. had to hotshot      |
| 4/4/2025   | different back up for rod tonges   |
|            | Off load BOPE. Accumaltor PSI up. Function Test BOPE. Rams & Blinds close in       |
| 4/4/2025   | 1.2 seconds  |
| 4/4/2025   | Crew took break  |
| 4/4/2025   | Lay down Rods (109-7/8, 111-3/4, 4-1.5' K-Bar, Inset Pump)                         |
| 4/4/2025   | Pump 100 BBLs of BW down CSG   |
| 4/4/2025   | Nipple down wellhead   |
| 4/4/2025   | Nipple up BOPE & Rig up working floor  |
|            | Install TIW Valve. Close BOPE & Lock Pins. Close all valves. Secure Location       |
|            | Rig crew travel home   |
|            | Crew travel to location  |
|            | Crew HTGSM. Discuss hand & finger placement  |
|            | 0 PSI on TBG, 0 PSI on CSG, 0 PSI on Surface CSG                                   |
| 4/5/2025   | POOH w/ 244 Jts of TBG. Lay down BHA   |
| 4/5/0005   | Rig up Key wireline. RIH w/ 5.5' CIBP. Set @ 7686'. POOH w/ wireline. Rig down     |
| 4/5/2025   | Key Wireline   |
| 4/5/2025   | RIH w/ 102 Jts of TBG to 3288'. Too windy to continue to run TBG in wellbore       |
| 4/5/2025   | Loaded TBG w/ 190 BBLs of fresh water.   |
|            | PSI test wellbore to 500 PSI & leaked off slowly. Possible air pocket in wellbore. |
| 4/5/2025   | Will re-attempt following day  |
|            |  |
| 4/5/2025   | Install TIW Valve. Close BOPE & lock pins. Close all valves. Secure Location       |
| 4/5/2025   | Crew travel home   |

•

| []       |  |
|----------|--|
|          | Crew travel to location  |
| 4/7/2025 | Crew HTGSM. Discuss hand & finger placement                                      |
| 4/7/2025 | 0 PSI on TBG, 0 PSI on CSG, 0 PSI on Surface CSG                                 |
| 4/7/2025 | Pump 140 BBLs of fresh water @ 2 BPM @ Did not hold                              |
| 4/7/2025 | POOH w/ 102 JTs of TBG   |
|          | Rig up Renegade Wireline. RIH w/ 5.5" CIBP. Tag previous CIBP @ 7670'. Set CIBP  |
| 4/7/2025 | @ 7620'. POOH w/ wireline  |
| 4/7/2025 | RIH w/ 102 JTs of TBG to 3288'.  |
| 4/7/2025 | Est rate, Circulated well w/ 60 BBLs of fresh water                              |
| 4/7/2025 | PSI test wellbore to 500 PSI & held good for 30 minutes                          |
| 4/7/2025 | POOH w/ TBG  |
| 4/7/2025 | Top fill wellbore. Bubble leak test performed. Good Test                         |
| 4/7/2025 | Close BOPE & Lock Pins. Close all valves. Secure Location                        |
| 4/7/2025 | Crew travel home   |
| 4/8/2025 | Crew travel to location  |
| 4/8/2025 | Crew HTGSM. Discuss hand & finger placement                                      |
| 4/8/2025 | 0 PSI on CSG, 0 PSI on Surface CSG   |
|          | Rig up Renegade Wireline. RIH w/ CBL Tools. Tag CIBP @ 7620'. Run CBL to         |
| 4/8/2025 | surface. Rig down wireline.  |
| 4/8/2025 | RIH w/ 238 Jts of TBG. Tag CIBP @ 7620'.   |
|          |  |
| 4/8/2025 | Begin to circulate well & TBG PSI up w/ 6 BBLs. Attempt to un-plug TBG & no luck |
| 4/8/2025 | POOH w/ 56 JTs of TBG. Found 3 Jts plugged w/ paraffin.                          |
| 4/8/2025 | Circulated TBG & begin to circulate.   |
| 4/8/2025 | RIH w/ TBG & Tag CIBP @ 7620.  |
|          |  |
| 4/8/2025 | Circulated well w/ 135 BBLs of BW w/ 40 BBLs w/ 10 sxs of flex gel @ 3 BPM.      |
|          |  |
| 4/8/2025 | Spot 4.7 BBLs (25 sxs) of Class H CMT & Displaced down to 7400' w/ 42.8 BBLs     |
| 4/8/2025 | POOH w/ 50 Jts of TBG. Lay down 7 JTs of TBG                                     |
|          |  |
| 4/8/2025 | Install TIW Valve. Close BOPE & Lock Pins. Close all valves. Secure Location     |
| 4/8/2025 | Crew travel home   |
|          | Crew travel to location  |
|          | Crew HTGSM. Discuss hand & finger placement                                      |
|          | 0 PSI on TBG, 0 PSI on CSG, 0 PSI on Surface PSI                                 |
| 4/9/2025 | Operator set COFO (high & low setting)   |
| 4/9/2025 | RIH w/ TBG. Tag CMT plug @ 7369'   |
| 4/9/2025 | Lay down 65 Jts of TBG.  |
|          | Est Rate. Spot 6 BBLs (25 sxs) of Class C CMT from 5357'- 5110' & diplaced down  |
| 4/9/2025 | w/ 29.5 BBLs   |
| 4/9/2025 | POOH w/ TBG. Lay down 8 Jts of TBG   |
| 4/9/2025 | Wait on CMT to set up  |
| 11012020 |  |

•

| 4/9/2025  | Lay down 30 JTs of TBG to 4180'  |
|-----------|--|
|           | Spot 48 BBLs (205 sxs) of Class C CMT at 5087' & displaced down to 2175' w/      |
| 4/9/2025  | 12.5 BBLs  |
| 4/9/2025  | POOH w/ 32 Jts of TBG  |
| 4/9/2025  | Lay down 102 JTs of TBG  |
| 4/9/2025  | Close BOPE & Lock Pins. Close all valves. Secure Location                        |
| 4/9/2025  | Rig crew travel home   |
| 4/10/2025 | Crew travel to location  |
| 4/10/2025 | Crew HTGSM. Discuss hand & finger placement                                      |
| 4/10/2025 | 0 PSI on CSG, 0 PSI on Surface CSG   |
| 4/10/2025 | Operator set COFO (high & low setting)   |
| 4/10/2025 | RIH w/ TBG. Tag CMT Plug @ 2173'.  |
| 4/10/2025 | POOH w/ TBG  |
| 4/10/2025 | RIH w/ AD1 PKR, 1 JT & 10' sub   |
|           | Rig up Key wireline. RIH w/ 1-3/8" perf gun. Perforate CSG @ 2100' POOH w/       |
| 4/10/2025 | wireline   |
|           |  |
|           | Est Injection & PSI up to 1500 PSI w/ 10 BBLs. PSI up down intermeidate CSG w/ 6 |
| 4/10/2025 | BBLs. Contact Bobby Trujillo w/ NMODC to perfoate CSG @ 1850'.                   |
|           | Rig up Key wireline. RIH w/ 1-3/8" perf gun. Perforate CSG @ 1850'. POOH w/      |
| 4/10/2025 | wireline & rig down  |
| 4/10/2025 | Est Injection rate 2.5 BPM @ 300 PSI w/ 20 BBLs                                  |
| 4/10/2025 | RIH w/ TBG to 2173'.   |
| 4/10/2025 | Rig crew took lunch break  |
|           | Est Rate. Spot 7 BBLs (30 sxs) of Class C CMT from 2173' to 1850' & displaced    |
| 4/10/2025 | down to 10.5 BBLs  |
| 4/10/2025 | Lay down TBG   |
| 4/10/2025 | Nipple down BOPE   |
| 4/10/2025 | Nipple up blind flange   |
|           | Est Rate 2 BPM @ 300 PSI. Circulate 110 BBLs (470 sxs) of Class C CMT &          |
| 4/10/2025 | cirulcated out of intermdiate. Wash up CMT truck                                 |
|           | Rig down pulling unit  |
| 4/10/2025 | Secure Location.   |
| 4/10/2025 | Crew travel home   |
| 4/11/2025 | Nipple down wellhead. Verify CMT to surface. Well is plugged                     |
|           | Travis w/ Smith & Son Cut & CApped wellhead. Duamondback Dispoal removed         |
| 5/6/2025  | wellhead and cleaned up wellsite   |

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

## State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

| Operator:             | OGRID:                         |
|-----------------------|--------------------------------|
| OXY USA INC           | 16696                          |
| P.O. Box 4294         | Action Number:                 |
| Houston, TX 772104294 | 465966                         |
|                       | Action Type:                   |
|                       | [C-103] Sub. Plugging (C-103P) |
|                       |                                |

CONDITIONS

| Created By |   | Condition<br>Date |
|------------|---|-------------------|
| gcordero   | Clean Location in accordance with 19.15.25.10 NMAC. | 7/3/2025          |
| gcordero   | Submit C-103Q within one year of plugging.          | 7/3/2025          |

Page 6 of 6

Action 465966