## State Of New Mexico Energy, Minerals and Natural Resources Department

20-Aug-25

## ADVANCED WIRELESS COMMUNICATIONS, L.L.C.

**Pre Enforcement Notification** 

24 Road 1956 Farmington, NM 87401

## Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the Compliance Officer copied on this letter, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

## INSPECTION DETAIL SECTION

[30-045-34323] DEWEY #001		OGRID: 371710 A-19-30N-13W 760		NL 1095 FEL
Inspection Date	Type Inspection	Inspector	In	spection No.
8/20/2025	Routine Inspection	[CZS] Clarence Smith	iCZ	ZS2523245729
Violation	Title Co		<b>Corrective Action Due</b>	
cCZS2523262299 19.15.10.8 Safety Procedures for Drilling and Production Fire Hazard			d 11/18/2025	
(Weeds around well head and equipment need to be removed.)				
cCZS2523262300 19.15.29 Releases Surface Leaks/Spills			11/18/2025	
(Staining brown ~ 30' x 20' needs to be removed.)				
cCZS2523262301 19.15.16.8 Sign on Wells Inaccurate Information			11/18/2025	
(Sign missing unit letter or 1/4 1/4 section.)				

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.