Received by OCD; 8/18/2025 11:36:17 AM State of New Mexico Phone: (505) 476-3441 Fax: (55) 476-3462 Energy, Minerals and Natural Resources General Information WELL API NO. Phone: (505) 629-6116 30-025-20776 OIL CONSERVATION DIVISION Online Phone Directory Visit: 5. Indicate Type of Lease https://www.emnrd.nm.gov/ocd/contact-us/ 1220 South St. Francis Dr. STATE FEE Santa Fe, NM 87505 6. State Oil & Gas Lease No. B-1732 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH Sunshine state 8. Well Number 1. Type of Well: Oil Well Gas Well Other 9. OGRID Number 2. Name of Operator Fulfer Oil and Cattle Co. LLC 141402 10. Pool name or Wildcat 3. Address of Operator P.O.Box 1224 Jal New Mexico 88252 Queens/grayburg /san andraes 4. Well Location line and 2209 . 990 feet from the FNL Unit Letter C feet from the FWL line Township 21S 19 County LEA Section **NMPM** 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3532 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING □ COMMENCE DRILLING OPNS. X **TEMPORARILY ABANDON** CHANGE PLANS P AND A MULTIPLE COMPL CASING/CEMENT JOB PULL OR ALTER CASING DOWNHOLE COMMINGLE **CLOSED-LOOP SYSTEM** OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. The well was plugged as follows: The well was plugged as follows:

Called 48 hrs before work begins. Set 7" CIBP at 3717' pressure test casing to 500#. Run Cement bond log TOC 2660.

Circulate to Welll With MLF and spot 80 sx Class c cement on top of CIBP from 3717-3253 tagged at 3325 oked OCD.

Perforate at 2603 test tight spot 25 sx Class C CementF/2653-2503 WOC and tag at 2525. ocd wanted 25 more sx so added, NO tag Required Perf at 1270 tight, oked spot 40 sx Class C Cement 1335/1102' pressure up and close in well.woc tagged at 1270. respot 30 sx per OCD pressure up Tagged at 1085' oked by ocd. perf at 317, test tight, oked spot 25 sx f/ 336-191. squeeze, tag at 240' oked.

Perforate at 150' and circulate the well out w/ 50 sx Class C Cement plug fell to 18' cut off Casings and filled both sides w/cement. Next day Cut off the casings 8" Below Ground level, Install DHM and weld cap install conduit pipe around surface and DHM and cement w/16 sx cement. Remediation will follow by panther per slo reds well bore schematic is attached. Remediation will follow by panther per slo regs. well bore schematic is attached cut off date 10/18/2024 Spud Date: Rig Release Date: 4/13/1964 5/6/1964

TITLE operations supervisor

DATE 11/27/2024

DATE

E-mail address: <u>mdennis3082Q@gmail.com</u> PHONE: 575-395-9970

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

TITLE

Conditions of Approval (if any):

SIGNATURE

Type or print name \_ For State Use Only

APPROVED BY:

michael Dennis

Michael Dennis

Prospect:	Fulfer Oil and Cattle Co LLC.		
lease:	Sunshine State 1		
Location:			
Footage:	990-FNL-2209-FWL		
Section:	UL-C, SEC 19, T21S, R37E		
Block:			
Township:			
Survey:			
County:			
Lat:			
Long:			
	Elevations:		
GL:	3,519		
KB:			
KB Calc:			
ck w/log2			


Date	History
	Called 48 hrs before work begins
	Set 7" CIBP at 3717' pressure test casing to 500#
	run Cement bond log TOC 2660
	Circulate to Welll With MLF and spot 80 sx Class c cement on top of CIBP
	from 3717-3253 tagged at 3325 oked OCD.
	Perforate at 2603 test tight spot 25 sx Class C CementF/2653-2503
	WOC and tag at 2525. ocd wanted 25 more sx so added, NO tag Required
	Perf at 1270 tight,oked spot 40 sx Class C Cement 1335/1102' pressure up
	and close in well.woc tagged at 1270. respot 30 sx per OCD pressure up
	Tagged at 1085' oked by ocd.
	perf at 317,test tight, oked spot 25 sx f/ 336-191. squeeze, tag at 240' oked
	Perforate at 150' and circulate the well out w/ 50 sx Class C Cement
	plug fell to 18' cut off Casings and filled both sides w/cement. Next day
	Cut off the casings 8" Below Ground level , Install DHM and weld cap
	install conduit pipe around surface and DHM and cement w/16 sx cement.
	Remediation will follow by panther per slo regs.
	cut off date 10/18/2024
	•

	Tubing Detail (top to bottom)  Description		
Joints	Description	Footage	Depth
	Total depth		

	Rod Detail (top to bottom)		
Rods	Description	Footage	Depth
	total depth		

Pumping Uni Weatherford Maximizer C320-305-100

Updated:	By:
11/27/24	Mike Dennis



Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory <a href="https://www.emnrd.nm.gov/ocd/contact-us">https://www.emnrd.nm.gov/ocd/contact-us</a>

## State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 496704

## **CONDITIONS**

Operator:	OGRID:
FULFER OIL & CATTLE LLC	141402
P.O. Box 1224	Action Number:
Jal, NM 88252	496704
	Action Type:
	[C-103] Sub. Plugging (C-103P)

## CONDITIONS

Created By		Condition Date
gcordero	Clean Location in accordance with 19.15.25.10 NMAC.	9/18/2025
gcordero	Submit C-103Q within one year of plugging.	9/18/2025