

State Of New Mexico
Energy, Minerals and Natural Resources Department

07-Oct-25

DUGAN PRODUCTION CORP

Pre Enforcement Notification

PO Box 420
Farmington, NM 87499

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the Compliance Officer copied on this letter, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

[30-045-33725] IRISH COM #090S

OGRID: 6515

O-11-26N-13W 1200 FSL 1600 FEL

Inspection Date	Type Inspection	Inspector	Inspection No.
10/7/2025	Routine Inspection	[TV] Thomas Vermersch	iTV2528047837
Violation	Title		Corrective Action Due
cTV2528060260	19.15.16.8 Sign on Wells Inaccurate Information (Well sign is missing the required footage.)		1/5/2026
cTV2528060261	19.15.29 Releases Surface Leaks/Spills (There is some staining around the wellhead and underneath that pumpjack that needs removed and cleaned up.)		1/5/2026
cTV2528060262	19.15.10.8 Safety Procedures for Drilling and Production General Housekeeping Required (There is some liner exposed near the pit burial marker that needs removed.)		1/5/2026

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.