Office Engage M	tate of New Mexico inerals and Natural Resources	Form C-103 Revised July 18, 2013	
<u>District I</u> – (575) 393-6161 Effergy, IVI 1625 N. French Dr., Hobbs, NM 88240	inerais and Natural Resources	WELL API NO. 30-015-01900	
611 S. Filst St., Attesta, NW 66210	NSERVATION DIVISION	5. Indicate Type of Lease	
1000 Die Drames Dd. Artes NIM 97410	South St. Francis Dr.	STATE FEE	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	anta Fe, NM 87505	6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPO (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR	TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name Humble State	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERM PROPOSALS.) 1. Type of Well: Oil Well Gas Well C	other	8. Well Number 001	
Name of Operator Southwestern Inc.		9. OGRID Number 21386	
3. Address of Operator		10. Pool name or Wildcat	
1304 W. Broadway, Hobbs, NM 88240 4. Well Location		Artesia; Queen-Grayburg-San Andres	
	rom the North line and 9	90feet from theEastline	
	ship 18S Range 28E	NMPM County EDDY CO., NM	
11. Elevation (Show whether DR, RKB, RT, GR, etc.		
12. Check Appropriate Bo	ox to Indicate Nature of Notice,	Report or Other Data	
NOTICE OF INTENTION TO		SSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐ PLUG AND AB TEMPORARILY ABANDON ☐ CHANGE PLAI		RK	
PULL OR ALTER CASING MULTIPLE CO			
DOWNHOLE COMMINGLE ☐ CLOSED-LOOP SYSTEM ☐			
OTHER:	OTHER:		
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion.	(Clearly state all pertinent details, an 19.15.7.14 NMAC. For Multiple Co	ad give pertinent dates, including estimated date impletions: Attach wellbore diagram of	
XTO Energy Inc., respectfully submits this NOI to Please see the attached P&A procedure with curr			
rease see the account of the processing with early	circuita propossa 1122 s 15. year	,	
Spud Date: 09/19/1958	Rig Release Date:		
	<u> </u>		
I hereby certify that the information above is true and	complete to the best of my knowled	ge and belief.	
J. D. P. Lland			
SIGNATURE COLUMN TO THE SIGNAT	TITLE President	DATE 23 Oct 2025	
Type or print name Rickey L. Houston For State Use Only	E-mail address: <u>Fickoryhond</u>	ah Quahoo. PHONE: 325-260-1678	
APPROVED BY:	TITLE	DATE	
Conditions of Approval (if any):			

PLUG AND ABANDON WELLBORE Humble State 001 EDDY COUNTY, NEW MEXICO Class II

AFE# PA.2024.13519

MASIP	MAOP	MAWP	Surface Csg Yield
1,000 psi	1,000 psi	3,000 psi	2950 PSI

SUMMARY: Plug and abandon wellbore according to BLM regulations.


Steps 1-8 shall be completed with Prep Rig

- 1) MIRU plugging company. Set open top steel pit for plugging.
- 2) POOH LD rods and pump.
- 3) ND WH and NU 3K manual BOP. Function test BOP.
- 4) POOH tbg.
- 5) MIRU WLU, RIH GR to 2,150'; RIH set CIBP at 2,110', pressure test to 500 PSI for 30 minutes.
- 6) Run CBL from 2,000' to surface. Please send CBL to engineering.
- 7) Dump bail 35' of Class cement from 2,110' to 2,075'. WOC and tag to verify.
- 8) ND BOP and NU Wellhead, RDMO.

Steps 9 and forward will be completed with P&A rig within 90 days from RDMO.


- 9) MIRU plugging company. Set open top steel pit for plugging
- 10) ND WH and NU 3K manual BOP. Function test BOP.
- 11) Spot 25 SKS Class C cement from 2,075' to 1,850'. (T/Queen, T/ Perf, T/Grayburg)
- 12)Spot 25 SKS Class C cement from 1,300' to TOC. WOC and tag to verify TOC. (T/7 Rivers)
- 13) MIRU WLU, perforate at TOC through 5-1/2" casing and at 210" through 5-1/2" & 8-5/8" casing.
- 14) Circulate Class C cement from TOC' to surface. (~370 SKS) (Surface Casing, T/7 Rivers, T/Queen)

- 15) ND BOP and cut off wellhead 5' below surface. RDMO PU, transport trucks, and pump truck.
- 16) Set P&A marker.
- 17) Pull fluid from steel tank and haul to disposal. Release steel tank.



of CIBP:2,110' to 2,075'. WOC and

Tag.



PBTD 2,376' TD 2,502'

Perfs: 2171'-87', 2230'-54', 2294'-2316' (4 spf)

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 525441

CONDITIONS

Operator:	OGRID:
XTO ENERGY, INC	5380
6401 Holiday Hill Road	Action Number:
Midland, TX 79707	525441
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
loren.diede	Notify the OCD inspection supervisor via email 24 hours prior to beginning Plug & Abandon (P&A) operations.	11/12/2025
loren.diede	Submit CBL tif file to NMOCD for upload into the Well Log File.	11/12/2025
loren.diede	Submit photo and GPS coordinates of the P&A marker with the C-103P subsequent P&A submission.	11/12/2025
loren.diede	The API# on the P&A marker must be clearly legible on the P&A marker photo.	11/12/2025
loren.diede	NMOCD does not consider this well to be within the LPCH restricted area and an above ground P&A marker is required.	11/12/2025