

Santa Fe Main Office
 Phone: (505) 476-3441
 General Information
 Phone: (505) 629-6116

Online Phone Directory Visit:
<https://www.emr.state.nm.us/od/directory>

State of New Mexico
 Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-103
 Revised July 18, 2013

<p>SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p> <p>1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other</p> <p>2. Name of Operator Sandlott Energy (Jackie Brewer DBA)</p> <p>3. Address of Operator P.O. Box 711 Lovington, NM 88260</p> <p>4. Well Location Unit Letter <u>C</u> : <u>1060</u> feet from the <u>North</u> line and <u>2380</u> feet from the <u>West</u> line Section <u>32</u> Township <u>18S</u> Range <u>28E</u> NMPM <u>Eddy</u> County</p>		WELL API NO. 30-015-02146
		5. Indicate Type of Lease <input checked="" type="checkbox"/> STATE <input type="checkbox"/> FEE <input type="checkbox"/> 6. State Oil & Gas Lease No.
		7. Lease Name or Unit Agreement Name Resler Yates State
		8. Well Number #061
		9. OGRID Number <u>154329</u>
		10. Pool name or Wildcat (3230) Artesia; Queen-Grayburg-San Andrews
<p>11. Elevation (Show whether DR, RKB, RT, GR, etc.)</p>		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK PLUG AND ABANDON
 TEMPORARILY ABANDON CHANGE PLANS
 PULL OR ALTER CASING MULTIPLE COMPL
 DOWNHOLE COMMINGLE
 CLOSED-LOOP SYSTEM
 OTHER:

SUBSEQUENT REPORT OF:

REMEDIAL WORK ALTERING CASING
 COMMENCE DRILLING OPNS. P AND A
 CASING/CEMENT JOB

OTHER:


13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Please see attached procedure & wellbore schematics

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE _____ DATE 11/12/2025

Type or print name Jackie Brewer E-mail address: _____ PHONE: _____
For State Use Only

APPROVED BY: _____ TITLE: _____ DATE: _____
 Conditions of Approval (if any):

Mountain Oil Company

Plug and Abandon

Submitted By: C. Key

Wellname: RESLER YATES #61

Location: 1580' FSL & 250' FEL; Sec 32, T18S, R28E; Eddy CO., NM

Date: August 8, 2025

API #: 30-015-02146

Surf Csg Set: 10"

Csg Size: 4 1/2"

Set @: 310

Set @: 2034'

Inter #1: 8 1/4"

Perfs: 2009'-2022'

Set @: 515'

Well is to be plugged & abandoned.


Procedure:

1. MIRU plugging crew.
2. ND WH & NU BOP.
3. POOH w/rods and tbg
4. Run wireline w/4 1/2" CIBP
5. Set CIBP @ 2000' (Top perf @ 2009)
6. POOH w/WL
7. Fill csg & test to 500# for 30 minutes
8. RIH w/WL & CBL to surface.
9. RIH w/tbg & tag CIBP
10. Spot 40 sks Class C neat cmt (545' +/-) on top CIBP. (Grayburg @1908, Queen @1514')
11. POOH w/tbg
12. WOC 6 hrs & tag plug @ 1464' or higher
13. Lay down pipe to 565'
14. Circulate approximately 45 sks Class C neat cmt to surface.
15. POOH LD cmt
16. WOC & confirm wellbore remains full
17. Cut off WH & install dry hole marker. Cut off anchors & clean location


*Perforating Job Company***Plug and Abandon**

18.

Vertical schematic (actual)



Revolving Top Casing



Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 524495

CONDITIONS

Operator: MEWBOURNE OIL CO P.O. Box 5270 Hobbs, NM 88241	OGRID:
	14744
	Action Number: 524495
	Action Type: [C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
loren.diede	Notify the OCD inspection supervisor via email 24 hours prior to beginning Plug & Abandon (P&A) operations.	11/13/2025
loren.diede	NMOCD does not consider this well to be within the LPCH restricted area and an above ground P&A marker is required. NMOCD requires that plug(s) be added to cover the 7 Rivers = (970') and Yates = (560') formation tops. Submit photo and GPS coordinates of the P&A marker with the final P&A reports. The API# on the marker is to be clearly legible. Run CBL from CIBP to surface. Submit the CBL tif file to NMOCD for uploading into the Well Log File.	11/13/2025