Submit I Copy To Appropriate District Office	State of New Mexico	Form C-103
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Re	WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIV	1SION 30-021-20414
District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis I	L5 Indicate Type of Lease
District IV - (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
	ICES AND REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PLUG BAG	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		CH West Bravo Dome Unit
1. Type of Well: Oil Well Gas Well Other X CO2		8. Well Number 341G
2. Name of Operator  Hess Corporation		9. OGRID Number
3. Address of Operator PO Box 840 Seminole TX 79360		10. Pool name or Wildcat
4. Well Location		West Bravo Dome CO2 Gas
Unit Letter G:	2420 feet from the N	line and 1650 feet from the E line
Section 34	Township <sup>19N</sup> Range	29E NMPM County Harding
A STATE OF THE STA	11. Elevation (Show whether DR, RKB,	RT, GR, etc.)
Control of the second s	4639 GR	
12. Check A	Appropriate Box to Indicate Nature	of Notice, Report or Other Data
NOTICE OF IN	ITENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON ☐ REM	MEDIAL WORK ☐ ALTERING CASING ☐
TEMPORARILY ABANDON DULL OR ALTER CASING .		MMENCE DRILLING OPNS.☐ P AND A ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐
DOWNHOLE COMMINGLE	MIDETIFLE COMPL CAS	INING/CEIVIEN I JOB
OTHER:	□ OTH	Fill Tag
13. Describe proposed or comp	leted operations. (Clearly state all pertine	ent details, and give pertinent dates, including estimated date
of starting any proposed we proposed completion or rec		Multiple Completions: Attach wellbore diagram of
1929 341G	ompletion.	
6/6/2012 Wireline tag	fill/PBTD	
, , , <u>, , , , , , , , , , , , , , , , </u>	*	
	•	
	·	
Spud Date: 11/15/2011	Rig Release Date:	06/06/2012
I haraby cartify that the information	above is true and complete to the best of	my knowledge and balisf
Thereby certify that the information	above is true and complete to the best of	my knowledge and beneft.
SIGNATURE Atta	TITLE Engineer	Tech DATE 06/11/2012
$\overline{\gamma}$	TITLE	DAIL
Type or print name Rita C Smith	E-mail address: rsi	mith@hess.com PHONE: 432-758-6726
For State Use Only	Martin TITLE DISTRI	PT CHDEDVICAD
APPROVED BY:	TITLE HISTORY	UI SUPERVISUR DATE 6/25/2012

Office	State of New Mexico	Form C-103	
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised August 1, 2011	
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283		WELL API NO. 30-021-20414	
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease	
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE X	
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505			
1	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		West Bravo Dome Unit	
1. Type of Well: Oil Well Gas Well Other X CO2		8. Well Number 341G	
2. Name of Operator  Hess Corporation		9. OGRID Number	
3. Address of Operator PO Box 840 Seminole TX 79360		10. Pool name or Wildcat	
	•	West Bravo Dome CO2 Gas	
4. Well Location	2420 feet from the N line and	1650 fact from the E line	
Omit Letter	itet from the the and	leet nom themile	
Section 34	Township 19N Range 29E	NMPM County Harding	
	11. Elevation <i>(Show whether DR, RKB, RT, GR, etc</i> 4639 GR		
	4037 GR		
12. Check A	appropriate Box to Indicate Nature of Notice	e, Report or Other Data	
NOTICE OF IN	TENTION TO SUI	BSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK □	PLUG AND ABANDON ☐ REMEDIAL WO		
TEMPORARILY ABANDON		RILLING OPNS. P AND A	
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEME	NT JOB 🗌	
DOWNHOLE COMMINGLE			
OTHER:	ac plug and tbg 📉 OTHER:	. п	
	leted operations. (Clearly state all pertinent details, a	nd give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion. 1929 341G WOS: Chase Frac plug to Bottom of rat hole & Run & set tbg. & AS1 packer			
day 1 MIRU Sundown PU & Pump 1	ruck. Hold JSA to discuss work & safety concerns.	•	
Kill well w/PW  ND WH & NU BOPs/stripper head,	/swivel		
PU & RIH w/mill & Ws.	No. 10. 10. 10. 10. 10. 10. 10. 10. 10. 10		
Dry drill on frac plug & push TOOH w/ mill & WS standing bac			
Flow to tank overnight day 2 Kill well with 8-16 bbls	FPW. ND Wellhead and NU BOP.		
PU & RIH w/ AS1 packer (w/blar			
	Circulate packer fluid. Latch onto packer.		
Pressure casing to 500#. Blee ND BOP's & NU WH.	ed down casing. Pressure tubing to 500#. Bleed off tubing	•	
	blanking plug. RDMO wireline. psi for 30 min and chart for NMOCD.		
	well over to production. * Note(s) 1. Hooking up to 5.5"	Tulsa Valve 2. AS-1 profile nipple 2.25"	
Spud Date: 11/15/2011	Rig Release Date:	·	
L		<u>·</u>	
	<del></del>		
I hereby certify that the information	above is true and complete to the best of my knowled	lge and belief.	
(d+1)			
SIGNATURE WOOL	TITLE Engineer Tech	DATE 06/13/2012 _	
	113 -3	. 420 250 6206	
Type or print name Rita C Smith	E-mail address: rsmith@hess	PHONE: 432-758-6726	
For State Use Only			
1 // 1	Man a de la compania		
APPROVED BY:	Martin TITLE DISTRICT SUPI	RVISOR DATE 6/25/20/2	