

Submit 1 Copy To Appropriate District Office
 District I - (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV - (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised August 1, 2011

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-021-20555
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/> P <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name West Bravo Dome Unit
8. Well Number 022J
9. OGRID Number 495
10. Pool name or Wildcat West Bravo Dome CO2 Gas
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4775 GR

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well Other CO2

2. Name of Operator Hess Corporation

3. Address of Operator PO Box 840 Seminole TX 79360

4. Well Location
 Unit Letter J : 1750 feet from the S line and 1335 feet from the E line
 Section 2 Township 18N Range 29E NMPM County Harding

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: Tag <input checked="" type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.
 1829 022J

6/6/2012 Wireline tag fill/PBTD

Spud Date: 04/09/2012 Rig Release Date: 06/06/2012

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rita C Smith TITLE Engineer Tech DATE 06/11/2012

Type or print name Rita C Smith E-mail address: rsmith@hess.com PHONE: 432-758-6726

For State Use Only

APPROVED BY: Ed Martin TITLE **DISTRICT SUPERVISOR** DATE 6/25/2012
 Conditions of Approval (if any):

Submit 1 Copy To Appropriate District Office
 District I - (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II - (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV - (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised August 1, 2011

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-021-20555
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/> P <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name West Bravo Dome Unit
8. Well Number 022J
9. OGRID Number 495
10. Pool name or Wildcat West Bravo Dome CO2 Gas
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4775 GR

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well Other X CO2

2. Name of Operator
Hess Corporation

3. Address of Operator PO Box 840 Seminole TX 79360

4. Well Location
 Unit Letter J : 1750 feet from the S line and 1335 feet from the E line
 Section 2 Township 18N Range 29E NMPM County Harding

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data.


NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPL <input type="checkbox"/> DOWNHOLE COMMINGLE <input type="checkbox"/>		SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS <input type="checkbox"/> P AND A <input type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/>	
OTHER: frac plug & tbg <input checked="" type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

WOS: Chase Frac plug to Bottom of rat hole & Run & set tbg. & AS1 packer
 Day 1 MIRU Sundown PU & Pump Truck. Hold JSA to discuss work & safety concerns.
 Kill well w/PW
 ND WH & NU BOPs/stripper head/swivel
 PU & RIH w/mill & WS.
 Dry drill on frac plug & push to at least 2360'
 TOOH w/ mill & WS standing back work string.
 Flow to tank overnight
 Day 2 Kill well with 8-16 bbls PW. ND Wellhead and NU BOP.
 PU & RIH w/ AS1 packer (w/blanking plug) & WS
 Set packer @ 2230 Feet. TOOH w/WS, laying down.
 PU & RIH w/ FG tubing (2.375"). Circulate packer fluid. Latch onto packer.
 Pressure casing to 500#. Bleed down casing. Pressure tubing to 500#. Bleed off tubing.
 ND BOP's & NU WH.
 MIRU WL service. RIH and pull blanking plug. RDMO wireline.
 Pressure test backside to 500 psi for 30 min and chart for NMOCD.
 RDMO PU. Clean location. Turn well over to production. * Note(s) 1. Hooking up to 5.5" Tulsa Valve 2. AS-1 profile nipple 1.5"

Spud Date: Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE Engineer Tech DATE 06/13/2012

Type or print name Rita C Smith E-mail address: rsmith@hess.com PHONE: 432-758-6726

For State Use Only

APPROVED BY:  TITLE **DISTRICT SUPERVISOR** DATE 6/25/2012

Conditions of Approval (if any):