

Submit 1 Copy To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
October 13, 2009

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. <b>3005920216</b>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name <b>BRAVO DOME CARBON DIOXIDE GAS UNIT (BDCDGU)</b>
8. Well Number <b>301</b>
9. OGRID Number <b>16696</b>
10. Pool name or Wildcat <b>BRAVO DOME CARBON DIOXIDE GAS UNIT 640 ACRE AREA</b>

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other **CO<sub>2</sub> SOURCE WELL**

2. Name of Operator  
**OXY USA Inc.**

3. Address of Operator  
**PO Box 303, AMISTAD, NEW MEXICO 88410**

4. Well Location  
Unit Letter **G** : **1650** feet from the **NORTH** line and **1650+** feet from the **EAST** line  
Section **30** Township **18 N** Range **35E** NMPM County **HUION**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
GL: **4670'**

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☒  
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

set CMT Retainer @ 2277'  
PLUG # 1 @ 2277 FT → 70SX Below + 10SX on top of retainer  
PLUG # 2 @ 1864 FT → 20SX  
PLUG # 3 @ 760 FT → 25SX  
PLUG # 4 SURFACE → 6SX

Spud Date:

**9/20/12**

Rig Release Date:

**9/20/12**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Albert Giussani*

TITLE SERVICE SUPERVISORS

**Sr. Eng. Advisor**

DATE **9-20-12**

**9/25/12**

Type or print name **AL GIUSSANI**

E-mail address: **albert\_giussani@oxy.com**

PHONE: **806 638 1296**

For State Use Only

APPROVED BY:

*El Martin*

TITLE

**DISTRICT SUPERVISOR**

DATE **10/2/2012**

Conditions of Approval (if any):

Job Events : BDU-1835-301

Job Event Type	Event Start Date	Truck/Unit ID	Remarks
Daily Summary	09/19/2012 23:59:00	Key 40253	09-19-12 MIRU Key rig 253 ND well head, NU BOP Attempt to J off the packer, with no luck, attempt to Unset packer still no luck, while working tbg to free packer, hung fiberglass collar on well head and parted fiberglass tbg. Attempted to screw back onto the pin, but no luck. Shut down and wait on fishing tools in am.
Daily Summary	09/20/2012 23:59:00	Key 40253	09-20-12 RU fishing tools, run spear and recover tbg. RU Wireline truck, go in to cut tbg. Tbg did not cut. Left tools in hole. Packer came lose at on/off tool. Pull and LD fg tbg Run 7" cement retainer and set at 2277', pump 70 sx under retainer, sting out and put 10sx on top. Pull 12 jts of tbg and set plug #2 at 1885' 20 sx Pull tbg to 755' set plug #3 25 sx Pull tbg to 30' and set 6 sx surface plug. RD Halliburton and release RD Key 253 and move

9/27/2012

RECEIVED OGD  
2012 SEP 28 A 8:11