Submit 3 Copies To Appropriate District	xico		Form C-103
Submit 3 Copies To Appropriate District Office District I  Energy Minerals and Natura	al Resources	TUELL ADIATO	May 27, 2004
1625 N. French Dr., Hobbs, NM 87240		WELL API NO.	1-20010
District II  1301 W. Grand Ave., Artesia, NM 88210 3 200QIL CONSERVATION District III  1220 South St. Fra:	DIVISION F	5. Indicate Type	
District III 1000 Rio Brazos Rd., ACKI NY 6749 ERVATION Santa Fe, NM 87		· -	FEE 🔽
I DETECT IV	7303	6. State Oil & Ga	
1220 S. St. Francis Dr., Santa Fe, NM84505 ).N		o. State On & Ga	15 Lease No.
SUNDRY NOTICES AND REPORTS ON WEL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN O DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101 PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Armijo Trust "	r Unit Agreement Name:
1. Type of Well: Oil Well Gas Well X Other	·	8. Well Number	#1
2. Name of Operator		9. OGRID Numbe	
XTO Energy Inc.			57067
3. Address of Operator		10. Pool name or	
2700 Farmington Ave., Bldg. K. Ste 1 Farmington, NM	1 87401	Wildcat Morris	son
4. Well Location			
Unit Letter P: 800' feet from the Sou	th line and	800' feet fro	om the <u>East</u> line
Section 27 Township 10N	Range 01w	NMPM NMPM	1 County Bernalillo
11. Elevation (Show whether L	DR, RKB, RT, GR, etc		
Pit or Below-grade Tank Application or Closure	42' GL		100 Marie 100 Ma
Pit type Depth to Groundwater Distance from nearest fresh	water well Dist	ance from nearest sur	rface water
Pit Liner Thickness: mil Below-Grade Tank: Volume_	bbls; Construction	n Material	
12 Check Appropriate Box to Indicate	Nature of Notice	Report or Othe	er Data
12. Check Appropriate Box to Indicate NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE COMPLETION	· ·	SEQUENT RE	
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  PLUG AND ABANDON    TEMPORARILY ABANDON  CHANGE PLANS    PULL OR ALTER CASING  MULTIPLE	SUBS REMEDIAL WORK COMMENCE DRILLII CASING TEST AND	SEQUENT RE	EPORT OF: ALTERING CASING  PLUG AND  X
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  PLUG AND ABANDON   TEMPORARILY ABANDON  CHANGE PLANS   PULL OR ALTER CASING  MULTIPLE  COMPLETION	SUBSTREMEDIAL WORK  COMMENCE DRILLING  CASING TEST AND  CEMENT JOB  OTHER:  tinent details, and give	SEQUENT RE	PORT OF: ALTERING CASING PLUG AND ABANDONMENT
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER:  13. Describe proposed or completed operations. (Clearly state all per of starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  XTO Energy received verbal approval to P&A well as f 6/01/05. Spotted plug #1 in 7-7/8" prod hole fr/5,54 Ppd 20 BFW spacer ahead & 7 BFW behind. Balanced w/hole fr/3,512' to 3,400' w/25 sx Type III cmt mixed Balance w/43 bbls drlg mud. Circ. Spotted plug #3 fr prod hole & 110' in 9-5/8" csg. Circ. Spotted plug 12.5#/gal. Circ 3 bbls cmt to pit. Circ. ID DP. ND E csg & installed dry hole marker. The loc will be res	SUBS REMEDIAL WORK  COMMENCE DRILLING CASING TEST AND CEMENT JOB  OTHER: tinent details, and give Completions: Attach  follows fr/Roy John 47' to 5,445' w/20 70 bbls drlg mid. ( 0 12.5#/gal. Ppd : r/1,107' to 794' w #4 fr/158' to surr BOPE. RD surrf equipstored in accordance	sequent Re  or pertinent dates, in wellbore diagram  nson with the N sx Type III cm Circ. Spotted p 20 BFW spacer a /45 sx Type III f w/50 sx Type p. RDMO rig. We ce w/NMCCD guid	PLUG AND ABANDONMENT  PLUG AND ABANDONMENT  Including estimated date of proposed completion  MMCD @ 7:00 a.m., int mixed @ 12.1#/gal. plug #2 in 8-3/4" prod whead & 5 RFW behind. I cmt w/115' in 8-3/4"  III cmt mixed @ elded plate on 9-5/8" delines.
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON  TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER:  13. Describe proposed or completed operations. (Clearly state all per of starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  XTO Energy received verbal approval to P&A well as f 6/01/05. Spotted plug #1 in 7-7/8" prod hole fr/5,54 Ppd 20 BFW spacer ahead & 7 BFW behind. Balanced w/1 hole fr/3,512' to 3,400' w/25 sx Type III cmt mixed Balance w/43 bbls drlg mud. Circ. Spotted plug #3 fr prod hole & 110' in 9-5/8" csg. Circ. Spotted plug 12.5#/gal. Circ 3 bbls cmt to pit. Circ. ID DP. ND E	REMEDIAL WORK  COMMENCE DRILLING  CASING TEST AND  CEMENT JOB  OTHER:  tinent details, and give  Completions: Attach  follows fr/Roy John  47' to 5,445' w/20  70 bbls drlg mud.  @ 12.5#/gal. Ppd:  r/1,107' to 794' w.  #4 fr/158' to surre  BOPE. RD surf equipatored in accordance	sequent Re  or pertinent dates, in wellbore diagram  nson with the N sx Type III cm Circ. Spotted p 20 BFW spacer a /45 sx Type III f w/50 sx Type p. RDMO rig. We ce w/NMCD guid and belief. I furthe	PLUG AND ABANDONMENT  PLUG AND ABANDONMENT  Cluding estimated date of proposed completion  MACCO @ 7:00 a.m., nt mixed @ 12.1#/gal. plug #2 in 8-3/4" prod whead & 5 BFW behind. I cmt w/115' in 8-3/4" III cmt mixed @ whead & behind and whead & completion  I cmt w/115' in 8-3/4"  III cmt mixed @ whead & completion  I cmt w/115' in 8-3/4"  III cmt mixed @ whead & completion  I cmt w/115' in 8-3/4"  III cmt mixed @ whead & completion  Characterity that any pit or below-
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER:  13. Describe proposed or completed operations. (Clearly state all per of starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  XTO Energy received verbal approval to P&A well as f 6/01/05. Spotted plug #1 in 7-7/8" prod hole fr/5,54 Ppd 20 BFW spacer ahead & 7 BFW behind. Balanced w/hole fr/3,512' to 3,400' w/25 sx Type III cmt mixed Balance w/43 bbls drlg mud. Circ. Spotted plug #3 fr prod hole & 110' in 9-5/8" csg. Circ. Spotted plug 12.5#/gal. Circ 3 bbls cmt to pit. Circ. ID DP. ND E csg & installed dry hole marker. The loc will be rest I hereby certify that the information above is true and complete to the grade tank has been/will be constructed or closed according to NMOCD guidelines SIGNATURE	SUBS REMEDIAL WORK  COMMENCE DRILLING CASING TEST AND CEMENT JOB  OTHER: tinent details, and give Completions: Attach  follows fr/Roy John 47' to 5,445' w/20 70 bbls drlg mid. 0 12.5#/gal. Ppd: r/1,107' to 794' w #4 fr/158' to surr BOPE. RD surf equipations best of my knowledge   a general permit	sequent Re  pertinent dates, in wellbore diagram  as Type III can Circ. Spotted p 20 BFW spacer a /45 sx Type III f w/50 sx Type p. RDMO rig. We ce w/NMCD guid and belief. I furthe or an (attached) al Assistant	PLUG AND ABANDONMENT  PLUG AND ABANDONMENT  Including estimated date of proposed completion  MOCD @ 7:00 a.m., int mixed @ 12.1#/gal. plug #2 in 8-3/4" prod whead & 5 RFW behind. If cmt w/115' in 8-3/4"  III cmt mixed @ 12.1#/gal. plug #2 in 8-3/4" prod whead & 5 RFW behind. If cmt w/115' in 8-3/4"  III cmt mixed @ 12.1#/gal. plug #2 in 8-3/4"
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER:  13. Describe proposed or completed operations. (Clearly state all per of starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  XTO Energy received verbal approval to P&A well as f 6/01/05. Spotted plug #1 in 7-7/8" prod hole fr/5,54 Ppd 20 BFW spacer ahead & 7 BFW behind. Balanced w/7 hole fr/3,512' to 3,400' w/25 sx Type III cmt mixed Balance w/43 bbls drlg mud. Circ. Spotted plug #3 fr prod hole & 110' in 9-5/8" csg. Circ. Spotted plug 12.5#/gal. Circ 3 bbls cmt to pit. Circ. ID DP. ND E csg & installed dry hole marker. The loc will be rest I hereby certify that the information above is true and complete to the grade tank has been/will be constructed or closed according to NMOCD guidelines SIGNATURE  Type or print name Kelly K. Small	SUBS REMEDIAL WORK  COMMENCE DRILLING CASING TEST AND CEMENT JOB  OTHER: tinent details, and give Completions: Attach  follows fr/Roy John 47' to 5,445' w/20 70 bbls drlg mid. 0 12.5#/gal. Ppd: r/1,107' to 794' w #4 fr/158' to surr BOPE. RD surf equipations best of my knowledge   a general permit	sequent Re  pertinent dates, in wellbore diagram  nson with the N sx Type III cm Circ. Spotted p 20 BFW spacer a /45 sx Type III f w/50 sx Type p. RDMO rig. We ce w/NMOCD guid and belief. I furthe or an (attached) al Assistant lly small@xtoen	PLUG AND ABANDONMENT  PLUG AND ABANDONMENT  Including estimated date of proposed completion  MOCD @ 7:00 a.m., int mixed @ 12.1#/gal. plug #2 in 8-3/4" prod whead & 5 RFW behind. If cmt w/115' in 8-3/4"  III cmt mixed @ 12.1#/gal. plug #2 in 8-3/4" prod whead & 5 RFW behind. If cmt w/115' in 8-3/4"  III cmt mixed @ 12.1#/gal. plug #2 in 8-3/4"
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER:  13. Describe proposed or completed operations. (Clearly state all per of starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  XTO Energy received verbal approval to P&A well as f 6/01/05. Spotted plug #1 in 7-7/8" prod hole fr/5,54 Ppd 20 BFW spacer ahead & 7 BFW behind. Balanced w/hole fr/3,512' to 3,400' w/25 sx Type III cmt mixed Balance w/43 bbls drlg mud. Circ. Spotted plug #3 fr prod hole & 110' in 9-5/8" csg. Circ. Spotted plug 12.5#/gal. Circ 3 bbls cmt to pit. Circ. ID DP. ND E csg & installed dry hole marker. The loc will be rest I hereby certify that the information above is true and complete to the grade tank has been/will be constructed or closed according to NMOCD guidelines SIGNATURE	SUBS REMEDIAL WORK  COMMENCE DRILLING CASING TEST AND CEMENT JOB  OTHER: tinent details, and give Completions: Attach  follows fr/Roy John 47' to 5,445' w/20 70 bbls drlg mid. 0 12.5#/gal. Ppd: r/1,107' to 794' w #4 fr/158' to surr BOPE. RD surf equipations best of my knowledge   a general permit	sequent Re  pertinent dates, in wellbore diagram  nson with the N sx Type III cm Circ. Spotted p 20 BFW spacer a /45 sx Type III f w/50 sx Type p. RDMD rig. We coe w/NMOCD guid and belief. I furthe lor an (attached) al Assistant lly_small@xtoen Tele	PLUG AND ABANDONMENT  PLUG AND ABANDONMENT  Including estimated date of proposed completion  PMOCD @ 7:00 a.m., nt mixed @ 12.1#/gal. plug #2 in 8-3/4" prod ahead & 5 BFW behind.  I cmt w/115' in 8-3/4"  III cmt mixed @ alched plate on 9-5/8" delines.  er certify that any pit or below-liternative OCD-approved plan DATE 06/03/05 nergy.com ephone No. 505 324-1090