

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

| |
|---|
| WELL API NO. 30-037-20053 |
| 5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> |
| 6. State Oil & Gas Lease No. |

| | | |
|---|--|--|
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | | 7. Lease Name or Unit Agreement Name: JOHN DAVID |
| 1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other | | 8. Well No. 1 |
| 2. Name of Operator CKG ENERGY | | 9. Pool name or Wildcat Wildcat |
| 3. Address of Operator PO BOX 1065, TUCUMCARI | | |
| 4. Well Location Unit Letter G : 1980' feet from the NORTH line and 1980' feet from the EAST line Section 19 Township 10N Range 27E NMPM QUAY County | | |
| 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4405' GR | | |

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐

OTHER: **RUN CBL & PERFORATE & FRAC** ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

02-06-03 - Drill out DV TUB @ 5943' - CIRC HOLE w/2% KCL & POH -

RUN Bond Log - TOP OF CMNT @ ±3700'

02-08-03 - PERF ZONE #1 @ 6581 to 88' - 14 SHOTS - T/H W/ PKR & 2 7/8" TBG. SET PKR 6511'

ACIDIZE w/1000 GALS 7 1/2% HCL - AVG TREATING PSI 1800# @ 5.8 BPM - 15 ID 520# - 15 MIN SI 320#

SWAB WELL DAY w/NO SHOS

02-12-03

SET CIBP @ 6540' - PERF @ 6309' - 14' - 10 SHOTS - T/H W/186 JTS 2 7/8" TBG & PKR. SET PKR @

6210' - ACIDIZE w/1500 GALS 7 1/2% HCL - AVG TREATING PSI 1500# @ 5 BPM - 15 ID 500# -

15 MIN 279# MADE 7 SWAB RUNS - WELL SHOW GOOD FLAIR - RAW BTM HOLE PRESSURE 2100 PSI

02-19-03

FRAC WELL w/5000 GALS 70% N₂ & 15,000# 2 9/16" SND, AVG PSI 2800# @ 10 BPM.

WELL CLEANING UP w/10 RT FLAIR

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE **AGENT**

DATE **04-02-03**

Type or print name

MIKE KOWAL

Telephone No.

(This space for State use)

APPROVED BY

TITLE **DISTRICT SUPERVISOR**

DATE **4/4/03**

Conditions of approval, if any