Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103	
District I	Energy, Minerals and Natural Resources		Revised March 25, 1999 WELL API NO.	
District II	i. French Dr., Hobbs, NM 88240		30-037-20029	
811 South First, Artesia, NM 88210	1 South First, Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of	of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 South St. Francis Dr. Santa Fe, NM 87505		STATE	FEE X	
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Salita Fe, Nivi a	37303	6. State Oil & G	as Lease No.
87505				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or	Unit Agreement Name:
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			T-4 Cattle Co.	
PROPOSALS.) 1. Type of Well:			1 4 Game Go.	
Oil Well Gas Well X	Other			
2. Name of Operator			7. Well No.	
Yates Petroleum Corpor	ration		#1	
3. Address of Operator			8. Pool name or	Wildcat
105 S. 4th Street Artes	ia, NM 88210		Wildcat	
4. Well Location			<u> </u>	
, , , , , , , , , , , , , , , , , , , ,				
Unit Letter N: 66	on feet from the South	line and	feet from the	West line
	301			_
Section 5	ownship 10N Range 10. Elevation (Show whether I		IPM Quay	County
	· ·	)K, KNB, K1, GK, EK 1' GR		
11. Check A	ppropriate Box to Indicate I		Report or Other 1	Data
NOTICE OF IN			SEQUENT REI	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR		ALTERING
PERFORM REMEDIAL WORK	FLOG AND ADAINDON	REWEDIAL WOR	.r	CASING
TEMPORARILY ABANDON X	CHANGE PLANS	COMMENCE DRI	ILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AN	ND	
OTHER:	П	OTHER:		[7]
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of				
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or				
recompilation.				
Propose to temporarily abandon well as follows:  Set a blanking plug in the packer at 6584' above the Penn perfs 6610-6615'.				
Set RBP at +/- 6180' above the Penn perfs 6213-6530'.				
Record a chart of the pressure test for the OCD.				
Cap the wellhead and T&A the well.				
Well has reserves. TA waiting on market.				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE Mind TITLE Engineering Technician DATE January 11, 2002				
Type or print name Susan Herpin Telephone No. 505-748-1471				
(This space for State use)				
APPPROVED BY TO THE DISTRICT SUPERVISOR DATE //16/02				
Conditions of approval, if any:				
OIL CONSERVATION COMMISSION TO BE NOTIFIED				
WITHIN 24 HOURS OF BEGINNING OPERATIONS				
	WITHIN 24	HOURS OF BE	CHILD III	