Submit 3 Copies To Appropriate District State of New Mexico Form C-103 Office Revised March 25, 1999 Energy, Minerals and Natural Resources District I WELL API NO. 1625 N. French Dr., Hobbs, NM 87240 District II 30-007-20403 **OIL CONSERVATION DIVISION** 811 South First, Artesia, NM 87210 5. Indicate Type of Lease District III 1220 South St Frances STATE FEE 1000 Rio Brazos Rd., Aztec. NM 87410 Santa Fe, NM 87505 District IV 6. State Oil & Gas Lease No. 2040 South Pacheco, Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS Lease Name or Unit Agreement (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A Name: DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) VPR A 1. Type of Well: Oil Well 🔲 Gas Well Other 2. Name of Operator Well No. **EL PASO ENERGY RATON, LLC** 3. Address of Operator 9. Pool name or Wildcat PO BOX 190, RATON, NM 87740 Stubblefield Canyon Raton-Vermejo Gas Well Location 535 feet from the East line Unit Letter 873 feet from the North line and 19E **NMPM** Section 32N Range Colfax County 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 8161' (GL) 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND **ABANDONMENT PULL OR ALTER CASING**  □ MULTIPLE
CASING TEST AND COMPLETION **CEMENT JOB** OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 1. Drill 11" hole to +/1 330' with air. Set 8 5/8" surface casing and cement to surface with 100 sks of cement. Drill 7 7/8" hole to 2,600' with air. Run open hole logs. Set 5 ½" casing to TD and cement to surface. Cement volumes calculated from open hole logs. 5. Perforate and stimulate Vermejo and/or Raton coals. Clean out wellbore and run production equipment. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE DR Lamble TITLE DATE 04/03/03 Engineer Donald R. Lankford Type or print name Telephone No. (505) 445-6721 (This space for State use)

APPPROVED BY

Conditions of approval, if an

TLE DISTRICT SUPERVISOR DATE 4/9/03