	State of New Me	xico		Form C-103
Office District I	Energy, Minerals and Natural Resources			May 27, 2004
1625 N. French Dr., Hobbs, NM 88240	63 /		WELL API NO.	
District II	OIL CONSERVATION	DIVISION		07-20394
1301 W. Grand Ave., Artesia, NM 88210 District III			5. Indicate Type of	f Lease
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE [	] FEE 🛛
District IV	Santa Fe, NM 87505		6. State Oil & Gas	Lease No.
1220 S. St. Francis Dr., Santa Fe, NM				
87505	ICES AND REPORTS ON WELLS		7 Lease Name or l	Unit Agreement Name
· ·	SALS TO DRILL OR TO DEEPEN OR PLU		7. Lease Name of	Omi Agreement Name
	"APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		VPR D	
PROPOSALS.)				
	Gas Well Other Coalbed Methane		8. Well Number	109
2. Name of Operator			9. OGRID Number	r 180514
EL PASO E & P COMPANY, L.P.				
3. Address of Operator			10. Pool name or \	Vildcat
PO BOX 190, RATON, NM 87740		Castle Rock Park – Vermejo		
4. Well Location				
	1564 feet from the South	line and 11	97 feet from the	West line
Section 12 Towns			<del>-</del>	<u>vvest</u> inic
	<u> </u>			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
8,263' (GL)  Pit or Below-grade Tank Application  or Closure				
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistance from nearest surface water				
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
12.	-ppropriate zen te marente in	,	reperver e mer z	
NOTICE OF IN	ITENTION TO:	SUB	SEQUENT REP	ORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOR			< /	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	_LING OPNS.□ F	P AND A
	010/110212/110			
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	JOB 🗌	
PULL OR ALTER CASING		CASING/CEMENT	JOB 🗌	
_		CASING/CEMENT OTHER:	JOB 🗆	
OTHER: Re	MULTIPLE COMPL  completion  perations. (Clearly state all pertinent details.	OTHER:	, including estimated date	of starting any proposed work
OTHER: Re	MULTIPLE COMPL ☐	OTHER:	, including estimated date	of starting any proposed work
OTHER: Re  13. Describe proposed or completed of SEE RULE 1103. For Multiple C	MULTIPLE COMPL  completion  perations. (Clearly state all pertinent details. completions: Attach wellbore diagram of projections)	OTHER:  and give pertinent dates posed completion or reco	, including estimated date	of starting any proposed work
OTHER: Re  13. Describe proposed or completed of SEE RULE 1103. For Multiple C  1. MIRU Animas Well Service. PU	MULTIPLE COMPL  completion  perations. (Clearly state all pertinent details. completions: Attach wellbore diagram of programs, Tubing, Production Equipment	OTHER:  and give pertinent dates posed completion or reco	, including estimated date ompletion.	of starting any proposed work
OTHER: Re  13. Describe proposed or completed of SEE RULE 1103. For Multiple C  1. MIRU Animas Well Service. PU	MULTIPLE COMPL  completion  perations. (Clearly state all pertinent details, completions: Attach wellbore diagram of propertions, Tubing, Production Equipment and Perforate and Stimulate the	OTHER:  and give pertinent dates posed completion or reco	, including estimated date ompletion.	of starting any proposed work
OTHER: Re  13. Describe proposed or completed of SEE RULE 1103. For Multiple C  1. MIRU Animas Well Service. PU  2. MIRU Weatherford and Hallibur Stage 1 - 1199'-1204', 1231'	MULTIPLE COMPL  completion  perations. (Clearly state all pertinent details, completions: Attach wellbore diagram of propertions, Tubing, Production Equipment and Perforate and Stimulate the	OTHER: . and give pertinent dates posed completion or recott. following Raton Coa	, including estimated date ompletion.	of starting any proposed work
OTHER:  Re  13. Describe proposed or completed of SEE RULE 1103. For Multiple C  1. MIRU Animas Well Service. PU  2. MIRU Weatherford and Hallibur Stage 1 - 1199'-1204', 1231', Acidize the perforations, pur  3. MIRU Completion Unit.	MULTIPLE COMPL  completion  perations. (Clearly state all pertinent details, ompletions: Attach wellbore diagram of propertion and Perforate and Stimulate the 1240' 64 Holes mp 71,762 gal 70 Quality Nitrogen foa	OTHER: . and give pertinent dates posed completion or recott. following Raton Coa	, including estimated date ompletion.	of starting any proposed work
OTHER:  Re  13. Describe proposed or completed of SEE RULE 1103. For Multiple C  1. MIRU Animas Well Service. PU  2. MIRU Weatherford and Hallibur Stage 1 - 1199'-1204', 1231', Acidize the perforations, pur  3. MIRU Completion Unit.  4. Retrieve WRBP at +/- 1300. Clean	MULTIPLE COMPL  completion  perations. (Clearly state all pertinent details, ompletions: Attach wellbore diagram of propertion and Perforate and Stimulate the 1-1240' 64 Holes mp 71,762 gal 70 Quality Nitrogen foam hole out to PBTD.	OTHER: and give pertinent dates posed completion or recot. following Raton Coa am with 58,000 lbs 20	, including estimated date ompletion.  I Intervals:  /40 mesh sand.	
OTHER:  Re  13. Describe proposed or completed of SEE RULE 1103. For Multiple C  1. MIRU Animas Well Service. PU  2. MIRU Weatherford and Hallibur Stage 1 - 1199'-1204', 1231', Acidize the perforations, pur  3. MIRU Completion Unit.  4. Retrieve WRBP at +/- 1300. Clean	MULTIPLE COMPL  completion  perations. (Clearly state all pertinent details, ompletions: Attach wellbore diagram of propertion and Perforate and Stimulate the 1240' 64 Holes mp 71,762 gal 70 Quality Nitrogen foa	OTHER: and give pertinent dates posed completion or recot. following Raton Coa am with 58,000 lbs 20	, including estimated date ompletion.  I Intervals:  /40 mesh sand.	
OTHER:  Re  13. Describe proposed or completed of SEE RULE 1103. For Multiple C  1. MIRU Animas Well Service. PU  2. MIRU Weatherford and Hallibur Stage 1 - 1199'-1204', 1231'-Acidize the perforations, pur  3. MIRU Completion Unit.  4. Retrieve WRBP at +/- 1300. Clean	MULTIPLE COMPL  completion  perations. (Clearly state all pertinent details, ompletions: Attach wellbore diagram of propertion and Perforate and Stimulate the 1240' 64 Holes mp 71,762 gal 70 Quality Nitrogen foam hole out to PBTD.  Supervisor and run pump, tubing, an	OTHER:  and give pertinent dates posed completion or record.  t. following Raton Coam with 58,000 lbs 20 and rods. Test well ar	, including estimated date ompletion.  I Intervals:  /40 mesh sand.  Ind put back on productions.	etion.
OTHER:  Re  13. Describe proposed or completed of SEE RULE 1103. For Multiple C  1. MIRU Animas Well Service. PU  2. MIRU Weatherford and Hallibur Stage 1 - 1199'-1204', 1231', Acidize the perforations, pur  3. MIRU Completion Unit.  4. Retrieve WRBP at +/- 1300. Clean	MULTIPLE COMPL  completion  perations. (Clearly state all pertinent details, ompletions: Attach wellbore diagram of propertion and Perforate and Stimulate the 1240' 64 Holes mp 71,762 gal 70 Quality Nitrogen foa an hole out to PBTD.  Supervisor and run pump, tubing, an above is true and complete to the beserver.	OTHER:  and give pertinent dates posed completion or record.  t. following Raton Coam with 58,000 lbs 20 and rods. Test well are set of my knowledge	, including estimated date ompletion.  I Intervals:  /40 mesh sand.  ad put back on product on the control of t	etion. certify that any pit or below
OTHER:  13. Describe proposed or completed of SEE RULE 1103. For Multiple C  1. MIRU Animas Well Service. PU  2. MIRU Weatherford and Hallibut Stage 1 - 1199'-1204', 1231'-Acidize the perforations, put  3. MIRU Completion Unit.  4. Retrieve WRBP at +/- 1300. Cleated the Production Completion Unit.  5. Turn well over to the Production Completed to See Rule 1103. For Multiple Completed to See Rule 110	MULTIPLE COMPL  completion  poperations. (Clearly state all pertinent details, ompletions: Attach wellbore diagram of propertion and Perforate and Stimulate the 1240' 64 Holes mp 71,762 gal 70 Quality Nitrogen foa an hole out to PBTD.  Supervisor and run pump, tubing, an above is true and complete to the best closed according to NMOCD guidelines	OTHER:  and give pertinent dates posed completion or record.  t. following Raton Coam with 58,000 lbs 20 and rods. Test well are set of my knowledge	, including estimated date ompletion.  I Intervals:  /40 mesh sand.  ad put back on product on the control of t	etion. certify that any pit or below
OTHER:  13. Describe proposed or completed of SEE RULE 1103. For Multiple C  1. MIRU Animas Well Service. PU  2. MIRU Weatherford and Hallibur Stage 1 - 1199'-1204', 1231' Acidize the perforations, pur  3. MIRU Completion Unit.  4. Retrieve WRBP at +/- 1300. Cleated the Production Completion Unit.  5. Turn well over to the Production Completed	MULTIPLE COMPL  completion  perations. (Clearly state all pertinent details, ompletions: Attach wellbore diagram of propertion and Perforate and Stimulate the 1-1240' 64 Holes mp 71,762 gal 70 Quality Nitrogen foath hole out to PBTD.  Supervisor and run pump, tubing, an above is true and complete to the best closed according to NMOCD guidelines  TITLE	OTHER:  and give pertinent dates posed completion or record.  t.  following Raton Coa am with 58,000 lbs 20 and rods. Test well are lest of my knowledge a general permit  Regulatory A	, including estimated date ompletion.  I Intervals:  /40 mesh sand.  ad put back on production of the	etion.   certify that any pit or belowive OCD-approved plan    DATE
OTHER:  13. Describe proposed or completed of SEE RULE 1103. For Multiple Completed and Hallibur Stage 1 - 1199'-1204', 1231' Acidize the perforations, pur 3. MIRU Completion Unit. 4. Retrieve WRBP at +/- 1300. Clease Turn well over to the Production I hereby certify that the information grade tank has been/will be constructed or SIGNATURE  Type or print name Shirley A Mi	MULTIPLE COMPL  completion  perations. (Clearly state all pertinent details, ompletions: Attach wellbore diagram of propertion and Perforate and Stimulate the 1-1240' 64 Holes mp 71,762 gal 70 Quality Nitrogen foath hole out to PBTD.  Supervisor and run pump, tubing, an above is true and complete to the best closed according to NMOCD guidelines  TITLE	OTHER:  and give pertinent dates posed completion or record.  t.  following Raton Coa am with 58,000 lbs 20 and rods. Test well are lest of my knowledge a general permit  Regulatory A	, including estimated date ompletion.  I Intervals:  /40 mesh sand.  ad put back on production of the	etion.   certify that any pit or belowive OCD-approved plan    DATE
OTHER:  13. Describe proposed or completed of SEE RULE 1103. For Multiple C  1. MIRU Animas Well Service. PU  2. MIRU Weatherford and Hallibur Stage 1 - 1199'-1204', 1231' Acidize the perforations, pur  3. MIRU Completion Unit.  4. Retrieve WRBP at +/- 1300. Cleated the Production Completion Unit.  5. Turn well over to the Production Completed	MULTIPLE COMPL  completion  perations. (Clearly state all pertinent details, ompletions: Attach wellbore diagram of propertion and Perforate and Stimulate the 1-1240' 64 Holes mp 71,762 gal 70 Quality Nitrogen foath hole out to PBTD.  Supervisor and run pump, tubing, an above is true and complete to the best closed according to NMOCD guidelines  TITLE	OTHER:  and give pertinent dates posed completion or record.  t.  following Raton Coa am with 58,000 lbs 20 and rods. Test well are lest of my knowledge a general permit  Regulatory A	, including estimated date ompletion.  I Intervals:  /40 mesh sand.  ad put back on production of the	etion.   certify that any pit or belowive OCD-approved plan    DATE
OTHER:  13. Describe proposed or completed of SEE RULE 1103. For Multiple Construction  1. MIRU Animas Well Service. PU  2. MIRU Weatherford and Hallibur Stage 1 - 1199'-1204', 1231' Acidize the perforations, pur  3. MIRU Completion Unit.  4. Retrieve WRBP at +/- 1300. Clean  5. Turn well over to the Production  I hereby certify that the information grade tank has been/will be constructed or SIGNATURE Shirley A Mither State Use Only	MULTIPLE COMPL  completion  perations. (Clearly state all pertinent details. completions: Attach wellbore diagram of propertion and Perforate and Stimulate the fe-1240' 64 Holes mp 71,762 gal 70 Quality Nitrogen foat an hole out to PBTD.  Supervisor and run pump, tubing, an above is true and complete to the become according to NMOCD guidelines  TITLE  tchell  E-mail address: shirley.n	OTHER:  and give pertinent dates posed completion or record.  t. following Raton Coal am with 58,000 lbs 20 and rods. Test well are lest of my knowledge a general permit Regulatory A mitchell@elpaso.co	including estimated date ompletion.  I Intervals:  /40 mesh sand.  I d put back on product of the product of th	etion.
OTHER:  13. Describe proposed or completed of SEE RULE 1103. For Multiple Completed and Hallibur Stage 1 - 1199'-1204', 1231' Acidize the perforations, pur 3. MIRU Completion Unit. 4. Retrieve WRBP at +/- 1300. Clease Turn well over to the Production I hereby certify that the information grade tank has been/will be constructed or SIGNATURE  Type or print name Shirley A Mi	MULTIPLE COMPL  completion  perations. (Clearly state all pertinent details. completions: Attach wellbore diagram of propertion and Perforate and Stimulate the fe-1240' 64 Holes mp 71,762 gal 70 Quality Nitrogen foat an hole out to PBTD.  Supervisor and run pump, tubing, an above is true and complete to the become according to NMOCD guidelines  TITLE  tchell  E-mail address: shirley.n	OTHER:  and give pertinent dates posed completion or record.  t.  following Raton Coa am with 58,000 lbs 20 and rods. Test well are lest of my knowledge a general permit  Regulatory A	including estimated date ompletion.  I Intervals:  /40 mesh sand.  I d put back on product of the product of th	etion.   certify that any pit or belowive OCD-approved plan    DATE