## District I

1625 N. French Dr., Hobbs, NM 88240 Phone: (505) 393-6161 Fax: (505) 393-0720

1301 W. Grand Ave., Artesia, NM 88210 Phone:(505) 748-1283 Fax:(505) 748-9720

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

Pit or Below-grade Tank Application or Closure

## State of New Mexico

Energy, Minerals and Natural Resources

Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

Form	ì	C-	l	0
Permit	1	15	3	5.

WELL API NUMBER	
30-021-20412	

F 6. State Oil & Gas Lease No.

5. Indicate Type of Lease

7. Lease Name or Unit Agreement Name SUNDRY NOTICES AND REPORTS ON WELLS WEST BRAVO DOME UNIT (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFRENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH 8. Well Number PROPOSALS.) 031 1. Type of Well:C 9. OGRID Number 2. Name of Operator HESS CORPORATION 495 10. Pool name or Wildcat 3. Address of Operator P.O. BOX 840, SEMINOLE, TX 79360 4. Well Location feet from S 1200 line Unit Letter feet from the line and Section Township Range NMPM Harding County 11. Elevation (Show whether DR, KB, BT, GR, etc.) 5384 GR

> Below-Grade Tank: Volume\_\_\_\_\_ \_\_ bbls; Construction Material\_ Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

Pit Type \_\_\_\_\_ Depth to Groundwater \_\_\_\_ Distance from nearest fresh water well \_\_\_\_ Distance from nearest surface water\_

12. Check Appropriate box to indicate Nature of Notice, Report of Other Data											
NOTICE OF IN	NTION TO:	SUBSEQUENT REPORT OF:									
PERFORM REMEDIAL WORK		PLUG AND ABANDON	ا □ ا	REMEDIAL WORK		ALTER CASING					
TEMPORARILY ABANDON		CHANGE OF PLANS		COMMENCE DRILLING OPNS.		PLUG AND ABANDON					
PULL OR ALTER CASING		MULTIPLE COMPL		CASING/CEMENT JOB							
Other:				Other: Drilling/Cement			$\boxtimes$				

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

RU, safety meeting rig inspection, spud well, drill, circulate and condition, run surf csg, cement surf csg, test lines, wait on cement, drill plug and cement, circ and condition TOOH, run log,

Run production csg, circ and condition cement production csg, circ cement to surface. Wait on cement, Clean pit, ND BOP, RD 5/29/2010 Spudded well.

Casing and Cement Program

Date	String	Fluid Type	Hole Size	Csg Size	Weight lb/ft	Grade	Est TOC	Dpth Set	Sacks	Yield	Class	1'' Dpth	Pres Held	Pres Drop	Open Hole
05/31/10	Surf		12.25	8.625	24	J55	0	1855	600	1.74	C lead		2000		
05/31/10	Surf		12.25	8.625	24	J55	0	1855	200	1.35	C tail		2000		
05/31/10	Surf		12.25	8.625	24	J55	0	1855	275	1.35	C 2nd tail		2000		
06/02/10	Prod		7.875	4.5	4.4	IJ	0	2809	135	2.94	midcon2 le				
06/02/10	Prod		7.875	4.5	12.75	J55	0	3027	365	1.85	midcon2 ta				

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ...., a general permit ..... or an (attached) alternative OCD-approved plan ......

SIGNATURE Electronically Signed

TITLE Engineering Tech

DATE 6/22/2010

Type or print name Rita Smith

E-mail address rsmith@hess.com Telephone No. 432-758-6726

For State Use Only:

APPROVED BY: Ed Martin

TITLE District Supervisor

DATE 6/25/2010 1:52:10 PM