

Submit 1 Copy To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
October 13, 2009

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED OGD
2011 MAY 25 A 9:51

WELL API NO.	30-021-20431
Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	West Bravo Dome Unit (WBDU)
8. Well Number	021H
9. OGRID Number	495
10. Pool name or Wildcat	(96387) West Bravo Dome CO2 Gas
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	4650'

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other CO2 SUPPLY	
2. Name of Operator	HESS Corporation
3. Address of Operator	PO Box 840 Seminole TX 79360
4. Well Location	Unit Letter H : 2000 feet from the NORTH line and 1100 feet from the EAST line Section 2 Township 18N Range 29E NMPM County HARDING
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4650'	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Start date

Monday, July 18, 2011

MIRU PXA rig. ND WH & NU BOPs. RIH w/ WS. Circulate P&A mud. PU & pump plug #1. PU & WOC.

Tag TOC (2110'). Pressure test casing 5.5" csg. to 500 psi. PU WS & Pump plug #2. PU & WOC.

Tuesday, July 19, 2011

Pump plug #3. TOOH. Cut of WH & anchors 3' below GL. Cap well with steel plate. Install dry hole marker.

Cut of WH & anchors 3' below GL. Clear, clean, and level location. RDMO

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rita C. Smith TITLE ENGINEERING TECH DATE 5/20/2011

Type or print name RITA C. SMITH E-mail address: rsmith@hess.com PHONE: 432-758-6726

For State Use Only

APPROVED BY: Ed Martin TITLE DISTRICT SUPERVISOR DATE 5/31/2011

Conditions of Approval (if any):