<u>District I</u> 1625 N French Dr., Hobbs, NM 88240 District II
1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe NM 87505

SEP **15** 2011 Revised October 10, 2003

NMOCD AND Submit 2 Copies to appropriate with Rule 116 on back side of form

				30	ilita 1 ⁻⁶ , INIVI 873	03			
30.015	-2602	4	Rele	ease Notific	eation and Co	rrective A	ction	·	-
nMUB/135330781				OPERATOR			al Report	Final Report	
			26932	4 Contact: Joe	Contact: Joe Hernandez				
Address: 2130 W Bender Blvd Hobbs, NM					Telephone No.: 575-942-8675				
Facility Name: HE West A & B Injection - Well HE West B 40				B 40 Facility Typ	Facility Type: Produced Water Injection				
				neral Owner: BLM LOCATION OF RELEASE			Lease No.: LC-029426-B		
Unit Letter	Section 10	Township 17S	Range 31E	Feet from the 560	North/South Line N	Feet from the 660	East/West Line W	County	Eddy
				Latitude: 32 8	8548772 Longitud	-103.8662599)		

Latitude: 32.8548772 Longitude: -103.8662599							
NATURE OF RELEASE							
Type of Release: Produced Water	Volume of Release: 20 bbls	Volume Recovered: 0 bbls					
Source of Release: 4" Injection Line Leak	Date and Hour of Occurrence: 09/09/11-1500	Date and Hour of Discovery: 09/0911-1530					
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required	If YES, To Whom?						
By Whom? J. Hemandez	Date and Hour: 09/0911 - 1530						
Was a Watercourse Reached? ☐ Yes ☑ No	If YES, Volume Impacting the Watercourse.						
If a Watercourse was Impacted, Describe Fully.*:							
Describe Cause of Problem and Remedial Action Taken.*: Hole develope	d in "injection line. Suspect over-pre	essure from scale. System was shutdown					
and the line leak exposed. Repairs pending.							
Describe Area Affected and Cleanup Action Taken.*: Pooled area of the							
down slope. The primary pathway and pool area have been excavated and samples collected and sent to for laboratory analysis. Results are pending.							
Corrective action plan, photos and site map attached.							
I hereby certify that the information given above is true and complete to the	hast of my knowledge and understa	nd that pursuant to NMOCD rules and					
regulations all operators are required to report and/or file certain release n							
public health or the environment. The acceptance of a C-141 report by th	e NMOCD marked as "Final Report" of	does not relieve the operator of liability					
should their operations have failed to adequately investigate and remediat							
or the environment. In addition, NMOCD acceptance of a C-141 report d	oes not relieve the operator of respons	ability for compliance with any other					
federal, state, or local laws and/or regulations.	OIL CONSEDI	ATION DIVISION					
Asplant Comment	OIL CONSERV	ATION DIVISION					
Signature:	Giral D. Mills	Kenne					
4."	Approved by District Supervisor.	NAMIUALIN					
Printed Name: Jose Hernandez	DEO 4 0 2044						
Title: Foreman	Approval Date: DEC 19 2011	Expiration Date:					
E-mail Address: jhernandez@linneenrgy com	Conditions of Approval:	Attached					
Date: 09/14/11 Phone: 575-738-1739	Remediation per OCD Rules 8	ķ					
Attach Additional Sheets If Necessary	Remediation por						

Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:

From: Fred Holmes [fred@etechenv.com]

Sent: Thursday, September 15, 2011 11:45 AM

To: Bratcher, Mike, EMNRD; tgregsto@blm.gov
Cc: 'Daniel Frick'; 'Ron Ragland'; 'Joe Hernandez'

Subject: West A & B Injection Line Leak

Attachments: HE West AB Well 40 Inj Line Release Initial C-141 091411.pdf

Categories: Red Category

Mike:

In discussion with Terry. She had this site already listed in her system to be associated with the LINN Energy, <u>HE West B #40 Well</u>. I have amended the C-141 I sent you yesterday to reflect this change. Please accept this as the replacement for the initial C-141.

Respectfully

Fred Holmes

Etech Environmental & Safety Solutions, Inc.

P.O. Box 8469

Midland, Texas 79708-8469 Phone: 432-563-2200 Fax: 432-563-2213 E-mail: fred@etechenv.com

CONFIDENTIAL

This e-mail message, including any attachments, is intended solely for the individual(s) named above. It contains confidential and/or proprietary information. If you are not the intended recipient, please do not read, copy or distribute it or any information it contains. Please immediately notify the sender by return mail and delete it.

From:

Gregston, Terry G [tgregsto@blm.gov] Tuesday, September 13, 2011 4:44 PM

Sent:

To:

'Daniel Frick'; Bratcher, Mike, EMNRD; 'Ron Ragland'; 'JHernandez@linnenergy.com'

Subject:


H E West B 40, spill map

Gentlemen,

Attached you will find a spill map for the H E West B 40 spill.

Our archeologists have reviewed this spill and have determined that a survey and monitor will be required for this spill site prior to proceeding with major cleanup operations.

Thank you for your assistance with this matter,



From:

Fred Holmes [fred@etechenv.com]

Sent:

Wednesday, September 14, 2011 2:17 PM

To: Subject: Bratcher, Mike, EMNRD; tgregsto@blm.gov

Attachments:

LINN Energy - HE West A & B Injection Line Initial C-141
HE West AB Inj Line Corrective Action Plan 091411.pdf; HE West AB Inj Line Release Initial

C-141 091411.pdf; West A-B Injection Line Release PhotoLog 091211.pdf; HE West AB Inj

Line Release Map 091311.pdf

Mike & Terry:

Attached is the initial C-141 for the LINN Energy, HE West A & B injection line leak that was discovered on 09/09/11. Remediation on the site is in progress. Also attached is a corrective action plan, site map, and photograph log of the site.

Respectfully:

Fred Holmes

Etech Environmental & Safety Solutions, Inc.

P.O. Box 8469

Midland, Texas 79708-8469 Phone: 432-563-2200 Fax: 432-563-2213 E-mail: fred@etechenv.com

CONFIDENTIAL


This e-mail message, including any attachments, is intended solely for the individual(s) named above. It contains confidential and/or proprietary information. If you are not the intended recipient, please do not read, copy or distribute it or any information it contains. Please immediately notify the sender by return mail and delete it.



Corrective Action Report – Short Form (To Accompany C-141)

Date: 09/14/11 Lease Name: HE West A & B Injection Line					
Type of Contamination: ☐ Hydrocarbon ☐ Produced Water ☐ Other (Specify):					
Cause of Release: Leak developed in the 4" injection line.					
added of recipied. Eduk developed in the Finipotion into.					
Site Information					
General Setting and Area of Impact (Check All that Apply):					
☐ Pad Only ☐ Road Only ☐ Off-Site Areas Impacted: ☐ Flat ☐ Sloped ☐ Drainage Features Impacted					
Estimated Depth of Contamination: 6 Feet, Vertical					
Estimated Area of Contamination: 5000 Square Feet					
Site Delineated: ☐ No ☐ Yes Method: ☐ Visual (probe/shovel) ☐ Sampling & Analysis (Attach Analysis)					
Corrective Actions to Be Taken					
Remedial Action Goals: ☐ Hydrocarbons <5,000 mg/kg ☐ Chlorides <1,000 mg/kg					
Other (Specify):					
Estimated Start Date: 09/10/11 Estimated Completion Date: 09/29/11					
Remedial Actions(Check All That Apply):					
☑ Dig & Haul Disposal Site: ☐ CRI ☑ Lea Land ☐ Sundown ☐ Other (Specify):					
☐ Blending ☐ Biological Degradation ☐ Irrigation ☐ Calcium Amendment & Irrigation					
☐ Cap & Cover Cap Material: ☐ Clay ☐ Caliche ☐ Native Soil					
☐ Liner: Mil Thickness: , Installation Depth: Feet					
☐ Other (Specify): Backfill excavation with like material.					
Clearance Confirmation Sampling to be Performed:					
Total and Committee Company to 201 on Comou.					
Restoration Activities (Check All That Apply)					
⊠ Erosion Control:					
Seeding: ☐ Natural ☐ BLM Seed Mix #2 ☐ BLM Seed Mix #3 ☐ BLM Seed Mix #4					
□ Other:					
Other Notes or Actions:					

During resotration, site will be furrowed "cross-gradient" to reduce erosion potential. Site will be seeded with a 50/50 mix of BLM 3 &4.



Data use subject to license.

© DeLorme XMap® 7

www.delorme.com

Photo No:

1.

Direction Taken: Northwest

Description:

View of spill pathremediation area from the roadside looking northwest.



Photo No:

2.

Direction Taken:

North

Description:

View of the spill path and remediation area looking up the slope toward the main excavation area.



Photo No:

3.

Direction Taken:

West

Description:
View of spill path
remediation area of east
slope where spill migrated
from the release point.



Photo No:


4.

Direction Taken:

West

Description:
View of release point after excavation activities performed on 09/10/11.





From:

Gregston, Terry G [tgregsto@blm.gov]

Sent:

Wednesday, September 14, 2011 5:58 PM

To:

Fred Holmes; Bratcher, Mike, EMNRD

Subject:

RE: LINN Energy - HE West A & B Injection Line Initial C-141: aka H E West B 40 C141

I have received your C141 spill report.

Thank you,

Terry Gregston
Environmental Protection Specialist
Bureau of Land Management
620 E. Greene St.
Carlsbad, NM 88220
Office (575) 234-5958
Cell (575) 361-2635
Fax (575) 234-5927

Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

From: Fred Holmes [mailto:fred@etechenv.com]
Sent: Wednesday, September 14, 2011 2:17 PM
To: 'Bratcher, Mike, EMNRD'; Gregston, Terry G

Subject: LINN Energy - HE West A & B Injection Line Initial C-141

Mike & Terry:

Attached is the initial C-141 for the LINN Energy, HE West A & B injection line leak that was discovered on 09/09/11. Remediation on the site is in progress. Also attached is a corrective action plan, site map, and photograph log of the site.

Respectfully:

Fred Holmes

Etech Environmental & Safety Solutions, Inc.

P.O. Box 8469

Midland, Texas 79708-8469 Phone: 432-563-2200 Fax: 432-563-2213

E-mail: fred@etechenv.com

CONFIDENTIAL

This e-mail message, including any attachments, is intended solely for the individual(s) named above. It contains confidential and/or proprietary information. If you are not the intended recipient, please do not read,

	copy or distribute it or any information it contains. delete it.	Please immediately notify the sender by return mail and				
	·					
•	ı					
	,					
2		•				

•

.

District I 1625 N. French Dr., Hobbs, NM 8822 District II 1301 W Grand Avenue, Artesia, NM 88 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505

Form C-141 SEP 1 4/2011 Revised October 10, 2003 Submit 2 Copies to appropriate ARTES coordinate in accordance with Rule 116 on back

side of form

	Janta	1 0, 14141 0 / 303				
30-015 - 26024 Relea	se Notificati	on and Corrective A	Action			
	\	OPERATOR		Initial Report	Final Report	
Name of Company: LINN Energy		Contact: Joe Hernandez	/			
Address: 2130 W Bender Blvd Hobbs, NM	Telephone No.: 575-942,48675					
Facility Name: HE West A & B Injection		Facility Type: Produced Water Injection				
Surface Owner: BLM	Mineral Owne	r: BLM	L	ease No.:		
HEWEST B#40	LOCATIO	ON OF RELEASE				
Unit Letter Section Township Range	Feet from the No.	rth/South Line Feet from the	e East/West	Line County		

Latitude: 32.85487 72 Longitude: -103.8662599 NATURE OF RELEASE Type of Release: Produced Water Volume of Release: 20 bbls Volume Recovered: 0 bbls Source of Release: 4" Injection Line Leak Date and Hour of Occurrence: Date and Hour of Discovery: /09/09/11-1500 09/0911-1530 Was Immediate Notice Given? If YES, To Whom? M. Bratcher, OCD, T. Gregston BLM By Whom? J. Hernandez Date and Nour: 09/0911 - 1530 Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. ☐ Yes ⊠ No If a Watercourse was Impacted, Describe Fully.*: Describe Cause of Problem and Remedial Action Taken.*: Hole developed in "injection line. Suspect over-pressure from scale. System was shutdown and the line leak exposed. Repairs pending. Describe Area Affected and Cleanup Action Taken.* Pooled area of the release is between two sand dunes. Fluids crested low area and moved eastward down slope. The primary pathway and pool area have been excavated and samples collected and sent to for laboratory analysis. Results are pending. Corrective action plan, photos and site map attached I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequate by investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other

federal, state, or local laws and/or regulations OIL CONSERVATION DIVISION Signature: Approved by District Supervisor: Printed Name: Jose Hernandez Title: Foreman Approval Date: Expiration Date: Attached E-mail Address: jhernandez@linneenrgy.com Conditions of Approval: Phone: 575-738-1739

Date: 09/14/11

^{*} Attach Additional Sheets If Necessary