Bratcher, Mike, EMNRD

Amanda Trujillo [atrujillo@yatespetroleum.com] From:

Sent: Tuesday, January 17, 2012 4:21 PM

r6 spillreports@epa.gov To:

Lisa Norton: Jerry Fanning: Bratcher, Mike, EMNRD Cc: Yates Petroleum Corp. - Rio Penasco Draw Pictures Subject:

How to UNZIP.html; First Inital Cleanup.txt Attachments:

Categories: Blue Category

Mr. Delgado;

As per our conversation, attached are pictures during the initial clean-up actions.

Actions taken included:

- Immediately upon discovery, the leaking pipeline was isolated
- Multiple vacuum trucks were called to the scene and began removing standing fluid
- A backhoe and other heavy equipment were dispatched to the scene to assist
- Earthen berms were constructed to segregate the impacted area
- The area was fenced to prevent livestock from entering

Thank you,

Amanda N. Trujillo Environmental Scientist Yates Petroleum Corporation Office 575-748-4310 Cell 575-703-6537

Email atrujillo@yatespetroleum.com

Bratcher, Mike, EMNRD

From: Amanda Trujillo [atrujillo@yatespetroleum.com]

Sent: Tuesday, January 17, 2012 4:28 PM
To: Eric Delgado; R6 SpillReports

Cc: Lisa Norton; Jerry Fanning; Bratcher, Mike, EMNRD
Subject: RE: Yates Petroleum Corp. - Rio Penasco Draw Pictures
Attachments: First Inital Cleanup.JPG; Before first inital cleanup.JPG

Categories: Blue Category

Please let me know if it worked this time. Thank you

From: Eric Delgado [mailto:Delgado.Eric@epamail.epa.gov]

Sent: Tuesday, January 17, 2012 4:25 PM **To:** Amanda Trujillo; R6 SpillReports

Cc: Lisa Norton; Jerry Fanning; Mike Bratcher (Mike.Bratcher@state.nm.us)

Subject: Re: Yates Petroleum Corp. - Rio Penasco Draw Pictures

Please re-send the attachment with the file extension re-named. Our firewall strips zip files and I cannot accept them.

From: Amanda Trujillo [atrujillo@yatespetroleum.com]

Sent: 01/17/2012 04:21 PM MST

To: R6 SpillReports

Cc: Lisa Norton < Lisa@yatespetroleum.com>; Jerry Fanning < jerryf@yatespetroleum.com>; "Mike Bratcher

(<u>Mike.Bratcher@state.nm.us</u>)" < <u>Mike.Bratcher@state.nm.us</u>> **Subject:** Yates Petroleum Corp. - Rio Penasco Draw Pictures

Mr. Delgado;

As per our conversation, attached are pictures during the initial clean-up actions.

Actions taken included:

- Immediately upon discovery, the leaking pipeline was isolated
- Multiple vacuum trucks were called to the scene and began removing standing fluid
- A backhoe and other heavy equipment were dispatched to the scene to assist
- Earthen berms were constructed to segregate the impacted area
- The area was fenced to prevent livestock from entering

Thank you,

Amanda N. Trujillo
Environmental Scientist
Yates Petroleum Corporation
Office 575-748-4310
Cell 575-703-6537
Email atrujillo@yatespetroleum.com

Bratcher, Mike, EMNRD

From:

Eric Delgado [Delgado.Eric@epamail.epa.gov]

Sent: To: Tuesday, January 17, 2012 4:25 PM

Cc:

Amanda Trujillo; R6 SpillReports

Subject:

Lisa Norton; Jerry Fanning; Bratcher, Mike, EMNRD Re: Yates Petroleum Corp. - Rio Penasco Draw Pictures

Attachments:

First

Categories:

Blue Category

Please re-send the attachment with the file extension re-named. Our firewall strips zip files and I cannot accept them.

From: Amanda Trujillo [atrujillo@yatespetroleum.com]

Sent: 01/17/2012 04:21 PM MST

To: R6 SpillReports

Cc: Lisa Norton <<u>Lisa@yatespetroleum.com</u>>; Jerry Fanning <<u>jerryf@yatespetroleum.com</u>>; "Mike Bratcher

(<u>Mike.Bratcher@state.nm.us</u>)" < <u>Mike.Bratcher@state.nm.us</u>> **Subject:** Yates Petroleum Corp. - Rio Penasco Draw Pictures

Mr. Delgado;

As per our conversation, attached are pictures during the initial clean-up actions.

Actions taken included:

- Immediately upon discovery, the leaking pipeline was isolated
- Multiple vacuum trucks were called to the scene and began removing standing fluid
- A backhoe and other heavy equipment were dispatched to the scene to assist
- Earthen berms were constructed to segregate the impacted area
- The area was fenced to prevent livestock from entering

Thank you,

Amanda N. Trujillo Environmental Scientist

Yates Petroleum Corporation

Office 575-748-4310 Cell 575-703-6537

Email atrujillo@yatespetroleum.com