


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

NMLB 12045 29710

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229/37	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Foster Eddy #9	Facility Type	Flowline
Surface Owner	Federal	Mineral Owner	
		Lease No. (API#)	30-015-26273



LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	17	17S	31E					Eddy

Latitude 32 49.990 Longitude 103 53.261

NATURE OF RELEASE

Type of Release	Produced water / Skim oil	Volume of Release	15bbls pw 1bbl oil	Volume Recovered	none recovered
Source of Release	3" poly line ruptured	Date and Hour of Occurrence	01/13/2012	Date and Hour of Discovery	01/13/2012 12:00 p.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
A 3" poly line ruptured. The line has been repaired and returned to service.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 16bbls of produced fluid was released from the ruptured poly line and due to the nature of the release we were unable to recover any fluid. The fluid travels along two paths measuring 4' x 60' and 4' x 15'. The fluid took the path of least resistance and streamed into low lying areas and pathways. Tetra Tech will sample the spill areas to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for approval prior to any significant remediation work.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Josh Russo		Signed By:  Approved by District Supervisor:	
Title: HSE Coordinator		Approval Date: FEB 14 2012	Expiration Date:
E-mail Address: jrusso@conchoresources.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 01/27/2012 Phone: 432-212-2399		Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 3/14/2012	

\* Attach Additional Sheets If Necessary

2RP-1011

## Bratcher, Mike, EMNRD

---

**From:** Joshua Russo [jrusso@concho.com]  
**Sent:** Friday, January 27, 2012 7:59 AM  
**To:** Bratcher, Mike, EMNRD; Amos, James A; Terry\_Gregston@blm.gov  
**Cc:** Tavaréz, Ike; Dorey, Kim; Franklin, Tom K.  
**Subject:** C-141 Initial Report - Foster Eddy flowline release  
**Attachments:** FOSTER EDDY #9 FLOWLINE -- DATE OF RELEASE -- 01-13-2012.pdf

Please see attached a C-141 Initial Report for a release we had from our Foster Eddy #9 flowline.

Thank you,

### Joshua Russo

HSE Coordinator  
550 W. Texas Ave, Suite 100  
Midland, Texas 79701  
Phone: (432) 683-7443  
Cell: (432) 212-2399  
[jrusso@conchoresources.com](mailto:jrusso@conchoresources.com)



**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system.  
Thank you

**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.