

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised January 1, 2008

Submit 1 Copy to appropriate  
District Office

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: DCP Midstream, LP	Contact: Patricia A. Grajeda	
Address: 10 Desta Drive, Suite 400 W, Midland, TX., 79705	Telephone# & E-mail: 432.620.5403/ pgrajedadebabb@dcpmidstream.com	
Facility Name: 10200 Line Cotton Draw 12"	Facility Type: Pipeline	
Surface Owner: State	Mineral Owner:	Well API No.: 30,025-38576

LOCATION OF RELEASE

Unit Letter	Section 10	Township 24	Range 32	Feet from the	North/South Line S	Feet from the	East/West Line E	County
-------------	---------------	----------------	-------------	---------------	-----------------------	---------------	------------------------	--------

Latitude N 32.3555/N32.2168 Longitude W 103.5683 / W 103.6749

NATURE OF RELEASE



Type of Release : Air/ Oil and Condensate	Volume of Release: 1, 340 Mscf. The amount of volume is unknown	Volume Recovered: Fluid soaked in ground. Approx. 50 bbl.
Source of Release: Pipeline	Date & Hour of Occurrence: 03/04/2012 12:27 PM	Date & Hour of Discovery: 03/04/2012 12:27 PM
Was Immediate Notice Given OCD? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom @ OCD? Yes, via email to Mike Bratcher	
By Whom? Kurt Jacquin	Date and Hour: Sun 03/04/2012 05:41 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken. (If water spilled, give Chloride content)\*  
DCP Midstream discovered a pipeline leak on the 12" Cotton Draw Line. DCP Midstream immediately shut in gas.

Describe Area Affected, Dimensions, and Cleanup Action Taken.\*  
Hungry Horse Environmental will be affecting the clean up by removing the contaminated soil and disposing in an OCD approved landfill.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Patricia A. Grajeda	Approved by ENV SPECIALIST District Supervisor: 	
Title: Environmental Specialist II	Approval Date: 03/06/12	Expiration Date: 05/07/12
E-mail Address: pgrajedadebabb@dcpmidstream.com	Conditions of Approval: SUBMIT FINAL C-141 BY 05/07/12	IR# 3-12-2785
Date: 03/05/2012 Phone: 432.620.5403		

\* Attach Additional Sheets If Necessary