1R-427-370

REPORTS

DATE: 4-10-12

1R 427-370 PECEIVED 000

EME E-23 EOL 2011

CLOSURE

RICE Operating Company

122 West Taylor • Hobbs, New Mexico 88240 Phone: (575) 393-9174 • Fax: (575) 397-1471

May 1, 2012

Mr. Edward Hansen New Mexico Energy, Minerals, & Natural Resources Oil Conservation Division, Environmental Bureau 1220 S. St. Francis Drive Santa Fe, New Mexico 87505

RE: Termination Request

EME E-23 EOL: UL/E, Sec. 23, T19S, R36E

RICE Operating Company - Eunice Monument Eumont SWD System

Mr. Hansen:

Rice Operating Company (ROC) is the service provider (agent) for the EME Saltwater Disposal (SWD) System and has no ownership of any portion of the pipeline, well, or facility. The System is owned by a consortium of oil producers, System Parties, who provide all operating capital on a percentage ownership/usage basis.

Background

In 2011, ROC initiated work on the former E-23 EOL junction box. The site is located in UL/E, Sec. 23, T19S, R36E. NM OSE records indicate that groundwater would likely be encountered at a depth of approximately 57 +/- feet. The site was delineated using a backhoe to collect soil samples at regular intervals, creating a 3x7x6-ft deep excavation. Each sample was field titrated for chlorides and field screened using a PID for hydrocarbons, resulting in low concentrations of each. The 6-ft sample was sent to a commercial laboratory for analysis of chloride and TPH, resulting in a chloride concentration of <16 mg/kg, and concentrations of gasoline range organics (GRO) and diesel range organics (DRO) below detectable limits. The excavated soil was returned to the excavation and contoured to the surrounding area. On 7/28/2011, the site was seeded with a blend of native vegetation and is expected to return to a productive capacity at a normal rate. The junction box final report, photo documentation, laboratory analysis, PID sheet, chloride graph and revegetation form are attached.

Recommendations

Site investigation demonstrates that residual chloride and hydrocarbons in the vadose zone will not with reasonable probability contaminate groundwater in excess of NMOCD standards. This site meets the requirements of the NMOCD-approved Revised Junction

Box Upgrade Work Plan (July 16, 2003). As such, ROC request termination of the regulatory file, or similar closure status.

Please contact me at (575)393-9174 if you have any questions or wish to discuss this site. Thank you for your time and consideration.

Sincerely,

RICE Operating Company

Hack Conder

Environmental Manager

enclosures

RICE OPERATING COMPANY JUNCTION BOX FINAL REPORT

BOX LOCATION

Land Type: BLM		SWD SYSTEM	JUNCTION	UNIT	SECTION	TOWNSHIP	RANGE	COUNTY	BOX D	IMENSIONS - F	EET
LAND TYPE: BLM STATE X FEE LANDOWNER OTHER Depth to Groundwater 57 feet NMOCD SITE ASSESSMENT RANKING SCORE: 10 Date Started 6/30/2011 Date Completed 7/28/2011 OCD Witness No Soil Excavated 4.7 cubic yards Excavation Length 3 Width 7 Depth 6 feet Soil Disposed None cubic yards Offsite Facility n/a Location n/a FINAL ANALYTICAL RESULTS: Sample Date 6/30/2011 Sample Depth 6' TPH and Chloride laboratory test results completed by using an approved lab and testing procedures pursuant to NMOCD guidelines. Sample PID (field) GRO DRO Chloride Location ppm mg/kg mg/kg Mg/kg mg/kg SOURCE 6' GRAB 0.0 <10.0 <10.0 <16 General Description of Remedial Action: This junction and line were eliminated during the pipeline replacement/bupgrade program. After the former junction box was removed, an investigation was conducted using a backnot to collect soil samples at recolar at 37%-6ft. deep excavation. Chloride field tests performed on each sample yielded concentrations similar to that of the background sample. Organic vapors were measured using a PID. Which lyielded low concentrations. The deepest sample, 6 ft. BGS, was sent to a commercial laboratory for analysis of chloride and TPH, which confirmed low concentrations. The deepest sample, 6 ft. BGS, was sent to a commercial laboratory for analysis of chloride and TPH, which confirmed low concentrations for each. The excavation was backfilled with excavation and is expected to return to a productive capacity at a normal rate. enclosures: photos, lab results, PID (field) screenings, chloride graph, revegetation form and the supplement of the surrounding area. On 7/28/2011, the site was seeded with a blend of native vegetation and is expected to return to a productive capacity at a normal rate. EINTE SUPERVISOR Robert Egans SIGNATURE signature not available REPORT ASSEMBLED BY Laura Peña SIGNATURE signature not available		Eunice Monument	F-23 FOI	F	23	105	36F	Lea	Length		Depth
Depth to Groundwater 57 feet NMOCD SITE ASSESSMENT RANKING SCORE: 10 Date Started 6/30/2011 Date Completed 7/28/2011 OCD Witness No Soil Excavated 4.7 cubic yards Excavation Length 3 Width 7 Depth 6 feet Soil Disposed None cubic yards Offsite Facility n/a Location n/a FINAL ANALYTICAL RESULTS: Sample Date 6/30/2011 Sample Depth 6 TPH and Chloride laboratory test results completed by using an approved lab and testing procedures pursuant to NMOCD guidelines. Sample PID (field) GRO DRO Chloride mg/kg mg/kg SOURCE 6' GRAB 0.0 <10.0 <10.0 <18 CHLORIDE FIELD TESTS LOCATION DEPTH mg/kg SOURCE 6' GRAB 0.0 <10.0 <10.0 <18 CHLORIDE FIELD TESTS LOCATION DEPTH mg/kg Source 6' GRAB 0.0 <10.0 <10.0 <18 CHLORIDE FIELD TESTS LOCATION DEPTH mg/kg Source 6' GRAB 0.0 <10.0 <10.0 <18 CHLORIDE FIELD TESTS LOCATION DEPTH mg/kg Source 6' GRAB 0.0 <10.0 <10.0 <18 CHLORIDE FIELD TESTS LOCATION DEPTH mg/kg Source 6' GRAB 0.0 <10.0 <10.0 <18 CHLORIDE FIELD TESTS LOCATION DEPTH mg/kg Source 6' GRAB 0.0 <10.0 <10.0 <18 CHLORIDE FIELD TESTS LOCATION DEPTH mg/kg Source 6' S5 vertical 2' 53 delineation 3' 59 tercical 2' 53 delineation 3' 59 tercical 2' 53 delineation 3' 59 tercical 2' 53 delineation 3' 59 source 6' GRAB 0.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0 <10.0		Eumont (EME)	L-23 LOL			130	302			Eliminated	
Date Started 6/30/2011 Date Completed 7/28/2011 OCD Witness No Soil Excavated 4.7 cubic yards Excavation Length 3 Width 7 Depth 6 feet Soil Disposed None cubic yards Offsite Facility n/a Location n/a FINAL ANALYTICAL RESULTS: Sample Date 6/30/2011 Sample Depth 6' TPH and Chloride laboratory test results completed by using an approved lab and testing procedures pursuant to NMOCD guidelines. Sample PID (field) GRO DRO Chloride Location ppm mg/kg mg/kg mg/kg SOURCE 6' GRAB 0.0 < 10.0 < 10.0 < 16 General Description of Remedial Action: This junction and line were eliminated during the pipeline replacement/upgrade program. After the former junction box was removed, an investigation was conducted using a backhoe to collect soil samples at regular intervals creating a 3X7X6-ft, deep excavation. Chloride field tests performed on each sample yielded concentrations similar to that of the background samples. Organic vapors were measured using a PID, which yielded low concentrations of each The excavation was backfilled with excavated soil to ground surface and Contoured to the surrounding area. On 7/28/2011, the site was seeded with a blend of native vegetation and is expected to return to a productive capacity at a normal rate. I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF. SITE SUPERVISOR Robert Egans SIGNATURE signature not available REPORT ASSEMBLED BY Laura Peña SIGNATURE signature not available		LAND TYPE: E	3LM	STATE_X	FEE LA	NDOWNER			OTHER		
Soil Excavated 4.7 cubic yards Excavation Length 3 Width 7 Depth 6 feet Soil Disposed None cubic yards Offsite Facility n/a Location n/a FINAL ANALYTICAL RESULTS: Sample Date 6/30/2011 Sample Depth 6' TPH and Chloride laboratory test results completed by using an approved lab and testing procedures pursuant to NMOCD guidelines. Sample PID (field) GRO DRO Chloride Location ppm mg/kg m		Depth to Groun	ndwater	57	feet	NMOC	SITE ASS	ESSMENT	RANKING S	SCORE:	10
Soil Disposed None cubic yards Offsite Facility n/a Location n/a FINAL ANALYTICAL RESULTS: Sample Date 6/30/2011 Sample Depth 6' TPH and Chloride laboratory test results completed by using an approved lab and testing procedures pursuant to NMOCD guidelines. Sample PID (field) GRO DRO Chloride Location ppm mg/kg mg/kg mg/kg mg/kg SOURCE 6' GRAB 0.0 <10.0 <10.0 <16 General Description of Remedial Action: This junction and line were eliminated during the pipeline replacement/upgrade program. After the former junction box was removed, an investigation was conducted using a backhoe to collect soil samples at regular intervals creating a 3XTX6-ft. deep excavation. Chloride field tests performed on each sample yielded concentrations similar to that of the background sample. Organic vapors were measured using a PID, which yielded low concentrations. The deepest sample, 6 ft. BGS, was sent to a commercial laboratory for analysis of chloride and TPH, which confirmed low concentrations of each. The excavation was backfilled with excavated soil or ground surface and contoured to the surrounding area. On 7/28/2011, the site was seeded with a blend of native vegetation and is expected to return to a productive capacity at a normal rate. I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF. SITE SUPERVISOR Robert Egans SIGNATURE signature not available REPORT ASSEMBLED BY Laura Peña SIGNATURE signature not available COMPANY RICE OPERATING COMPANY		Date Started	6/30	/2011	Date Co	mpleted	7/28/2011	OCD	Witness	<u>No</u>	
TPH and Chloride laboratory test results completed by using an approved lab and testing procedures pursuant to NMOCD guidelines. Sample		Soil Excavated	4.7	cubic ya	rds Exc	cavation Le	ngth 3	Width	7	_ Depth	6 feet
TPH and Chloride laboratory test results completed by using an approved lab and testing procedures pursuant to NMOCD guidelines. Sample		Soil Disposed	None	cubic ya	rds Of	fsite Facility	n	/a	_ Location	n/a	1
Sample PID (field) GRO DRO Chloride Location Ppm mg/kg background 6" 55 SOURCE 6' GRAB 0.0 <10.0 <10.0 <10.0 <16 General Description of Remedial Action: This junction and line were eliminated during the pipeline replacement/upgrade program. After the former junction box was removed, an investigation was conducted using a backhoe to collect soil samples at regular intervals creating a 3X7X6-ft. deep excavation. Chloride field tests performed on each sample yielded concentrations similar to that of the background sample. Organic vapors were measured using a PID, which yielded low concentrations. The deepest sample, 6 ft. BGS, was sent to a commercial laboratory for analysis of chloride and TPH, which confirmed low concentrations of each. The excavation was backfilled with excavated soil to ground surface and contoured to the surrounding area. On 7/28/2011, the site was seeded with a blend of native vegetation and is expected to return to a productive capacity at a normal rate. I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF. SITE SUPERVISOR Robert Egans SIGNATURE signature not available REPORT ASSEMBLED BY Laura Peña SIGNATURE company	FINA	AL ANALYTI	CAL RE	SULTS:	Sample	e Date	6/30/201	1	Sample De	epth	6'
SOURCE 6' GRAB 0.0 <10.0 <10.0 <16 Comparison Compar	,		TPH and C		-		•	•	oved lab and	d testing	
SOURCE 6' GRAB 0.0 <10.0 <10.0 <10.0 <16 background 6' 55 vertical 2' 53 delineation 3' 59 termoved, an investigation was conducted using a backhoe to collect soil samples at regular intervals creating a 3X7X6-ft, deep excavation. Chloride field tests performed on each sample yielded concentrations similar to that of the background sample. Organic vapors were measured using a PID, which yielded low concentrations of each. The excavation was backfilled with excavated soil to ground surface and contoured to the surrounding area. On 7/28/2011, the site was seeded with a blend of native vegetation and is expected to return to a productive capacity at a normal rate. I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF. SITE SUPERVISOR Robert Egans SIGNATURE Signature not available Signature not available Signature Signature not available Signature Signature		Sample	PID (fie	eld) G	RO	DRO	Chloride			RIDE FIELD T	ESTS
General Description of Remedial Action: This junction and line were eliminated delineation trench at the junction are pipeline replacement/upgrade program. After the former junction box was removed, an investigation was conducted using a backhoe to collect soil samples at regular intervals creating a 3X7X6-ft. deep excavation. Chloride field tests performed on each sample yielded concentrations similar to that of the background sample. Organic vapors were measured using a PID, which yielded low concentrations. The deepest sample, 6 ft. BGS, was sent to a commercial laboratory for analysis of chloride and TPH, which confirmed low concentrations of each. The excavation was backfilled with excavated soil to ground surface and contoured to the surrounding area. On 7/28/2011, the site was seeded with a blend of native vegetation and is expected to return to a productive capacity at a normal rate. I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF. SITE SUPERVISOR Robert Egans SIGNATURE signature not available REPORT ASSEMBLED BY Laura Peña SIGNATURE signature not available COMPANY RICE OPERATING COMPANY RICE OPERATING COMPANY RICE OPERATING COMPANY RICE OPERATING COMPANY RICE OPERATING COMPANY		Location	ppm	n m	g/kg	mg/kg	mg/kg		OCATION	DEPTH	mg/kg
General Description of Remedial Action: This junction and line were eliminated during the pipeline replacement/upgrade program. After the former junction box was removed, an investigation was conducted using a backhoe to collect soil samples at regular intervals creating a 3X7X6-ft. deep excavation. Chloride field tests performed on each sample yielded concentrations similar to that of the background sample. Organic vapors were measured using a PID, which yielded low concentrations. The deepest sample, 6 ft. BGS, was sent to a commercial laboratory for analysis of chloride and TPH, which confirmed low concentrations of each. The excavation was backfilled with excavated soil to ground surface and contoured to the surrounding area. On 7/28/2011, the site was seeded with a blend of native vegetation and is expected to return to a productive capacity at a normal rate. I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF. SITE SUPERVISOR Robert Egans SIGNATURE signature not available REPORT ASSEMBLED BY Laura Peña SIGNATURE signature not available COMPANY RICE OPERATING COMPANY RICE OPERATING COMPANY RICE OPERATING COMPANY RICE OPERATING COMPANY RICE OPERATING COMPANY	SC	URCE 6' GRAB	0.0	<	10.0	<10.0	<16	b	ackground	6"	55
General Description of Remedial Action: This junction and line were eliminated during the pipeline replacement/upgrade program. After the former junction box was removed, an investigation was conducted using a backhoe to collect soil samples at regular intervals creating a 3X7X6-ft. deep excavation. Chloride field tests performed on each sample yielded concentrations similar to that of the background sample. Organic vapors were measured using a PID, which yielded low concentrations. The deepest sample, 6 ft. BGS, was sent to a commercial laboratory for analysis of chloride and TPH, which confirmed low concentrations of each. The excavation was backfilled with excavated soil to ground surface and contoured to the surrounding area. On 7/28/2011, the site was seeded with a blend of native vegetation and is expected to return to a productive capacity at a normal rate. I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF. SITE SUPERVISOR Robert Egans SIGNATURE signature not available REPORT ASSEMBLED BY Laura Peña SIGNATURE signature not available COMPANY RICE OPERATING COMPANY RICE						-			vertical	2'	53
General Description of Remedial Action: This junction and line were eliminated during the pipeline replacement/upgrade program. After the former junction box was removed, an investigation was conducted using a backhoe to collect soil samples at regular intervals creating a 3X7X6-ft. deep excavation. Chloride field tests performed on each sample yielded concentrations similar to that of the background sample. Organic vapors were measured using a PID, which yielded low concentrations. The deepest sample, 6 ft. BGS, was sent to a commercial laboratory for analysis of chloride and TPH, which confirmed low concentrations of each. The excavation was backfilled with excavated soil to ground surface and contoured to the surrounding area. On 7/28/2011, the site was seeded with a blend of native vegetation and is expected to return to a productive capacity at a normal rate. I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF. SITE SUPERVISOR Robert Egans SIGNATURE signature not available REPORT ASSEMBLED BY Laura Peña SIGNATURE COMPANY RICE OPERATING COMPANY ASSEMBLED BY Laura Peña SIGNATURE COMPANY RICE OPERATING COMPANY								، ا		3'	59
during the pipeline replacement/upgrade program. After the former junction box was removed, an investigation was conducted using a backhoe to collect soil samples at regular intervals creating a 3X7X6-ft. deep excavation. Chloride field tests performed on each sample yielded concentrations similar to that of the background sample. Organic vapors were measured using a PID, which yielded low concentrations of each. The deepest sample, 6 ft. BGS, was sent to a commercial laboratory for analysis of chloride and TPH, which confirmed low concentrations of each. The excavation was backfilled with excavated soil to ground surface and contoured to the surrounding area. On 7/28/2011, the site was seeded with a blend of native vegetation and is expected to return to a productive capacity at a normal rate. I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF. SITE SUPERVISOR Robert Egans SIGNATURE signature not available REPORT ASSEMBLED BY Laura Peña SIGNATURE company Rice OPERATING COMPANY RICE OP	Canai	ral Description	of Remedi	al Action:	This junction	on and line w	ere eliminate				
removed, an investigation was conducted using a backhoe to collect soil samples at regular intervals creating a 3X7X6-ft. deep excavation. Chloride field tests performed on each sample yielded concentrations similar to that of the background sample. Organic vapors were measured using a PID, which yielded low concentrations. The deepest sample, 6 ft. BGS, was sent to a commercial laboratory for analysis of chloride and TPH, which confirmed low concentrations of each. The excavation was backfilled with excavated soil to ground surface and contoured to the surrounding area. On 7/28/2011, the site was seeded with a blend of native vegetation and is expected to return to a productive capacity at a normal rate. I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF. SITE SUPERVISOR Robert Egans SIGNATURE signature not available REPORT ASSEMBLED BY Laura Peña SIGNATURE ALL ALL ALL ALL ALL ALL ALL ALL ALL AL											
regular intervals creating a 3X7X6-ft. deep excavation. Chloride field tests performed on each sample yielded concentrations similar to that of the background sample. Organic vapors were measured using a PID, which yielded low concentrations. The deepest sample, 6 ft. BGS, was sent to a commercial laboratory for analysis of chloride and TPH, which confirmed low concentrations of each. The excavation was backfilled with excavated soil to ground surface and contoured to the surrounding area. On 7/28/2011, the site was seeded with a blend of native vegetation and is expected to return to a productive capacity at a normal rate. I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF. SITE SUPERVISOR Robert Egans SIGNATURE signature not available REPORT ASSEMBLED BY Laura Peña SIGNATURE ALURA COMPANY RICE OPERATING COMPANY RICE OPERATING COMPANY RICE OPERATING COMPANY RICE OPERATING COMPANY RICE OPERATING COMPANY									•		
each sample yielded concentrations similar to that of the background sample. Organic vapors were measured using a PID, which yielded low concentrations. The deepest sample, 6 ft. BGS, was sent to a commercial laboratory for analysis of chloride and TPH, which confirmed low concentrations of each. The excavation was backfilled with excavated soil to ground surface and contoured to the surrounding area. On 7/28/2011, the site was seeded with a blend of native vegetation and is expected to return to a productive capacity at a normal rate. I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF. SITE SUPERVISOR Robert Egans SIGNATURE signature not available REPORT ASSEMBLED BY Laura Peña SIGNATURE COMPANY RICE OPERATING COMPANY RICE OPERATING COMPANY RICE OPERATING COMPANY RICE OPERATING COMPANY RICE OPERATING COMPANY RICE OPERATING COMPANY N. — 1 12 — 12								L_ _	· · · · · · · · · · · · · · · · · · ·	0	
vapors were measured using a PID, which yielded low concentrations. The deepest sample, 6 ft. BGS, was sent to a commercial laboratory for analysis of chloride and TPH, which confirmed low concentrations of each. The excavation was backfilled with excavated soil to ground surface and contoured to the surrounding area. On 7/28/2011, the site was seeded with a blend of native vegetation and is expected to return to a productive capacity at a normal rate. enclosures: photos, lab results, PID (field) screenings, chloride graph, revegetation form enclosures: photos, lab results, PID (field) screenings, chloride graph, revegetation form BELIEF. SITE SUPERVISOR Robert Egans SIGNATURE signature not available REPORT ASSEMBLED BY Laura Peña SIGNATURE COMPANY RICE OPERATING COMPANY ASSEMBLED BY Laura Peña SIGNATURE COMPANY RICE OPERATING COMPANY							_ •				
laboratory for analysis of chloride and TPH, which confirmed low concentrations of each. The excavation was backfilled with excavated soil to ground surface and contoured to the surrounding area. On 7/28/2011, the site was seeded with a blend of native vegetation and is expected to return to a productive capacity at a normal rate. enclosures: photos, lab results, PID (field) screenings, chloride graph, revegetation form I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF. SITE SUPERVISOR Robert Egans SIGNATURE signature not available REPORT ASSEMBLED BY Laura Peña SIGNATURE COMPANY RICE OPERATING COMPANY **RICE OPERATING COMPANY** **RI									BGS, was sen	t to a commerc	cial
excavated soil to ground surface and contoured to the surrounding area. On 7/28/2011, the site was seeded with a blend of native vegetation and is expected to return to a productive capacity at a normal rate. enclosures: photos, lab results, PID (field) screenings, chloride graph, revegetation form I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF. SITE SUPERVISOR Robert Egans SIGNATURE signature not available REPORT ASSEMBLED BY Laura Peña SIGNATURE COMPANY RICE OPERATING COMPANY											
enclosures: photos, lab results, PID (field) screenings, chloride graph, revegetation form I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF. SITE SUPERVISOR Robert Egans SIGNATURE signature not available REPORT ASSEMBLED BY Laura Peña SIGNATURE AND COMPANY RICE OPERATING COMPANY N. 1715-172											
I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF. SITE SUPERVISOR Robert Egans SIGNATURE signature not available REPORT ASSEMBLED BY Laura Peña SIGNATURE ALLE COMPANY RICE OPERATING COMPANY											
I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF. SITE SUPERVISOR Robert Egans SIGNATURE signature not available REPORT ASSEMBLED BY Laura Peña SIGNATURE ALLE COMPANY RICE OPERATING COMPANY			-								
I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF. SITE SUPERVISOR Robert Egans SIGNATURE signature not available REPORT ASSEMBLED BY Laura Peña SIGNATURE ALLE COMPANY RICE OPERATING COMPANY					enclosur	es: photos l	ab results. P	ID (field) scr	eenings chlo	ride graph, rev	egetation form
BELIEF. SITE SUPERVISOR Robert Egans SIGNATURE signature not available REPORT ASSEMBLED BY Laura Peña SIGNATURE ALLE PROPERATING COMPANY RICE OPERATING COMPANY N 1/1:- 1/2:-										ando grapin, ro	
REPORT ASSEMBLED BY Laura Peña SIGNATURE AURA PEÑA COMPANY RICE OPERATING COMPANY N-1/1-1/1-1/2-1/2											
ASSEMBLED BY Laura Peña SIGNATURE AURA PEÑA COMPANY RICE OPERATING COMPANY N. 1/2: 1/2: 1/2	SITE S	UPERVISOR	Robert Ega	ans SIC	SNATURE	signat	ure not availat	ole	_		
ASSEMBLED BY Laura Peña SIGNATURE AURA PEÑA COMPANY RICE OPERATING COMPANY N. 1/2: 1/2: 1/2	p	FPORT					c /	//			
VI-10-12			Laura Per	ia SIG	NATURE /	10114	$a \times a$	na	COMPANY	' RICE OPERAT	TING COMPANY
PROJECT LEADER Zach Conder SIGNATURE DATE Y-10-12	73	2	Lauia FEI	310		Juin	~/ ~		- COMICAINT	NOL OF EIVA	INTO CONFAINT
	PROJE	CT LEADER	Zach Cond	der Sic	NATURE S	/ 			DATE	4-10	-12
				<u></u> 510		-			_		

EME E-23 EOL

Unit E, Section 23, T19S, R36E



Site prior to excavating, facing north

6.30.11



Digging source, facing south

6.30.11



Backfilling site, facing east

6.30.11



Seeding site, facing north

7.28.11



Raking in seed, facing north

7.28.11



Site completed, facing north

7.28.11



July 05, 2011

Bruce Baker

Rice Operating Company

112 W. Taylor

Hobbs, NM 88240

RE: EME E-23 EOL

Enclosed are the results of analyses for samples received by the laboratory on 06/30/11 16:17.

Cardinal Laboratories is accredited through Texas NELAP for:

Method SW-846 8021

Benzene, Toluene, Ethyl Benzene, and Total Xylenes

Method SW-846 8260

Benzene, Toluene, Ethyl Benzene, and Total Xylenes

Method TX 1005

Total Petroleum Hydorcarbons

Certificate number T104704398-08-TX. Accreditation applies to solid and chemical materials and non-potable water matrices.

Cardinal Laboratories is accreditated through the State of Colorado Department of Public Health and Environment for:

Method EPA 552.2

Haloacetic Acids (HAA-5)

Method EPA 524.2

Total Trihalomethanes (TTHM)

Method EPA 524.4

Regulated VOCs (V2, V3)

Accreditation applies to public drinking water matrices.

Celey D. Keine

This report meets NELAP requirements and is made up of a cover page, analytical results, and a copy of the original chain-of-custody. If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Celey D. Keene

Lab Director/Quality Manager



Analytical Results For:

Rice Operating Company Bruce Baker 112 W. Taylor Hobbs NM, 88240

Fax To:

(575) 397-1471

Received: Reported: 06/30/2011

07/05/2011

EME E-23 EOL

Project Name: Project Number:

NONE GIVEN

Project Location:

NOT GIVEN

Sampling Date:

06/30/2011

Sampling Type:

Soil

Sampling Condition:

Cool & Intact

Sample Received By:

Jodi Henson

Sample ID: SOURCE @ 6' (H101360-01)

Chloride, SM4500Cl-B

mg/kg

Analyzed By: HM

Cimentally Cittle Control	***************************************		· · · · · · · · · · · · · · · · · · ·						
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Chloride	<16.0	16.0	07/01/2011	ND	416	104	400	3.77	
ТРН 8015М	mg	/kg	Analyze	d By: ab					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
GRO C6-C10	<10.0	10.0	07/01/2011	ND	163	81.5	200	3.90	
DRO >C10-C28	<10.0	10.0	07/01/2011	ND	149	74.3	200	1.95	
Surrogate: 1-Chlorooctane	109	% 70-130)					_	
Swrogate: 1-Chlorooctadecane	106	% 70-131) .						



Cardinal Laboratories

*=Accredited Analyte

FLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by clerit, its subdidiaries, affiliates or successors arising out of or related to the performance of the services hereunder by Cardinal, regardless of whether such claims is based upon any of the above stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.

Celegi Keena



ND

Notes and Definitions

RPD Relative Percent Difference

** Samples not received at proper temperature of 6°C or below.

*** Insufficient time to reach temperature.

Chloride by SM4500Ct-B does not require samples be received at or below 6°C

Samples reported on an as received basis (wet) unless otherwise noted on report

Analyte NOT DETECTED at or above the reporting limit



Cardinal Laboratories

*=Accredited Analyte

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of the services hereunder by Cardinal, regardless of whether such claims based upon any of the above stated reasons or otherwise. Results relate only to the samples identified above. This

Celeg & Keene

Laboratories

† Cardinal cannot accept verbal changes. Please fax written changes to 505-393-2476

CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

Page 4 of 4

101 East Mariand, Hobbs, NM 88240 (505) 393-2326 FAX (505) 393-2476 KICE Operation Company Hame: BILL TO ANALYSIS REQUEST Project Manager: Bruse Baker P.O. #: Address: 122 W Taylor Company: city: Hobbs NM Atin: Phone #: 353 - 9771 Fa:: #: Address: Project #: Project Owner: City: Project Name: State: Zip: Project Location: EME E-23 ECA Phone #: Kubert Egans Sampler Namo: Fax #: MATRIX PRESERV SAMPLING FOR LAB USE ONLY (S) (G)RAB OR (C)OMP. WASTEWATER ACID/BASE: ICE / COOL OTHER: Sample I.D. Lab I.D. OIL SOIL H101360 DATE TIME Sucret 666 6- 60 1_ 10 medy for any claim arising whether based in contract or tort, shall be limited to the amount paid by the cliem to the analysis. All claims including those for negligence and any other cause white control to deemed waived unloss made in writing and received by Cardinal within 30 days after completion of the applicable service. In no event shalf Cardinal be listife for incidental or consequential demages, including willhout limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, alfilities of successors prising out of or related to the performance of services belounder by Carolinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise. ☐ Yes ☐ No Add'l Phone #:
☐ Yes ☐ No Add'l Fax #: Relinquished By: Received By: Phone Result: Fax Result: REMARKS: Bruse Zouk, Lava, Robert Relinguished By: Date: Received By: Time: Delivered By: (Circle One) Sample Condition CHECKED BY: (Irritials) Cool /Intact / Yes Yes Sampler - UPS - Bus - Other:

RICE ENVIRONMENTAL CONSULTING & SAFETY

122 West Taylor Hobbs, NM 88240 PHONE: (505) 393-9174 FAX: (505) 397-1471 PID METER CALIBRATION & FIELD REPORT FORM

METER READING ACCURACY:

CK.	X	MODEL: PGM 7300	SERIAL NO: 590-000508
MODEL		MODEL: PGM 7300	SERIAL NO: 590-000504
NO.		MODEL: PGM 7320	SERIAL NO: 592-903318
		MODEL: PGM 7300	SERIAL NO: 590-000183
		GAS COMPOSITION	: ISOBUTYLENE 100PPM / AIR: BALANCE
LOT NO	930737		EXPIRATION DATE:6-16-2013

ACCURACY: +/- 2% 100PPM

COMPANY	
RICE	

SYSTEM	JUNCTION	UNIT	SECTION	TOWN SHIP	RANGE
EME	E-23 EOL	Е	23	T19S	R36E

SAMPLE ID	PID	SAMPLE ID	PID
BACK GROUND	0		
SOURCE @ 2'	0		
SOURCE @ 3'	0		
SOURCE @ 4'	0		
SOURCE @ 5'	0		
SOURCE @ 6'	0		
			9 V
			LI .

I verify that I have calibrated the above instrument in accordance to the manufacture operation manual.

SIGNATURE: State of These

DATE: 6-30-2011


EME E-23 EOL

Unit 'E', Sec. 23, T19S, R36E

Backhoe samples at junction (source)

Depth bgs (ft)	[Cl] ppm
2	53
3	59
4	56
5	53
. 6	80

Groundwater = 57 ft





PO Box 5630 Hobbs, NM 88241 Phone: (575) 393-4411 Fax: (575) 393-0293

REVEGETATION FORM

1. General Information EME E-23 EOL Site name: Section U/L Township Range County Latitude Longitude E 23 19S 36E Lea N 32*38.769' W 103*16.629' Bruce Baker Contact Name: Email: bbaker@rice-esc.com Map detail of site attached Site size. square feet Additional information: 2. Soils *Do not rip caliche subsoils; caliche rocks brought to the surface by ripping shall be removed. Bioremediated Imported Blended Salvaged from site Texture: Sandy Describe soil & subsoil: Soil prep methods: Rip Depth(in): Disc 🗌 Depth (in): Rollerpack [Date completed: 3. Bioremediation Fertilizer Hay \square Other 🗌 Describe: Type: Lbs/acre: *Attach seed bag tags to this form. Seed bag tags shall contain the site name and S-T-R. Custom seed mix X Prescribed mix Seed mix name: Warm Season Mix Seeding date: 7/28/2011 Broadcast 🛛 Method: Soil conditions during seeding: Dry 🛛 Damp [Wet [Photos attached Observations: Number of photos: 5. Certification I hereby certify that the information in this form and attachments is true and complete to the best of my knowledge and belief. Name: Robert Egans Title: Environmental Tech Date: 7/28/2011 Rolled your Signature:

