


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd. 192463	Contact	Christopher Jones
Address	1502 W. Commerce Drive, Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Winston Gas Com Btry	Facility Type	Gathering

Surface Owner	BLM	Mineral Owner		Lease No.	NM LC 063246
---------------	-----	---------------	--	-----------	--------------

LOCATION OF RELEASE

APZ: 30-015-28633
Winston Gas Com # 2

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	31	21S	24E					Eddy County, NM

Latitude N 32.441

Longitude W 104.536

NATURE OF RELEASE

Type of Release	Oil and Produced Water	Volume of Release	700 bbls	Volume Recovered	650 bbls
Source of Release	Gasket failure on free water knockout	Date and Hour of Occurrence	08/10/2012 @ 8:00 am	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD; Terry Gregston-BLM		
By Whom?	Chris Jones	Date and Hour	08/14/2012 @ 10:08 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A gasket failure on the free water knockout caused 700 bbls of oil and produced water to leak onto the ground 650 bbls of liquid were recovered via vacuum truck Remediation will be performed according to a NMOCD and BLM approved remediation plan.

Describe Area Affected and Cleanup Action Taken *

The area affected is approximately 60' x 150' 650 bbls of oil and produced water were recovered and additional remediation will be performed according to a NMOCD and BLM approved remediation plan

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:			
Printed Name:	Christopher Jones	Approved by District Supervisor.	Signed By
Title:	HES Specialist	Approval Date:	SEP 11 2012 Expiration Date.
E-mail Address:	Christopher_Jones@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date:	Phone: (575) 328-4121		

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**

October 11th 2012

2RP-1281

Bratcher, Mike, EMNRD

From: Christopher_Jones@oxy.com
Sent: Wednesday, September 05, 2012 12:57 PM
To: Terry_Gregston@blm.gov; Bratcher, Mike, EMNRD
Cc: kswinney@bbcinternational.com; cbrunson@bbcinternational.com
Subject: Winston Gas Com

Sorry, thought that this was sent already.

This is to inform you that Oxy Permian Primary had a produced water leak on the Winston Gas Com Battery on August 10, 2012. Oxy released 800 bbls of oil and produced water and recovered 750 bbls due to equipment failure on separator equipment. The location is located at NM LC 063246 UNIT B SECT 31 TS 21 S RANGE 24 E EDDY COUNTY NEW MEXICO Oxy will do some initial remediation, a C-141 to follow. BBC International will delineate at a later date. Driving directions: HWY 137 MILE MARKER 41 TURN RIGHT AT OXY SIGN FOLLOW RD TO BATTERY.

Chris Jones
HES Specialist
Permian Primary Production
Carlsbad, NM
Cell 575-499-3337
Off 575-628-4121

"We do not inherit the earth from
our ancestors; we borrow it from
our children." Chief Seattle

Bratcher, Mike, EMNRD

From: Tiffney_Burkham@oxy.com
Sent: Tuesday, August 28, 2012 6:29 AM
To: Bratcher, Mike, EMNRD
Subject: C-141 Winston, Rogers
Attachments: Document.pdf

Mike

I sent these to you by mail and they got returned back to me. If you have any questions please call me.

Thanks,

Tiffney Burkham | Oxy Permian - HES Administrative Assistant | O: 575-628-4116 | C: 575-706-4374

Bratcher, Mike, EMNRD

From: Christopher_Jones@oxy.com
Sent: Tuesday, August 14, 2012 7:13 AM
To: Bratcher, Mike, EMNRD; Terry_Gregston@blm.gov; cbrunson@bbcinternational.com; kswinney@bbcinternational.com
Cc: Tiffney_Burkham@oxy.com; Mark_Richards@oxy.com
Subject: Winston Gas Com

This is to inform you that Oxy Permian Primary had a produced water leak on the Winston Gas Com on August 11, 2012. Oxy released 700 bbls of oil and produced water and recovered 650 bbls due to a gasket failing on the free water knock out. The location is located at UNIT B SECT 31 TS 21 S RANGE 24 E EDDY COUNTY NEW MEXICO. Oxy will do some initial remediation, a C-141 to follow. BBC International will delineate at a later date. Driving directions: HWY 137 MILE MARKER 41 TURN RIGHT AT OXY SIGN FOLLOW RD TO BATTERY.

Chris Jones
HES Specialist
Permian Primary Production
Carlsbad, NM
Cell 575-499-3337
Off 575-628-4121

"We do not inherit the earth from
our ancestors; we borrow it from
our children." Chief Seattle