

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW 1225753966

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. 260737	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU-183 Flow line spill location is 1700 ft. N.W. of the well location on Rawhide Road	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-33224
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter O	Section 6	Township 24S	Range 30 E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	--------------	-----------------	---------------	---------------	------------------	---------------	----------------	----------------

Latitude N 32.240774 Longitude W 103.918504

NATURE OF RELEASE

Type of Release: Produced water and crude oil	Volume of Release: 3 bbls crude oil and 5 bbls. produced water	Volume Recovered: 3 bbls total fluid
Source of Release: 2 7/8 inch flow line	Date and Hour of Occurrence: 9/2/12 time unknown	Date and Hour of Discovery: 9/2/12 8:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The 2 7/8 inch flow developed a leak due to external corrosion. A temporary leak clamp was installed on the pipe.

Describe Area Affected and Cleanup Action Taken.*

The spill occurred in the lease road, approximately 200 sq.ft. was affected by the release and response activities. The saturated soil was removed from the road way and placed on a nearby well pad. Clean caliche was used to cover the area for traffic use. The spill will be remediated in accordance to the NMOCD recommended guidelines for spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Tony Savoie</u>		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist: <u>Signed By M/L B...</u>	
Title: Waste Management and Remediation Specialist		Approval Date: SEP 13 2012	Expiration Date:
E-mail Address: tasavoie@basspet.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 9/5/12	Phone: 432-556-8730	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: October 13, 2012	

* Attach Additional Sheets If Necessary

RECEIVED
SEP 06 2012
NMOCD ARTESIA

2RP-1296