District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Attesta, NM 88210 District III 1600 Ro Brazos Road, Aztec, NM 87410 District IV

E-mail Address atrujillo@yatespetroleum.com

Date Monday September 24, 2012

Attach Additional Sheets If Necessary

State of New Mexico Energy Minerals and Natural Resources

SEP 24 2012

NMOCD ARTESIA

RECEIVED

Form C-141 Revised October 10, 2003

12 Copies to appropriate let Office in accordance with Rule 116 on back side of form

## Oil Conservation Division 1220 South St. Francis Dr. Santa Fa. NM 87505

1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505 Release Notification and Corrective Action nJMW1229736540 **OPERATOR** [X] Initial Report ☐ Final Report Name of Company OGRID Number Contact Yates Petroleum Corporation 25575 Amanda Trujillo Address Telephone No. 104 S. 4<sup>1H</sup> Street 575-748-1471 Facility Name Facility Type API Number Order Number Anemone ANE Federal #2 30-015-27982 Gas well 2RP-Surface Owner Mineral Owner Lease No. Pederal Federal NM - 78214 LOCATION OF RELEASE Cont Letter Section Township , Range Feet from the North/South Line | Feet from the Fast/West Line County 840 1) \_22\$ 24E 1090 NORTH WEST TDDY NATURE OF RELEASE Type of Release Volume of Release Volume Recovered 10 oil OIL. 10 oil Date and Hour of Occurrence Source of Release Date and Hour of Discovery Equipment failure on pumps and alarms 9/18/2012 9/18/2012 - PM Was Immediate Notice Criven? If YES, To Whom? Mike Bratcher - NMOCD/Artesia By Whom? Date and Hour Amanda Trujillo Yates Petroleum Corporation 9/24/2012 Was a Watercourse Reached? If YES, Volume Impacting the Watercourse, ☐ Yes ⊠ No If a Watercourse was Impacted, Describe Fully MA Describe Cause of Problem and Remedial Action Taken.\* Remuda Energy, Oil Transporter, was pulling a load of oil off the tanks when it a hose failed and caused a spill. Trucker reversed flow back into tank to contain remaining oil Describe Area Affected and Cleanup Action Taken.\* An approximate size of 30° x 40° was impacted. The impacted area is located in front of the storage tanks. Soil from the pooling areas was excavated and disposed of at an NMOCD approved facility. Vertical and horizontal delineation samples will taken and analysis ran for TPH and BTEX once all contaminated material has been removed. Depth to Ground Water; >100' (approx. 585', per New Mexico State Engineers Office); Wellhead Protection Area: No: Distance to Surface Water Body: >1000'; SITE RANKING IS 0. Thereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions to releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of hability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health of the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for comphance with any other federal, state, or local laws and/or regulations OIL CONSERVATION DIVISION Signature Approved by District Supervisor. Signed By Printed Name: Amanda Trujillo Title, Environmental Scientist Expiration Date

Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:

November 23, 2012

Phone: 575-748-4310

Conditions of Approval

2RP-1333

Attached [

## Bratcher, Mike, EMNRD

From:

Amanda Trujillo <atrujillo@yatespetroleum.com>

Sent:

Monday, September 24, 2012 5:23 PM

To:

Jennifer Palma; Jerry Fanning; Jim Amos (James\_Amos@blm.gov); Bratcher, Mike,

**EMNR** 

Subject:

Anemome ANE Federal Battery Anenome (Inital 9-18-2012).pdf

Mr. Bratcher:

Attachments:

Anemone ANE Federal #2

Section 9, Township 22 South, Range 23 East

**Eddy County** 

Date of Release: 9/18/2012

Approximately 10 bbls oil released; 0 bbls recovered

Cause of release was due to Remuda Energy, while picking up a load of oil. A broken hose on the truck was a result.

Attached is the C-141

If you should have any questions please feel free to contact me at the number below

Amanda N. Trujillo
Environmental Scientist
Yates Petroleum Corporation
Office 575-748-4310

Cell 575-703-6537

Email atrujillo@yatespetroleum.com

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.