

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JAN 03 2013

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW 1301552456

Name of Company Oxy Permian Ltd. 192463		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address 1502 W. Commerce Dr., Carlsbad, NM		Contact Christopher Jones			
Facility Name Righthand Canyon 35-7 SWD		Telephone No. (575) 628-4121			
		Facility Type SWD			
Surface Owner		Mineral Owner		Lease No. API#30-015-34529	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	35	21S	24E	1975	South	2405	West	Eddy County, NM

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 175 bbls	Volume Recovered 0 bbls
Source of Release Failure in 2" valve on the discharge line	Date and Hour of Occurrence 12/27/2012	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher- OCD, James Amos-BLM, Terry Gregston-BLM	
By Whom? Christopher Jones	Date and Hour 12/27/2012 @ 1:53 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Failure in a 2" valve on the discharge line caused 175 bbls of produce water to leak onto the ground. Fluids were not recoverable. The valve was repaired.

Describe Area Affected and Cleanup Action Taken.*

Failure in a 2" valve on the discharge line caused 175 bbls of produce water to leak onto the ground. Fluids were not recoverable. Remediation will be performed in accordance with an OCD and BLM approved remediation plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Christopher Jones		Approved by District Supervisor:	Signed By 
Title: HES Specialist		Approval Date: JAN 15 2013	Expiration Date:
E-mail Address: Christopher.Jones@oxy.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 1-3-13 Phone: (575) 628-4121			

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:

February 15, 2013

2RP-1493

Bratcher, Mike, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Thursday, January 03, 2013 10:46 AM
To: Christopher_Jones@oxy.com; jamos@blm.gov; Bratcher, Mike, EMNRD;
tgregsto@blm.gov; kswinney@bbcinternational.com; cbrunson@bbcinternational.com
Cc: Mark_Richards@oxy.com; Tiffney_Burkham@oxy.com
Subject: Correction: Righthand Canyon 35-7 SWD

Correction: The API number for the Righthand Canyon 35-7 SWD is 30-015-34529. If you have any questions, please contact me.

Kathy Purvis
BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388
Fax: (575) 397-0397
Email: kathy@bbcinternational.com

-----Original Message-----

From: Christopher_Jones@oxy.com [mailto:Christopher_Jones@oxy.com]
Sent: Thursday, December 27, 2012 1:53 PM
To: jamos@blm.gov; Mike.Bratcher@state.nm.us; tgregsto@blm.gov; kswinney@bbcinternational.com;
cbrunson@bbcinternational.com; kathy@bbcinternational.com
Cc: Mark_Richards@oxy.com; Tiffney_Burkham@oxy.com
Subject: Righthand canyon 35-7 SWD

This is to inform you that Oxy Permian Primary had a spill of produced water at the Righthand canyon 35-7 SWD on December 27, 2012. Oxy released 175 bbls of produced water, 0 bbls was recovered. Leak was due to failure in the 2" valve on the discharge line. Oxy will have BBC do some initial remediation, a C-141 to follow. BBC will delineate at a later date.

REGULATORY LEASE # NM 53218 API30-015-34259<tel:30-015-34259> SECT 35 T21S R24E EDDY COUNTY NEW MEXICO
WEATHER COLD OVERCASTHWY 285 NORTH FROM CARLSBAD GO 15 MILES, TURN WEST ON CR137 GO 10 MILES, TURN SOUTH ONTO MAIN DIRT RD GO UP HILL 3 MILES, FACILITY ON RIGHT.

Chris Jones
HES Specialist
Permian Primary Production
Carlsbad, NM
Cell 575-499-3337
Off 575-628-4121

"We do not inherit the earth from our ancestors; we borrow it from our children." Chief Seattle

Bratcher, Mike, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Thursday, January 03, 2013 11:13 AM
To: jamos@blm.gov; Bratcher, Mike, EMNRD; tgregsto@blm.gov
Cc: christopher_jones@oxy.com; cbrunson@bbcinternational.com;
kswinney@bbcinternational.com; jgilkey@bbcinternational.com
Subject: Initial C-141 for Righthand Canyon 35-7 SWD
Attachments: Initial C-141, signed and sent 1-3-13.pdf

Attached is the initial C-141 for a leak occurring at the Righthand Canyon 35-7 SWD on 12/27/2012 in Eddy County, NM. Receipt notification via email is greatly appreciated. Please contact me if you have any questions.

Kathy Purvis

BBC International, Inc.

1324 W. Marland

Hobbs, NM 88240

Phone: (575) 397-6388

Fax: (575) 397-0397

Email: kathy@bbcinternational.com

Bratcher, Mike, EMNRD

From: Amos, James <jamos@blm.gov>
Sent: Thursday, January 03, 2013 12:59 PM
To: Kathy Purvis
Cc: Bratcher, Mike, EMNRD; tgregsto@blm.gov; christopher_jones@oxy.com; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com
Subject: Re: Initial C-141 for Righthand Canyon 35-7 SWD

Received. Please provide a copy of the water analysis for the fluids that were spilled along with a rough schematic of the spill site and the flow path of the fluids. thanks

On Thu, Jan 3, 2013 at 11:12 AM, Kathy Purvis <kathy@bbcinternational.com> wrote:

Attached is the initial C-141 for a leak occurring at the Righthand Canyon 35-7 SWD on 12/27/2012 in Eddy County, NM. Receipt notification via email is greatly appreciated. Please contact me if you have any questions.

Kathy Purvis

BBC International, Inc.

1324 W. Marland

Hobbs, NM 88240

Phone: (575) 397-6388

Fax: (575) 397-0397

Email: kathy@bbcinternational.com

Bratcher, Mike, EMNRD

From: Christopher_Jones@oxy.com
Sent: Thursday, December 27, 2012 1:53 PM
To: jamos@blm.gov; Bratcher, Mike, EMNRD; tgregsto@blm.gov;
kswinney@bbcinternational.com; cbrunson@bbcinternational.com;
kathy@bbcinternational.com
Cc: Mark_Richards@oxy.com; Tiffney_Burkham@oxy.com
Subject: Righthand canyon 35-7 SWD

This is to inform you that Oxy Permian Primary had a spill of produced water at the Righthand canyon 35-7 SWD on December 27, 2012. Oxy released 175 bbls of produced water, 0 bbls was recovered. Leak was due to failure in the 2" valve on the discharge line. Oxy will have BBC do some initial remediation, a C-141 to follow. BBC will delineate at a later date.

REGULATORY LEASE # NM 53218 API30-015-34259<tel:30-015-34259> SECT 35 T21S R24E EDDY COUNTY NEW MEXICO
WEATHER COLD OVERCAST HWY 285 NORTH FROM CARLSBAD GO 15 MILES, TURN WEST ON CR137 GO 10 MILES, TURN
SOUTH ONTO MAIN DIRT RD GO UP HILL 3 MILES, FACILITY ON RIGHT.

Chris Jones
HES Specialist
Permian Primary Production
Carlsbad, NM
Cell 575-499-3337
Off 575-628-4121

"We do not inherit the earth from our ancestors; we borrow it from our children." Chief Seattle

Bratcher, Mike, EMNRD

From: Amos, James <jamos@blm.gov>
Sent: Thursday, December 27, 2012 4:17 PM
To: Christopher_Jones@oxy.com
Cc: Bratcher, Mike, EMNRD; tgregsto@blm.gov; kswinney@bbcinternational.com; cbrunson@bbcinternational.com; kathy@bbcinternational.com; Mark_Richards@oxy.com; Tiffney_Burkham@oxy.com
Subject: Re: Righthand canyon 35-7 SWD

We have received your notice. thanks

On Thu, Dec 27, 2012 at 1:52 PM, <Christopher_Jones@oxy.com> wrote:

This is to inform you that Oxy Permian Primary had a spill of produced water at the Righthand canyon 35-7 SWD on December 27, 2012. Oxy released 175 bbls of produced water, 0 bbls was recovered. Leak was due to failure in the 2" valve on the discharge line. Oxy will have BBC do some initial remediation, a C-141 to follow. BBC will delineate at a later date.

REGULATORY LEASE # NM 53218 API30-015-34259<<tel:30-015-34259>>

SECT 35 T21S R24E

EDDY COUNTY NEW MEXICO

WEATHER COLD OVERCAST HWY 285 NORTH FROM CARLSBAD GO 15 MILES, TURN WEST ON CR137 GO 10 MILES, TURN SOUTH ONTO MAIN DIRT RD GO UP HILL 3 MILES, FACILITY ON RIGHT.

Chris Jones
HES Specialist
Permian Primary Production
Carlsbad, NM
Cell 575-499-3337
Off 575-628-4121

"We do not inherit the earth from our ancestors; we borrow it from our children." Chief Seattle