<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II Bill S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

Date: 04-26-13

* Attach Additional Sheets If Necessary

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. RECEIVED

Form C-141 Revised August 8, 2011

JUN 2 7 2013
Submit 1 Copy to appropriate District Office in NMOCD ARTESIA

Revised August 8, 2011

Sant	ta Fe, NM 875	05					
Release Notifica	tion and Co	rrective A	ction				
nJMW 1319233299	OPERA			x Initial Report			
Name of Company Southern Bay Operating, LLC 25652			X IIII	ar report	т ны тере	J1 C	
Address 5100 East Skelly Drive, Suite 650 Tulsa, OK 74135		lo. 940-704-26	508				
Facility Name Grayburg Jackson Premier San Andres Unit F Central Battery	K Facility Typ	e: Oil Productio	on Battery				
Surface Owner: BLM Mineral Ow	ner: BLM	;	API N	o. Various			
	TION OF REI	LEASE	use:30-01	5-3116	3		
Unit Letter Section Township Range Feet from the K 27 17 S 30 E	North/South Line	Feet from the	East/West Line	County Eddy			
Latitude	Longitud	e					
NATU	RE OF RELI	EASE					
Type of Release Spill	Volume of		Volume	Volume Recovered			
	120 BBL		65 bbl.				
Source of Release 3" water leg on the production separator Was Immediate Notice Given?		Date 06-24-13 Hour 4:30 am Date 06-24-13 Hour 10:30 am Dif YES, To Whom?			10:30 am Discovery		
x Yes \(\sum \) Not Requir		Mike Bratcher					
By Whom? Danny Harrell	Date and F	Date and Hour 06-24-13 Time: 17:37 AM					
Was a Watercourse Reached? Yes x No	If YES, Vo	If YES, Volume Impacting the Watercourse.					
If a Watercourse was Impacted, Describe Fully.* N/A		<u>!</u>					
Describe Cause of Problem and Remedial Action Taken.* 3" water leg from the production separator to the produced water tar secondary containment. The lease operator shut in the facility and a			20 bbls of produced	d water inside	e the battery		
Describe Area Affected and Cleanup Action Taken.* The spill of 120 bbls of produced water was contained inside the bat recovered using a vacuum truck (approx. 65 bbls). Secondary contai vertical/horizontal delineation will conducted to determine the extension of the secondary contains the secondary	inment was flushed	with fresh water	and recovered wit			1	
I hereby certify that the information given above is true and complet regulations all operators are required to report and/or file certain relepublic health or the environment. The acceptance of a C-141 report should their operations have failed to adequately investigate and renor the environment. In addition, NMOCD acceptance of a C-141 refederal, state, or local laws and/or regulations.	ease notifications a by the NMOCD m nediate contaminati	nd perform correct arked as "Final R on that pose a the	ctive actions for re Report" does not re reat to ground wate	leases which lieve the ope er, surface wa	may endanger rator of liability ater, human health		
:		OIL CONSERVATION DIVISION					
Signature: Danny W. Harrell	Approved by	Environmental 9	Spanialist:		/		
Printed Name: Danny W. Harrell	Approved by	Approved by Environmental Specialist: Signed By Mile Brancher					
Title: EH&S Manager	Approval Da	JL 1 1 201; te:	Expiration	n Date:			
E-mail Address: dharrell@halconresources.com	Conditions o			Attached			

like approval by BLM. SUBMIT REMEDIATION

PROPOSAL NO LATER THAN:

Phone:225-571-1170



United States Department of the Interior Bureau of Land Management



Report of Undesirable Event

. Operator: Southern Bay Operating, I	LLC	Field Name: Graybu	ırg Jackson Pre	emier San Andres Unit			
. IID NO (Unit/PA, Lease, CA, R/W):	LC-0467934			RECEIVED			
Date and Time of Occurrence: 24 Jun	ne 2013 Time: 10:30) AM					
Date and Time Reported to BLM: 24	June 2013 Time: 15	8:20		JUN 27 2013			
Reported By: Danny Harrell		Phone Number: 225-571-1170		NMOCD ARTESIA			
Person in Charge: Mark Newton		Phone Number 940-704-2608		THINGO WILLGIA			
. Location: County Eddy S	State NM		East Sec. 27	Qtr SE Qtr SE			
	1: 6: > 7: 1	South	····	TY'II ND (
Surface Ownership (Federal, Fee, InWell or Facility ID: Grayburg Jackson				O Hills, NM			
0. Type of Event (see instructions): Spi		ies Olli K Celital B	attery				
1. Cause of, and Extent of Event: 3" w		ator to produced water	er tank failed d	ue to corrosion spilling produced			
vater inside secondary containment.	2 1	1		. 1 51			
			i				
2. Volume Discharged or Consumed:	Oil.	Water 120 bbl.	Gas	Other			
Volume Recovered:	Oil	Water 65 bbl.	Gas	Other			
Volume Lost:	Oil	Water	Gas	Other			
3. Time Required to Control Event: 1.	/2 Hr						
4. Action Taken to Control Event:							
The facility and associated wells we	ere shut in.		f				
<u> </u>							
6. Clean up Procedures and Dates: Free produced water inside the batte containment was flushed with fresh	water and recovered	d with a vacuum truc	k.;Sampling ar				
will conducted to determine the ext	ent of the residual C	and TPH contamin	ation.				
7. Action Taken to Prevent Recurrence	e/Initiate or Update	Contingency Plannin	ng _				
The failed 3" water leg off the sepa	rator was replaced w	vith a new 3" poly lir	ne which is cor	rosion resistant.			
8. General Remarks:							
8. General Remarks.							
9. Other Federal, State, and Local Age	encies Notified: New	Mexico Oil Conserv	vation Division	- Mike Bratcher @ 17:37 on 6-			
24-13	neies notified. New	Wiekied Off Conserv	vation Division	- WINC Dratcher @ 17.37 on 0-			
0. Signature: Danny W. Harrell		Date: 27 June 2013					
		<u> </u>					
LM USE ONLY	•••••	• • • • • • • • •		••••••			
A. Field Office:		B. Date Reported to	MSO:				
C. Event Classification (I, II, or III):							
D. Site Inspected By:		Date:	·				
E. FY (PRIORITY YEAR):		INSPECTION NO					
E INSPECTION TYPE: NII		G ACTIVITY CO	ODE (SV or E/	1).			

OFFICE HRS:

INSPECTION HRS:

H. NO. TRIPS:

Instructions ! Report of Undesirable Event

- 1. Name of operator and oil field name.
- 2. Identification number for the lease, unit, participating area, communitization agreement, or right of way.
- 3. Date and time the undesirable event occurred.
- 4. Date and time the undesirable event was reported to BLM.
- 5. Reported by whom. Individual's name and telephone number.
- 6. Who will be in charge of the cleanup and their telephone number.
- 7. Exact location at which the undesirable event occurred.
- 8. Surface ownership; federal, state, fee, Indian, (describe) and other notable features like nearby town, communities or landmarks.
- 9. Associated well number, tank battery identification, pipeline nomenclature or other identification description.
- 10. Type of event; oil spill, oil and saltwater spill, oil and toxic fluid spill, toxic fluid spill, saltwater spill, saltwater and toxic fluid spill, gas venting, blowout, fire, fatality, injury, property damage or other (specify).
- 11. Describe cause and extent of event so a determination can be made as to avoidable or unavoidable loss.
- 12. List the amount discharged as a result of the event and list the amount recovered from the event. Also list the amount which was actually lost.
- 13. Time required to control the event in hours from the time of occurrence to when the event was stopped.
- 14. Describe the procedures and actions that were taken to control the event (include and attach photographs).
- 15. Describe the damage that that event caused, estimate the acreage of surface disturbance or length (feet, yard, miles) of area affected; document any affected cultural resources, loss of any wildlife or livestock, and the cause and extent of any personal injury; identify if any sensitive areas or surface waters are or could be affected (include stream names).
- 16. Describe the cleanup procedures that were used along with dates and plans for reclaiming or remediating the disturbed areas.
- 17. Describe the actions taken or plans to prevent future events or if contingency plans will be developed or modified.
- 18. List any other miscellaneous remarks.
- 19. Identify other federal, state and local agencies notified such as Environmental Protection Agency, Montana Department of Environmental Quality, North Dakota Industrial Commission, South Dakota Department of Environment and Natural Resources, land owners (list names and phone numbers).
- 20. Signature and date of person receiving or submitting the report.
 - A. BLM Field Office where the undesirable event occurred.
 - B. Actual date reported to the Montana State Office: Send a copy of the event report to MSO via e-mail or (406-896-5292- Fax).
 - C. Determine and document the proper event classification.

Class I: >100 Barrels of fluids, >500 Mcf, into environmentally sensitive areas, or major incidents.

Class II: >10 but<100 Barrels of fluids, >50 Mcf but <500 Mcf

Class III: <10 Barrels of fluids, < 50 Mcf

- D. List the inspection date and the BLM on site inspector.
- E. Current Fiscal Year and Inspection Number by I&E.
- F. Inspection type: NU = Undesirable event.
- G. Activity Code: SV = Spills or venting of gas.

FA = Fires or personnel accidents.

H. Number of onsite trips, inspection hours on site, travel hours to and from the site and number of office hours.

Drew Hall <DHall@halconresources.com> From:

Thursday, June 27, 2013 10:45 AM Sent: Amos, James; Bratcher, Mike, EMNRD To:

Eileen Shannon; Steve Milinichik; Gordon Ware (GWare@kleinfelder.com); Bill Walker; Cc:

Danny Harrell; Mark Newton; Tim McDonald

Grayburg Jackson Premier San Andres Unit K Central Battery - 120 bbl Produced Water Subject:

Spill on 6/24/13

BLM Report of Undesirable Event ntl-3aform.doc; C-141 New Mexico State form for spill Attachments:

notification.doc

Jim and Mike,

Please find attached the respective notification forms for your agencies for the 120 bbl produced water spill that occurred at the Grayburg Jackson Premier San Andres Unit K Central Battery on June 24th, 2013.

We will send you hard copies in the mail.

Gordon and Eileen.

Please make arrangements to visit this site and conduct soil sampling to determine lateral and vertical (take a hand auger) extent of the Cliand any TPH/BTEX that was entrained in the produced water. I also would like you to collect at least two background samples outside of the spill impacted area. Please contact Mark Newton (cc'd) to make arrangements for the site visit. Next week would be good, if possible.

Please let me know if you have questions or need clarification.

Regards,

Drew Hall **Environmental Compliance Manager** Halcon Resources Email: dhall@halconresources.com

Mobile: 720-648-5613;

From: Bratcher, Mike, EMNRD

Sent: Thursday, June 27, 2013 1:33 PM

To: Danny Harrell

Cc: Warren, JeanMarie, EMNRD

Subject: RE: Grayburg Jackson Premier San Andres Unit K Central Battery - 120 bbl Produced

Water Spill on 6/24/13

Danny,

I received the documents sent, including NMOCD Form C-141. Where the form asks for an API number, "Various" is listed. I realize this is likely a centralized tank battery that receives product from numerous wells. If we have a specific API number, it makes our data entry much simpler and also will allow you to access the approved form, which will have a date by which a remediation proposal is due. It will also include a "RP" number (such as 2RP-1234). With that number, you will be able to access all documents pertaining to that particular incident through OCD Online. After reviewing our database, I believe this battery is either at, or very near Southern Bay's Grayburg Jackson PSU #17 (API: 30-015-31163). Unless you object, or want to use a different API number, this is the one we will use to track this release event. There can be instances where it is not practicable to use an API number, such as a flowline or pipeline release that may not be near any of your wells. In those instances, our data entry process is a little different, but it will still be assigned the RP number. You will likely have to contact us to get that number if you wish to track the event, or obtain copies of related documents. I am just copying you and my co-worker on this correspondence, but feel free to distribute as you see necessary. Either myself or Ms. Warren can assist you if you have any questions. Her extension number is 101.

Thanks,

Mike Bratcher NMOCD District 2 811 S. First Street Artesia, NM 88210 O: 575-748-1283 X108

C: 575-626-0857 F: 575-748-9720

From: Drew Hall [mailto:DHall@halconresources.com]

Sent: Thursday, June 27, 2013 10:45 AM **To:** Amos, James; Bratcher, Mike, EMNRD

Cc: Eileen Shannon; Steve Milinichik; Gordon Ware (GWare@kleinfelder.com); Bill Walker; Danny Harrell; Mark Newton;

Tim McDonald

Subject: Grayburg Jackson Premier San Andres Unit K Central Battery - 120 bbl Produced Water Spill on 6/24/13

Jim and Mike,

Please find attached the respective notification forms for your agencies for the 120 bbl produced water spill that occurred at the Grayburg Jackson Premier San Andres Unit K Central Battery on June 24th, 2013.

We will send you hard copies in the mail.

Gordon and Eileen,

Please make arrangements to visit this site and conduct soil sampling to determine lateral and vertical (take a hand auger) extent of the Chand any TPH/BTEX that was entrained in the produced water. I also would like you to collect at least two background samples outside of the spill impacted area. Please contact Mark Newton (cc'd) to make arrangements for the site visit. Next week would be good, if possible.

Please let me know if you have questions or need clarification.

Regards,

Drew Hall
Environmental Compliance Manager
Halcon Resources
Email: dhall@halconresources.com

Mobile: 720-648-5613



From: Eileen Shannon <EShannon@kleinfelder.com>

Sent: Thursday, June 27, 2013 11:10 AM

To: Drew Hall; Amos, James; Bratcher, Mike, EMNRD

Cc: Steve Milinichik; Gordon Ware; Bill Walker; Danny Harrell; Mark Newton; Tim McDonald

Subject: RE: Grayburg Jackson Premier San Andres Unit K Central Battery - 120 bbl Produced

Water Spill on 6/24/13

Thanks Drew, I am in the field today and will look at this tonight

Sent from my Windows Phone

From: Drew Hall

Sent: 6/27/2013 10:45 AM

To: Amos, James; Bratcher, Mike, EMNRD

Cc: <u>Eileen Shannon</u>; <u>Steve Milinichik</u>; <u>Gordon Ware</u>; <u>Bill Walker</u>; <u>Danny Harrell</u>; <u>Mark Newton</u>; <u>Tim McDonald</u> **Subject**: Grayburg Jackson Premier San Andres Unit K Central Battery - 120 bbl Produced Water Spill on 6/24/13

Jim and Mike,

Please find attached the respective notification forms for your agencies for the 120 bbl produced water spill that occurred at the Grayburg Jackson Premier San Andres Unit K Central Battery on June 24th, 2013.

We will send you hard copies in the mail.

Gordon and Eileen,

Please make arrangements to visit this site and conduct soil sampling to determine lateral and vertical (take a hand auger) extent of the Cland any TPH/BTEX that was entrained in the produced water. I also would like you to collect at least two background samples outside of the spill impacted area. Please contact Mark Newton (cc'd) to make arrangements for the site visit. Next week would be good, if possible.

Please let me know if you have questions or need clarification.

Regards,

Drew Hall
Environmental Compliance Manager
Halcon Resources

Email: dhall@halconre'sources.com

Mobile: 720-648-5613-

HALCÓN

From: Gordon Ware <GWare@kleinfelder.com>

Sent: Thursday, June 27, 2013 12:50 PM

To: Drew Hall; Amos, James; Bratcher, Mike, EMNRD

Cc: Eileen Shannon; Steve Milinichik; Bill Walker; Danny Harrell; Mark Newton; Tim

McDonald

Subject: RE: Grayburg Jackson Premier San Andres Unit K Central Battery - 120 bbl Produced

Water Spill on 6/24/13

Drew,

Thanks we will read trough and get this completed.

I will work with Eileen on scheduling for next week if at all possible.

Regards,

-GW

From: Drew Hall [mailto:DHall@halconresources.com]

Sent: Thursday, June 27, 2013 11:45 AM **To:** Amos, James; Bratcher, Mike, EMNRD

Cc: Eileen Shannon; Steve Milinichik; Gordon Ware; Bill Walker; Danny Harrell; Mark Newton; Tim McDonald **Subject:** Grayburg Jackson Premier San Andres Unit K Central Battery - 120 bbl Produced Water Spill on 6/24/13

Jim and Mike,

Please find attached the respective notification forms for your agencies for the 120 bbl produced water spill that occurred at the Grayburg Jackson Premier San Andres Unit K Central Battery on June 24th, 2013.

We will send you hard copies in the mail.

Gordon and Eileen,

Please make arrangements to visit this site and conduct soil sampling to determine lateral and vertical (take a hand auger) extent of the Cl and any TPH/BTEX that was entrained in the produced water. I also would like you to collect at least two background samples outside of the spill impacted area. Please contact Mark Newton (cc'd) to make arrangements for the site visit. Next week would be good, if possible.

Please let me know if you have questions or need clarification.

Regards,

Drew Hall
Environmental Compliance Manager

Halcon Resources

Email: dhall@halconresources.com

Mobile: 720-648-5613



Warren, JeanMarie, EMNRD

From:

Bratcher, Mike, EMNRD

Sent:

Wednesday, July 03, 2013 6:55 AM

To:

Warren, JeanMarie, EMNRD

Subject:

FW: Grayburg Jackson Premier San Andres Unit K Central Battery - 120 bbl Produced

Water Spill on 6/24/13

As a matter of fact I did hear something back! - MLB

From: Danny Harrell [mailto:DHarrell@halconresources.com]

Sent: Thursday, June 27, 2013 4:42 PM **To:** Bratcher, Mike, EMNRD; Drew Hall

Subject: RE: Grayburg Jackson Premier San Andres Unit K Central Battery - 120 bbl Produced Water Spill on 6/24/13

Yes Sir that is fine with me. The Gray burg Jackson PSU #17 is one of the wells that flows to this battery. I will make sure to include this API in the report I mail to you.

From: Bratcher, Mike, EMNRD [mailto:mike.bratcher@state.nm.us]

Sent: Thursday, June: 27, 2013 2:33 PM

To: Danny Harrell

Cc: Warren, JeanMarie, EMNRD

Subject: RE: Grayburg Jackson Premier San Andres Unit K Central Battery - 120 bbl Produced Water Spill on 6/24/13

Danny,

I received the documents sent, including NMOCD Form C-141. Where the form asks for an API number, "Various" is listed. I realize this is likely a centralized tank battery that receives product from numerous wells. If we have a specific API number, it makes our data entry much simpler and also will allow you to access the approved form, which will have a date by which a remediation proposal is due. It will also include a "RP" number (such as 2RP-1234). With that number, you will be able to access all documents pertaining to that particular incident through OCD Online. After reviewing our database, I believe this battery is either at, or very near Southern Bay's Grayburg Jackson PSU #17 (API: 30-015-31163). Unless you object, or want to use a different API number, this is the one we will use to track this release event. There can be instances where it is not practicable to use an API number, such as a flowline or pipeline release that may not be near any of your wells. In those instances, our data entry process is a little different, but it will still be assigned the RP number. You will likely have to contact us to get that number if you wish to track the event, or obtain copies of related documents. I am just copying you and my co-worker on this correspondence, but feel free to distribute as you see necessary. Either myself or Ms. Warren can assist you if you have any questions. Her extension number is 101.

Thanks,

Mike Bratcher NMOCD District 2 811 S. First Street Artesia, NM 88210 O: 575-748-1283 X108

C: 575-626-0857 F: 575-748-9720 From: Drew Hall [mailto:DHall@halconresources.com]

Sent: Thursday, June 27, 2013 10:45 AM **To:** Amos, James; Bratcher, Mike, EMNRD

Cc: Eileen Shannon; Steve Milinichik; Gordon Ware (GWare@kleinfelder.com); Bill Walker; Danny Harrell; Mark Newton;

Tim McDonald

Subject: Grayburg Jackson Premier San Andres Unit K Central Battery - 120 bbl Produced Water Spill on 6/24/13

Jim and Mike,

Please find attached the respective notification forms for your agencies for the 120 bbl produced water spill that occurred at the Grayburg Jackson Premier San Andres Unit K Central Battery on June 24th, 2013.

We will send you hard copies in the mail.

Gordon and Eileen,

Please make arrangements to visit this site and conduct soil sampling to determine lateral and vertical (take a hand auger) extent of the Cl and any TPH/BTEX that was entrained in the produced water. I also would like you to collect at least two background samples outside of the spill impacted area. Please contact Mark Newton (cc'd) to make arrangements for the site visit. Next week would be good, if possible.

Please let me know if you have questions or need clarification.

Regards,

Drew Hall
Environmental Compliance Manager
Halcon Resources
Email: dhall@halconresources.com

Mobile: 720-648-5613

HALCÓN RESOURCES