District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr. Santa Fe. NM 87505

State of New Mexico Energy Minerals and Natural Resources

JUL 29 2013

RECEIVED

Form C-141 Revised August 8, 2011

NMOCIDI Copy to appropriate District Office in Alaccordance with 19.15.29 NMΛC.

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505

		-	, 		S	anta Fe	e, NM <u>875</u>	05					
			Rele	ease	Notifi	cation	and Co	rrective A	ction			5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	
MLn	WIB	21135	5743	5			OPERA	ΓOR	[✓ Initia	l Report	☐ Final R	leport
Name of Co		Chevron U			32	3	Contact David A. Pagano						
Address 1	5 Smith	Rd., Midlaı	nd, TX,	7970	5	,	Telephone No. wk: 575-396-4414X275 cell: 505-787-9816						
Facility Nan	ne TexM	ack BTY					Facility Type Oil Production Batteries						
Surface Owner Federal Mineral Owner							Federal			API No. 30-015-29720) Closest Well Texmack 11-1)			
				La			_	e: -103.843080					
Unit Letter	Section	Township	Range	Fee	t from the		N OF RELEASE /South Line Feet from the East/W			/est Line County			
C	11	178	31E	1 00	990	North	South Line	1650	West	est isine	County	Eddy	
				-		-							
NATURE OF RELEASE													
Type of Relea	ase Flare						Volume of Release 219MSCF/day			Volume Recovered 0 MSCF			
Source of Release Flare							Date and Hour of Occurrence 07/28/13 06:00PM Date and Hour of Discovery 07/28/13 06:00PM				scovery		
Was Immedia	ate Notice (Given? ⊠] No	☐ Not R	equired	If YES, To Whom? Bratcher, Mike, EMNRD							
By Whom?						•	Date and Hour 07/29/13 4:30 PM						
Was a Water	course Read	ched?				If YES, Volume Impacting the Watercourse.							
Yes No							,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,						
If a Watercou	rco was Im	nacted Decer	ibe Eully	* N/A				<u></u>					
											******		-
Describe Cause of Problem and Remedial Action Taken.* Frontier shut in sales line to complete maintenance/expansion at Maljamar Gas Plant. Expect to be down for 7-10 days.													
Describe Area Affected and Cleanup Action Taken.*													
Chevron will stay in close contact with frontier in order to stop flaring as soon as they were able to accept our gas in the sales line.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
G: 4	Da	-il Pas	ama					OIL CON	SERV.	ATION	DIVISIO	<u>)N</u>	
Signature: David A. Pagano							Approved by Environmental Specialist: Signed By Mile Description						
Title: Health & Environmental Specialist								UL 30 201	3				
								itions of Approval: Attached					

* Attach Additional Sheets If Necessary

Phone: 505-787-9816

Date: 07/29/12

Remediation per OCD Rule & Guidelines, & like approval by BLM. <u>SUBMIT REMEDIATION</u>

2RP-1775

PROPOSAL NO LATER THAN:

Bratcher, Mike, EMNRD

From: Pagano, David (David.Pagano) <David.Pagano@chevron.com>

Sent: Monday, July 29, 2013 5:09 PM

To: Pagano, David (David.Pagano); Bratcher, Mike, EMNRD

Cc: Moschetti, Nick (NMOS); DeLeon, Josepha; Nevarez, Joseph D

Subject: Initial C-141 & C-129 reports for the flaring at our Skelly 907, Skelly 940 & TexMack

Batteries due to Frontier shutting in our sales line

Attachments: 20130728 C-141 Skelly 907 Bty Flare IS.pdf; 20130728 C-141 TexMack Bty Flare IS.pdf;

20130728 C-141_SKU 940 Bty Flare IS.pdf; C-129 - Skelly 907 BatteryS.pdf; C-129 -

Skelly 940 Battery S.pdf; C-129 - TexMack Battery S.pdf

Mike,

Here are the Initial C-141 & C-129 reports for the flaring at our Skelly 907, Skelly 940 & TexMack Batteries due to Frontier shutting in our sales line. Flaring started at 6:00PM on 7/28/13. They expect to be down from 7-10 days. Once the sales line is back up and we are no longer flaring I will send the final reports. You will find the wells associated with each battery at the bottom of the email. Please let me know if you have any questions or need additional information.

Regards,

David A. Pagano

MCA Health & Environmental Specialist (Central Permian – Vacuum/Buckeye, Dollarhide & Sundown) 56 Texas Camp Rd., Lovington, NM 88260

Phone: 575-396-4414 x275

2 Cell: 505-787-9816 **2** Fax: 575-396-6913 **dpgn@chevron.com**

"CONFIDENTIALITY NOTICE: This message is confidential and may be privileged. If you believe that this email has been sent to you in error, please reply to the sender that you received the message; then please delete this

Well	Battery
SU 689	SKELLY UNIT
SU 699	SKELLY UNIT
SU 700	SKELLY UNIT
SU 703	SKELLY UNIT
SU 707	SKELLY UNIT
SU 711	SKELLY UNIT
SU 713	SKELLY UNIT
SU 714	SKELLY UNIT
SU 718	SKELLY UNIT
SU 719	SKELLY UNIT
SU 722	SKELLY UNIT
SU 724	SKELLY UNIT
SU 725	SKELLY UNIT
SU 828	SKELLY UNIT
SU 907	SKELLY UNIT
SU 908	SKELLY UNIT

SU 912	SKELLY UNIT
SU 914	SKELLY UNIT
SU 930	SKELLY UNIT
SU 931	SKELLY UNIT
SU 933	SKELLY UNIT
SU 936	SKELLY UNIT
SU 937	SKELLY UNIT