Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Santa Fe, NM 87505 Santa Fe, NM 87505													
Release Notification and Corrective Action													
atul	132	34494				X Initial Report 🛛 Final Report							
Name of Company: BOPCO, L.P. 260737						1. OPERATOR Contact: Jody Walters							
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88260						Telephone: No.575-887-7329							
Facility Name: PLU Big Sinks 14-25-30 USA Battery						Facility: Type Exploration and Production							
Surface Owner: Federal Mineral Owner						:: Federal API No. 30-015-39508							
Surface Ow	ner. react	<u> </u>		I					7.111.10	. 50-015 5	/////		
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County													
Unit Letter N	Section 14	Township 25S	Range 30E	Feet from the	North	n/South Line	Feet from the	East/W	est Line	County Eddy			
Latitude <u>N32.124358</u> Longitude <u>W130.853639</u>													
NATURE OF RELEASE													
Type of Release: Produced water										Volume Recovered: 38bbls water			
Source of Release: Open valve on tank									Date and Hour of Discovery: 8/1/2013,4:20 pm				
Was Immediate Notice Given?						If YES, To Whom? OCD Artesia Office							
X Yes No Not Required													
By Whom? Jody Walters						Date and Hour: 8/1/2013, 6:30pm							
Was a Watercourse Reached?						If YES, Volume Impacting the Waterdourse RECEIVED							
If a Watercourse was Impacted, Describe Fully.*									A	UG 16 2	013		
									NWC	CD AR	1551		
Describe Cause of Problem and Remedial Action Taken.*The ZH Services Inc. vacuum truck operator was pulling a load of produced water from the water tanks. He had pulled water level down below load line and disconnected the hose leaving location. He forgotten to close the valve on the tank about 1.5 hours later another truck arrived on location to haul another load of produced water. This driver closed the leaking valve and recovered the free standing fluid.													
Describe Area Affected and Cleanup Action Taken.* Approximately 7400 sq.ft. of the tank battery pad was affected by the release. The free standing fluid was recovered. The spill area will be remediated in accordance to the NMOCD and BLM guidelines.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
Signaturez on Sauce Printed Name: Tony Savoie						<u>OIL CONSERVA</u>				TION DIVISION			
						Approved by Environmental Specialistined By Mily Bernue							
		nt and Remedi	ation Spe	cialist		AU Approval Dat		E	Expiration	Date:			
E-mail Addre	ese tacavoia	e@basspet.cor	n			Conditions of	Approval						
		agoussper.col			 Re		er OCD Rule & G	Guideline	es, &	Attached			
Date: 5/5/2013 Phone:432-556-8730 like approval by BLM. SUBMIT REMEDIATION													
Auach Addi	lional Shee	ets II INECESS	ary			Septa	sal no later t ember 2	$\frac{\text{HAN:}}{2,2}$	2013	2R	Y-	-1855	