District J 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 RECEIVED

SEP 1 0 2013 Revised October 10, 2003

NMOCD Arthric Corpies to appropriate with Rule 116 on back side of form

Release Notification and Corrective Action

······································	6238				OPERAT	OR			····	al Report		Final Repor
Name of Company			LLC 229		Contact				McNeill			
	Vest Illinois Av				Telephone N				0-0077			
Facility Name	Patton 5	Fee #002	2H ·		acility Typ	<u> </u>		l'ank E	Battery			
Surface Owner Pri	Lease No. (API#) 30-01						30-015	-39815				
			LOCA	ATION	OF REI	LEASE	3		4			
Unit Letter Section D 5							m the	East/	West Line	County	Eddy	
			Latitude 32.6	9433	Longit	ude 104	.41197					
			NAT	TURE	OF RELI							
Type of Release Oil	Volume of Release 30bbls				Volume	Volume Recovered 20bbls						
Source of Release He	Date and H 09-07-2013					Date and Hour of Discovery 09-07-2013 07:00am						
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required					If YES, To Whom?							
By Whom? Michelle Mullins					Date and H							
Was a Watercourse R		If YES, Volume Impacting the Watercourse.										
If a Watercourse was	mpacted, Describ	be Fully.*										
Describe Cause of Pro	blem and Remed	ial Action	Tøken.*								•	
Fire tube gasket failed	due to high LP p	oressure. R	eplace gasket o	ı fire tub	e.							
Describe Area Affecte	d and Cleanup A	ction Take	en.*		·			······································				
Initially 30bbls of oil recovered. Contamina condition.												
I hereby certify that the regulations all operate public health or the er should their operation or the environment. I federal, state, or local	rs are required to vironment. The a s have failed to a n addition, NMO	report and acceptance dequately CD accept	d/or file certain are of a C-141 rep investigate and ance of a C-141	release no ort by the remediate	otifications as NMOCD m contaminati	id perford orked as ' on that po	m correc 'Final R ose a thr	ctive ac eport" eat to g	tions for re does not re ground wate	leases which lieve the ope er, surface w	may er rator of ater, hu	danger Tiability man health
		OIL CONSERVATION DIVISION										
Signature:					Approved by District Supergistied By Mily Branches							
Printed Name:	Robert	Grubbs J				4 4			ьу <i>_у-(/)</i>	T POINT	TUN (.19	\
Title:	Senior Environ	imental Co	ordinator		Approval SE	<u>ę 19</u>	2013		Expiration	Date:		
E-mail Address:	rgrubbs@	concho.co	om .		Conditions of	Approve	al:			Attached		
Date: 09-10-2013		Phone:	432-661-660	<u>) </u>						<u> </u>		
Attach Additional S	neets If Necessa	ігу							,	2R	P-	- 1912

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>

Sent: Tuesday, September 10, 2013 3:07 PM

To: Bratcher, Mike, EMNRD

Cc: Robert McNeill

Subject: C-141's Initial - Final Reports - Sidewinder #001H, F.U.N. State Com #001H, Down South

State Com #001H and the Patton 5 Fee #002H

Attachments: Sidewinder #001H (Tank Battery) -- Date of Release --09-03-2013.pdf; F.U.N. State

Com #001H (Tank Battery) -- Date of Release -- 09-05-2013.pdf; Down South State Com #001H (Tank Battery) -- Date of Release -- 09-10-2013.pdf; Patton 5 Fee #002H (

Tank Battery) -- Date of Release -- 09-10-2013.pdf



Mr. Bratcher,

Please see attached the C-141 Initial Reports for the following releases that occurred at our Sidewinder #001H, F.U.N. State Com #001H, Down South State Com #001H and the Patton 5 Fee #002H in Eddy County New Mexico. These are lined facilities.

Thank you,

Robert Grubbs Ir. Sr. Environmental Coordinator 432.683.7443 (main)

432.818.2369 (direct)

432.661.6601 (cell)

rgrubbs@concho.com

Mailing Address:

One Concho Center

600 W. Illinois Avenue

Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From:

Michelle Mullins < MMullins@concho.com>

Sent:

Sunday, September 08, 2013 9:52 AM

To:

Bratcher, Mike, EMNRD

Cc:

Robert Grubbs

Subject:

Patton 5 Fee #2H-Immediate Notification

Mr. Bratcher:

At approximately 7:00 a.m. on 9/7/2013, a produced fluid release was discovered at the above-referenced facility. An estimated 30 barrels of produced fluid was released. The cause of the release is currently under investigation. We will follow up within 15 days with a C-141 Report. GPS coordinates and legal description is below.

32.69433 104.41197

Patton 5 Fee #2H Unit D Sec. 5 T19S R26E 1040' FNL & 330' FWL Eddy County, NM API 30-015-39815

Thank you.

Michelle Mullins HSE Field Technician COG Operating, LLC (432) 934-1052 mmullins@concho.com

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.