

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

SEP 12 2013

Form C-141
Revised October 10, 2003

Submit a Copy to Appropriate District Office in accordance with 19.15.29 NMAC

Release Notification and Corrective Action

nJMW 1326350530

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating	Contact: Brian Wall;
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: JL Keel B # 37	Facility Type: Injection

Surface Owner: Federal	Mineral Owner:	API No.: 3001525934
------------------------	----------------	---------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	05	17S	31E	1780	North	660	West	Eddy

Latitude: 32.86578 Longitude: -103.89748

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 79 bbls	Volume Recovered: 45 bbls
Source of Release: 2" Fiberglass line	Date and Hour of Occurrence: 09/11/2013 11:00am	Date and Hour of Discovery: 09/11/2013 11:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher- NM OCD Mike Burton- BLM	
By Whom? Brian Wall	Date and Hour 09/12/2013 8:45am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: had an alarm @ 7:40 am for low discharge at keel west water station went out to facility reset pump and noticed that injection header pressure did not go up to normal operating pressure notify all pumpers to keep an eye out for any leaks out on pasture or on injection wells then relief pumper call and said he was driving through a well and saw stream of water running down the road it was hard to tell because it had just rain the night before and early in the morning he started walking out following the fluid and came up to injection well that was leaking s/i line and header ASAP then we noticed that 2" injection line had blew up about 2' below ground

Describe Area Affected and Cleanup Action Taken.* : called crew to start fixin line than had vac truck suck all standing fluid on ground and recover 45 bbls of fluid fluid ran south of well head 1300' then South West to finger about 1000' each.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 


Printed Name: Brian Wall

Title: Construction Foreman II

E-mail Address: bwall@linenergy.com

Date: 09/12/2013

Phone: 806-367-0645

Approved by District Supervisor Signed By 

SEP 20 2013

Approval Date:

Expiration Date:

Conditions of Approval:
Remediation per OCD Rule & Guidelines, &
like approval by BLM. SUBMIT REMEDIATION

Attached ☐

PROPOSAL NO LATER THAN:


October 20, 2013

* Attach Additional Sheets If Necessary

2RP-
1921

Bratcher, Mike, EMNRD

From: McCracken, Theresa <TMcCracken@linnenergy.com>
Sent: Thursday, September 12, 2013 3:29 PM
To: Bratcher, Mike, EMNRD; mburton@blm.gov
Cc: Callahan, Terry; Fitzwater, Nancy; Moreno, Laura; Butters, Thomas; Golding, Chris; Wall, Fred; smcghee@diversifiedfsi.com; aruth@diversifiedfsi.com; mpatterson@rocketmail.com
Subject: Linn- JL Keel B #37 9-11-13
Attachments: Keel B #37 9-11-13.pdf



Please find attached the initial C-141 for the above referenced location.



NASDAQ:LINE

Theresa McCracken

Field Administrator

LINN Energy, LLC

2130 W Bender

Hobbs, NM 88240

T: 575-738-1739 / F: 575-738-1740

tmccracken@linnenergy.com

This electronic message, together with any attachments, contains information from LINN Energy that may be confidential and intended solely for the use of the addressee only. If you are not the intended recipient, please note that any disclosure, dissemination, distribution or copying of this message, or any attachment, is strictly prohibited. Also, please notify the original sender by return e-mail and delete the message, along with any attachments, from your computer. Finally, the recipient should check this email and any attachments for the presence of viruses. The organization accepts no liability for any damage caused by any virus transmitted by this email.