

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 1 on back
side of form

RECEIVED OGD

Release Notification and Corrective Action

2011 AUG 18 A 12:03

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company OXY USA WTP LP 16696	Contact Thomas Bernal
Address 329 Marathon Rd, Lakewood	Telephone No. (575) 628-4112
Facility Name INDIAN BASIN GAS PLANT	Facility Type Gas Processing Plant

Surface Owner	Mineral Owner INDIAN BASIN	Lease No.
---------------	----------------------------	-----------

LOCATION OF RELEASE

Unit Letter G	Section 23	Township 21-S	Range 23-E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	------------------	---------------	---------------	------------------	---------------	----------------	----------------

Latitude 32°27'52.502" Longitude 104°34'28.004"

NATURE OF RELEASE

Type of Release Gas	Volume of Release 598.6 MCF	Volume Recovered 0
Source of Release Residue Flare	Date and Hour of Occurrence 8/3/2011 6:14:00 PM	Date and Hour of Discovery 8/3/2011 6:14:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Sandy Ballard	Date and Hour 8/04/2011 9:00AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Cause:
FLARED RESIDUE GAS STREAM 35 MINUTES ON HIGH OXYGEN CONTENT.
Remedial Action Taken:
Operations sampled inlet gathering line for excessive O₂. Due to the short duration of the flare event the source of O₂ could not be determined.

Describe Area Affected and Cleanup Action Taken.*
NA

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Sandy Ballard</u>		OIL CONSERVATION DIVISION	
Printed Name: Sandy J Ballard		Approved by District Supervisor:	Accepted for record NMOCD
Title: <u>HES SPECIALIST</u>		Approval Date: <u>SEP 27 2013</u>	Expiration Date:
E-mail Address: sandy_ballard@oxy.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: <u>8-4-2011</u> Phone: 575-513-8020			

* Attach Additional Sheets If Necessary

fJMW 1327034125 iJMW 1327055815 2RP-1949