

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

Name of Company OXY USA WTP LP 16696		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Address 329 Marathon Rd, Lakewood		Contact CAMPBELL, RODNEY		
Facility Name INDIAN BASIN GAS PLANT		Telephone No. (575) 628-4167		
		Facility Type GAS PROCESSING FACILITY		
Surface Owner		Mineral Owner INDIAN BASIN	Lease No.	

LOCATION OF RELEASE

Unit Letter G	Section 23	Township 21-S	Range 23-E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	------------------	---------------	---------------	------------------	---------------	----------------	----------------

Latitude 32°27'52.502" Longitude 104°34'28.004"

NATURE OF RELEASE

Type of Release Gas	Volume of Release 545.5 MCF	Volume Recovered 0
Source of Release Residue Flare	Date and Hour of Occurrence 9/16/2013 7:50:00 PM	Date and Hour of Discovery 9/16/2013 7:50:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? MIKE BRATCHER	
By Whom? RODNEY CAMPBELL	Date and Hour 9-17-2013 9:52 A.M. VOICEMAIL	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

RECEIVED

OCT 02 2013

Describe Cause of Problem and Remedial Action Taken.*

Cause:
INDIAN BASIN GAS PLANT FLARED 545.5 MCF OF RESIDUE SALES GAS DUE TO HIGH OXGEN CONTENT. VRU SUCTION PRESSURE TRANSMITTER FAILED, ALLOWING VRU TO REMAIN RUNNING PULLING A VACCUM.

Remedial Action Taken:
OPERATIONS NOTIFIED FIELD PRODUCTION COORDINATOR AND ONCALL PLANT PERSONNEL. BOTH EMPLOYEES CALLED OUT CHECK METERS IN FIELD, BUT DIDN'T FIND ANYTHING. WHEN THEY CAME BACK TO THE PLANT, OPERATIONS NOTIFIED THEM O2 LEVEL WAS STARTING TO CLIMB, AND HOOKED UP METER TO METER IN PLANT AND FOUND SOURCE OF OXYGEN.

Describe Area Affected and Cleanup Action Taken.*
N/A

NMOCD ARTESIA

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rodney Campbell</i>		OIL CONSERVATION DIVISION	
Printed Name: RODNEY CAMPBELL		Approved by District Supervisor: Accepted for record NMOCD	
Title: <i>HEs supervisor</i>		Approval Date: OCT 03 2013	Expiration Date:
E-mail Address: RODNEY.CAMPBELL@OXY.COM		Conditions of Approval:	
Date: <i>9-20-13</i> Phone: (575) 628-4167		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

ATMW 1327034125

ATMW 1327652893

2RP-1968