

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW 1328351949

OPERATOR		<input type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company OXY USA WTP LP <i>16696</i>		Contact Campbell, Rodney	
Address 329 Marathon Rd, Lakewood		Telephone No. (575) 628-4167	
Facility Name INDIAN BASIN GAS PLANT		Facility Type Gas Processing Plant	
Surface Owner	Mineral Owner INDIAN BASIN	Lease No.	

LOCATION OF RELEASE

Unit Letter G	Section 23	Township 21-S	Range 23-E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	------------------	---------------	---------------	------------------	---------------	----------------	----------------

Latitude 32°27'52.502" Longitude 104°34'28.004"

NATURE OF RELEASE

Type of Release Gas	Volume of Release 1145.83 MCF	Volume Recovered 0	
Source of Release Residue Flare	Date and Hour of Occurrence 4/27/2012 9:00:00 AM	Date and Hour of Discovery 4/27/2012 9:00:00 AM	
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher		
By Whom? Rodney Campbell	Date and Hour Voice Mail left 04/30/2012 at 9:33 A.M.		
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. n/a		
If a Watercourse was Impacted, Describe Fully.* n/a		<div style="border: 2px solid black; padding: 5px; text-align: center;">RECEIVED MAY 03 2012 NMOCD ARTESIA</div>	
Describe Cause of Problem and Remedial Action Taken.* Cause: IBGP experienced a cry by-pass at 9:00 A.M. on 4/27/2012. At this time we are unaware of the cause of the cryo by-pass. Remedial Action Taken: Operations and Maintenance worked expeditiously to reverse cryo by-pass.			
Describe Area Affected and Cleanup Action Taken.* n/a			
<p>I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.</p>			
Signature: <i>Rodney Campbell</i>		<div style="text-align: center;">OIL CONSERVATION DIVISION Accepted for record NMOCD</div>	
Printed Name: Rodney Campbell			
Title: <i>HES Specialist</i>		Approval Date: OCT 10 2013	Expiration Date:
E-mail Address: rodney_campbell@oxy.com		Conditions of Approval:	
Date: <i>4/30/2012</i> Phone: 575-628-4167		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

nJMW 1327034125

nJMW 1328353025

2R-P-1985