

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*ijmw 1329732720*

<b>OPERATOR</b> <input checked="" type="checkbox"/> Initial Report <input checked="" type="checkbox"/> Final Report		
Name of Company OXY USA WTP LP <i>16696</i>	Contact CAMPBELL, RODNEY	
Address 329 Marathon Rd, Lakewood	Telephone No. (575) 628-4167	
Facility Name INDIAN BASIN GAS PLANT	Facility Type GAS PROCESSING FACILITY	
Surface Owner	Mineral Owner INDIAN BASIN	Lease No.

**LOCATION OF RELEASE**

Unit Letter G	Section 23	Township 21-S	Range 23-E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	------------------	---------------	---------------	------------------	---------------	----------------	----------------

Latitude 32°27'52.502" Longitude 104°34'28.004"

**NATURE OF RELEASE**

Type of Release Gas	Volume of Release 968.9 MCF	Volume Recovered 0
Source of Release Residue Flare	Date and Hour of Occurrence 8/23/2013 6:33:00 AM	Date and Hour of Discovery 8/23/2013 6:33:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? MIKE BRATCHER	
By Whom? RODNEY CAMPBELL	Date and Hour 08/26/2013 7:20 a.m. LEFT VOICE MAIL	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*  
N/A

**RECEIVED**

AUG 29 2013

**NMOCD ARTESIA**

Describe Cause of Problem and Remedial Action Taken.\*

Cause:

INDIAN BASIN GAS PLANT FLARED RESIDUE SALES GAS FOR 131 MINUTES DUE TO HIGH OXYGEN CONTENT.

Remedial Action Taken:

OPERATIONS NOTIFIED OXY MEASUREMENT TECH AND FIELD PRODUCTION COORDINATOR. PRODUCTION COORDINATOR CALLED TO PRODUCERS TO SEE IF ANYTHING WAS PUT ONLINE. TWO PLANT EMPLOYEES TESTED INLET LINES WITH PORTABLE METER, BUT DIDN'T FIND ANYTHING. GLEN WITH KINDER - MORGAN CAME OUT TO MAKE SURE HIS EQUIPMENT WAS RUNNING CORRECTLY, WHICH IT WAS.

Describe Area Affected and Cleanup Action Taken.\*

N/A

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature: *Rodney Campbell*

Printed Name: RODNEY CAMPBELL

Title: *HES Specialist*

E-mail Address: RODNEY.CAMPBELL@OXY.COM

Date: 8-26-13

Phone: (575) 628-4167

Approved by District Supervisor:

Accepted for record  
NMOCD

Approval Date:

OCT 24 2013

Expiration Date:

Conditions of Approval:

Attached ☐

\* Attach Additional Sheets If Necessary

*ijmw 1327034125*

*ijmw 1329733942 ZRP-2025*