


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nJMW1329137307

Name of Company OXY USA WTP LP <i>16696</i>		Contact CAMPBELL, RODNEY	
Address 329 Marathon Rd, Lakewood		Telephone No. (575) 628-4167	
Facility Name INDIAN BASIN GAS PLANT		Facility Type GAS PROCESSING FACILITY	
Surface Owner		Mineral Owner INDIAN BASIN	Lease No.

LOCATION OF RELEASE

Unit Letter G	Section 23	Township 21-S	Range 23-E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	------------------	---------------	---------------	------------------	---------------	----------------	----------------

Latitude 32°27'52.502" Longitude 104°34'28.004"

NATURE OF RELEASE

Type of Release Gas	Volume of Release 621.8 MCF	Volume Recovered 0
Source of Release Residue Flare	Date and Hour of Occurrence 1/2/2013 8:38:00 AM	Date and Hour of Discovery 1/2/2013 8:38:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? MIKE BRATCHER- Voice Mail	
By Whom? RODNEY CAMPBELL	Date and Hour 01/02/2013 1:25 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

Cause:
IBGP FLARED RESIDUE GAS FOR 37 MINUTES DUE TO HIGH OXYGEN CONTENT.
Remedial Action Taken:
OPERATIONS SAMPLED INLET GATHERING LINE FOR EXCESSIVE O2. OPERATIONS NOTIFIED FIELD PRODUCTION COORDINATOR AND PLANT TECHNICIAN. DUE TO THE SHORT DURATION OF THE FLARE EVENT THE SOURCE OF O2 COULDN'T BE DETERMINED.

Describe Area Affected and Cleanup Action Taken.*
N/A

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rodney Campbell</i>		OIL CONSERVATION DIVISION	
Printed Name: RODNEY CAMPBELL		Accepted for record NMOC D	
Title: <i>HEU Spec's list</i>		Approval Date: OCT 18 2013	Expiration Date:
E-mail Address: RODNEY_CAMPBELL@OXY.COM		Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>1-3-12</i> Phone: (575) 628-4167			

* Attach Additional Sheets If Necessary

nJMW1327034125

iJMW1329141455

2RP-2007