

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

Name of Company OXY USA WTP LP 16696		OPERATOR <input checked="" type="checkbox"/> Initial Report <input checked="" type="checkbox"/> Final Report	
Address 329 Marathon Rd, Lakewood		Contact CAMPBELL, RODNEY	
Facility Name INDIAN BASIN GAS PLANT		Telephone No. (575) 628-4167	
		Facility Type GAS PROCESSING FACILITY	
Surface Owner		Mineral Owner INDIAN BASIN	Lease No.


LOCATION OF RELEASE

Unit Letter G	Section 23	Township 21-S	Range 23-E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	------------------	---------------	---------------	------------------	---------------	----------------	----------------

Latitude 32°27'52.502" Longitude 104°34'28.004"

NATURE OF RELEASE

Type of Release Gas	Volume of Release 128.1 MCF	Volume Recovered 0
Source of Release Residue Flare	Date and Hour of Occurrence 10/13/2013 8:06:00 AM	Date and Hour of Discovery 10/13/2013 8:06:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Cause: OXY INDIAN BASIN GAS PLANT FLARED RESIDUE SALES GAS FOR 12 MINUTES DUE TO HIGH OXYGEN CONTENT. Remedial Action Taken: OPERATIONS CHECKED STABILIZER DISCHARGE METER WITH PORTABLE OXYGEN ANALYZER, BUT DUE TO THE SHORT DURATION OF EVENT, SOURCE OF OXYGEN WASN'T DETERMINED. OPERATIONS ALSO CHECKED WITH OXY FIELD PRODUCERS AND THEY ADVISED THEY DIDN'T PUT ANY WELLS ONLINE.		
Describe Area Affected and Cleanup Action Taken.* N/A		



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: RODNEY CAMPBELL		Accepted for record NMOCD	
Title: HES Spec. 12		Approval Date: NOV 06 2013	Expiration Date:
E-mail Address: RODNEY_CAMPBELL@OXY.COM		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10-14-13	Phone: (575) 628-4167		

* Attach Additional Sheets If Necessary

Like approval by
BLM

2RP-2054

fJMW 132 703 4125
1JMW 1331129399