

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*nJMW1333741376*

Name of Company OXY USA WTP LP <i>116696</i>		Contact CAMPBELL, RODNEY	<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Address 329 Marathon Rd, Lakewood		Telephone No. (575) 628-4167		
Facility Name INDIAN BASIN GAS PLANT		Facility Type GAS PROCESSING FACILITY		
Surface Owner	Mineral Owner INDIAN BASIN	Lease No.		

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy

Latitude 32°27'52.502" Longitude 104°34'28.004"

**NATURE OF RELEASE**

Type of Release Gas	Volume of Release 9910 MCF	Volume Recovered 0
Source of Release Residue Flare SSM	Date and Hour of Occurrence 10/28/2013 12:33:00 PM	Date and Hour of Discovery 10/28/2013 12:33:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? MIKE BRATCHER	
By Whom? RODNEY CAMPBELL	Date and Hour 10/29/2013 1:15 PM.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A	<div style="border: 2px solid black; padding: 5px; text-align: center;"> <p><b>RECEIVED</b></p> <p>NOV 22 2013</p> <p><b>NMOCD ARTESIA</b></p> </div>	
Describe Cause of Problem and Remedial Action Taken.* Cause: OXY INDIAN BASIN GAS PLANT FLARED WHILE STARTING THE PLANT FROM A TURNAROUND Remedial Action Taken: THE PLANT WAS RUNNING VERY LOW RATES DURING START UP. ONCE PLANT PROCESSES WERE WARMED UP AND READY TO HANDLE MORE VOLUME PRODUCERS WERE NOTIFIED TO COME BACK ONLINE.		
Describe Area Affected and Cleanup Action Taken.* N/A		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rodney Campbell</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: RODNEY CAMPBELL	Approved by District Supervisor: Signed By <i>Mike Bratcher</i>	
Title: <i>HEs Specialist</i>	Approval Date: <b>DEC 03 2013</b>	Expiration Date:
E-mail Address: RODNEY_CAMPBELL@OXY.COM	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>11-21-13</i> Phone: (575) 628-4167	<b>Like approval by</b>	

\* Attach Additional Sheets If Necessary

**BLM**

*nJMW 1327034125*  
*nJMW 1333741657*

*2RP-2091*