

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

RJMW 1333833426

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company OXY USA WTP LP <i>16696</i>	Contact KYLE CAIN		
Address 329 Marathon Rd, Lakewood	Telephone No. (575) 628-4122		
Facility Name INDIAN BASIN GAS PLANT	Facility Type GAS PROCESSING FACILITY		
Surface Owner	Mineral Owner INDIAN BASIN	Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	23	21-S	23-E					Eddy

Latitude 32°27'52.502" Longitude 104°34'28.004"

NATURE OF RELEASE

Type of Release Gas	Volume of Release 215.6 MCF	Volume Recovered 0
Source of Release Residue Flare	Date and Hour of Occurrence 11/14/2013 3:25:00 PM	Date and Hour of Discovery 11/14/2013 3:25:00 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	
If a Watercourse was Impacted, Describe Fully.* N/A	<div style="border: 2px solid black; padding: 5px; display: inline-block;"> <p>RECEIVED</p> <p>NOV 22 2013</p> <p>NMOCD ARTESIA</p> </div>	

Describe Cause of Problem and Remedial Action Taken.*
Cause:
OXY INDIAN BASIN GAS PLANT FLARED RESIDUE SALES GAS FOR 8 MINUTES DUE TO HIGH OXYGEN CONTENT
Remedial Action Taken:
OPERATIONS SAMPLED ALL INLET LINES AND STABILIZER DISCHARGE METER AND CONTACTED CHRIS BALLAD IN THE FIELD BUT DUE TO THE SHORT DURATION OF THE FLARE EVENT, SOURCE OF OXYGEN COULD NOT BE DETERMINED

Describe Area Affected and Cleanup Action Taken.*
N/A

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rodney Campbell</i>	OIL CONSERVATION DIVISION	
Printed Name: RODNEY CAMPBELL	Approved by District Supervisor	Signed By <i>Mike Brannon</i>
Title: <i>HES specialist</i>	Approval Date: DEC 04 2013	Expiration Date:
E-mail Address: RODNEY_CAMPBELL@OXY.COM	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>11-21-13</i> Phone: (575) 628-4167	Like approval by	

* Attach Additional Sheets If Necessary

RJMW 1327034125
RJMW 1333833824

BLM

ZRP-2015