State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action													
nJMh 1334342099							ΓOR		🛛 Initia	al Report	F	inal Report	
Name of Company: BOPCO, L.P. 260137							Contact: Tony Savoie						
Address: 52		Telephone No. 575-887-7329											
Facility Nar	ne: PLU-E	Big Sinks 19-	24-31 U	SA #1 Battery	<u> </u>	Facility Type: Exploration and Production							
Surface Owner: Federal Mineral Owner: F							Federal API No. 30-015-40261]	
				LOCA	TION	OF REI	LEASE						
Unit LetterSectionTownshipRangeFeet from theNorth/C1924S31E140North								1	t/West Line Count Vest Eddy				
<i>i</i>		.	L	Latitude N 32	.209878	<u>8</u> Longituc	le <u>W 103.81927</u>	- -					
				NAT	URE	OF REL	EASE						
Type of Release: Crude oil and produced water							Volume of Release: 10 bbls crude Volume Recovered: 7 bbls crude oil and						
Source of Release: Produced water tank							oil and 68 bbls produced water 65 bbls produced water Date and Hour of Occurrence: Date and Hour of Discovery:						
							Date 12/4/13 time unknown 12/4/13 at 1:00 p.m.						
Was Immediate Notice Given?							If YES, To Whom? NMOCD #104 and BLM						
By Whom? Tony Savoie							Date and Hour: 12/4/13 at 3:37 p.m.						
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse						
☐ Yes ⊠ No						RECEIVED							
If a Watercourse was Impacted, Describe Fully.*									DEC	0 9 2012			
DEC 09 2013													
MOCD ARTESIA													
Describe Cause of Problem and Remedial Action Taken.*													
The well had just been put back on production, due to no casing gas pressure to operate the vessels the production was turned into the SWD tanks, the well unloaded causing the water tanks to overflow out of the hatches and enardo valve. The well was switched back into normal operations.													
	0									1			
Describe Are	a Affected	and Cleanup /	Action Tal	.en.*									
Most of the s	spill was co	ntained within	the 0 peri	n containment arc									
up all of the	t of the tank free standin	cs. The spill all g fluid and a p	so ponded	up in an area cov her was used to w	ering ab ash dow	out 2000 sq. m the most h	it outside the con eavily impacted v	tainmer egetatio	nt walls. A	vacuum truck	: was us ill be rei	mediated in	
		CD and BLM						-					
I hereby certi	ify that the	information gi	ven above	is true and comp	lete to th	ne best of my	knowledge and u	indersta	nd that pur	suant to NMC	DCD rul	es and	
regulations a	ll operators	are required t	o report ai	nd/or file certain r ce of a C-141 repo	elease no	otifications a	nd perform correct	ctive act	ions for rel	eases which	may end	langer	
				investigate and r									
				otance of a C-141	report do	pes not reliev	e the operator of	respons	ibility for c	ompliance w	ith any o	other	
icuciai, state,		ws and/or regu	nations.		OIL CONSERVATION DIVISION								
Signature 1 a 2 a													
Signature: 1 m Zaure							Approved by Environmental Specialist: Signed By Mile Brandson						
Printed Name	e: Tony Sav	voie			Signe	ëd By_//	11/4 202	METAL.	<u>992</u>				
Title: Waste Management and Remediation Specialist							Approval Date: C 0 9 2013 Expiration Date:						
E-mail Addro	ess: tasavoi		Conditions of Approval:										
							on per OCD Rule			Attached	Ц		
Date: 12/9/1 * Attach Addi		ets If Necess		Phone: 432-556-8	130	like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 7000 (1000)							
					-	Janua		612		LKI	/	10-2	
					-				•				