

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

Incident # NHMP140652 7038 OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P.	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU-441H The spill was located 2485 feet S.E. of the well location	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-41281
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter P	Section 18	Township 24S	Range 30E	Feet from the 192	North/South Line South	Feet from the 180	East/West Line East	County: Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	-----------------

Latitude N 32.21082 **Longitude** W 103.91292

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 45 bbls.	Volume Recovered: 2 bbls
Source of Release: 8" frac hose	Date and Hour of Occurrence: 1/23/14 Time unknown	Date and Hour of Discovery: 1/23/14 at 2:30 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency #104 and the BLM	
By Whom? Tony Savoie	Date and Hour: 1/23/14 at 5:33 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

FEB 03 2014

NMOCD ARTESIA

Describe Cause of Problem and Remedial Action Taken.*

An 8" hose connected to a portable pump ruptured while fracking the PLU-441H well. The hose section was replaced.

Describe Area Affected and Cleanup Action Taken.*

The spill affected approximately 1885 sq.ft. of pasture, all of the water outside of the pump containment soaked into the ground. Approximately 2 bbls of water was recovered from the containment area.

The spill will be cleaned up in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: *Tony Savoie*

Printed Name: Tony Savoie

Approved by Environmental Specialist: *[Signature]*

Title: Waste Management and Remediation Specialist

Approval Date: 3/6/14

Expiration Date:

E-mail Address: tasavoie@basspet.com

Conditions of Approval:

Attached ☐

Date: 2/3/14

Phone: Remediation per OCD Rule & Guidelines, &


* Attach Additional Sheets If Necessary

like approval by BLM. **SUBMIT REMEDIATION**

PROPOSAL NO LATER THAN:

9/6/14

*OGRID 260737
2RP 2181*



Data use subject to license.

© DeLorme. Topo North America™ 9.

www.delorme.com

