1/1

1625 N. French Dr., Hobbs, NM 88240 District 11 District 1

State of New Mexico **Energy Minerals and Natural Resources**

Form C-141 Revised August 8, 2011

1625 N. French Dr., Propos, J.M.

District II

811 S. First St., Artesia, NM 88210

District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

PECEIVED

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action						
	OPERAT			l Report	Final Report	
Name of Company Chevron Address 1400 Smith Street, Houston, TX 77002	Contact		y Summers			
Facility Name Well Brininstool 25-23-33 USA 002H		Telephone No. 832-714-0719 Facility Type Drilling and completions				
Surface Owner Brininstool XL Ranches Mineral Own						
LOCATION OF RELEASE						
	orth/South Line	Feet from the	East/West Line	County	1	
	ft FNL					
LatitudeN32° 16.921 LongitudeW103° 31.699						
NATURE OF RELEASE						
Type of Release Hydraulic fracturing gel Source of Release Frac pop-off line running to flow back half tanks		Volume of Release 7 barrels Volume Re			ecovered 6.75 barrels Hour of Discovery	
•	4/28/2014	4/28/2014 at 3:00 AM 4/28/2014			at 3:03 AM	
Was Immediate Notice Given? ☐ Yes ☐ No ☒ Not Requi	If YES, To	If YES, To Whom?				
By Whom?		Date and Hour				
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Vo	If YES, Volume Impacting the Watercourse.				
If a Watercourse was Impacted, Describe Fully.*						
N/A						
Describe Cause of Problem and Remedial Action Taken.* Mechanical failure during flowback. A sudden high pressure was released to the pop-off line which was rigged up to the flowback open-top tank causing the line to jolt itself loose from the chain. As the result, the opening of the line moved toward the edge of the tank and spilled hydraulic fracturing gel outside the tank. Equipment was shut off for inspection immediately after the spill was discovered. The pop-off line was repositioned to securely connect to the gas buster instead.						
Describe Area Affected and Cleanup Action Taken.* A 20'x20' area around the flowback tanks, Ground surface was covered with a thick layer of crutched-rock foundation. The spill didn't come in contact with actual soil. No spill ran off of the well pad. Workers immediately shut down the equipment to stop the flow. 6.36 bbls of spill was captured in a secondary containment. Approximately 7 bbls of the spill went on ground. A vacuum truck recovered 6.75 bbls off the ground. The recovered spill and contaminated soil were sent to an approved disposal facility.						
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.						
		OIL CONSERVATION DIVISION				
Signature:						
Printed Name: Bikky Summers	Approved by	Approved by Environmental Specialist:				
Title: D&C Waste and Water Specialist	Approval Dat	pproval Date: 5-13-14 Expiration Date: 7-14-14			14-14	
E-mail Address: BSummers@Chevron.com	Conditions of	conditions of Approval:				
	Site som	Site samples required and Attached			LI RAD	
Date: 5/12/2014 Phone: 832-714-0719 delinitre and remediate Attach Additional Sheets If Necessary The area as per NMOCO 05-14-3						

guides, submit Final C-141 by 7-14-14.

MAY & 4 2014

