


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Release Notification and Corrective Action

n HMP 1415734365

| | | | |
|---|--|--|---------------------------------------|
| OPERATOR | | <input checked="" type="checkbox"/> Initial Report | <input type="checkbox"/> Final Report |
| Name of Company: Linn Operating <i>269324</i> | | Contact: Brian Wall | |
| Address: 2130 W. Bender Hobbs, NM 88240 | | Telephone No.: 575-738-1739 | |
| Facility Name: H E West B #58 | | Facility Type: Oil Producer | |
| Surface Owner: Federal | | Mineral Owner: | |
| | | API No.: 30-01527311 | |

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| C | 10 | 17S | 31E | 1305 | North | 2625 | West | Eddy |

Latitude: 32.8527476727543 Longitude: -103.857625755191

NATURE OF RELEASE

| | | |
|--|--|---|
| Type of Release: Produced Water | Volume of Release: 20 bbls | Volume Recovered: 0 |
| Source of Release: Fiber glass pipeline | Date and Hour of Occurrence: 06/01/2014 | Date and Hour of Discovery: 06/01/2014 0900 |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? Jennifer Van Curren- BLM Mike Bratcher- NM OCD | |
| By Whom? Brian Wall | Date and Hour 06/02/2014 0815 | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |
| If a Watercourse was Impacted, Describe Fully.*: | | |
| Describe Cause of Problem and Remedial Action Taken.*: Release was caused by failure in 2" HP fiberglass line. Split in line appears to be from deterioration of line due to age. Line is located at South East corner of location. Line was isolated and is scheduled to be fixed. | | |
| Describe Area Affected and Cleanup Action Taken.*: Released fluid in a fine area measuring approximately 15x20 ft, and pooled in an area around line approximately 20x30 ft. Total fluid release is estimated at 20 BBL. Fluid could not be picked up due to absorption. Delineate site and turn in CAP to BLM and OCD. Remove contaminated soils and haul to approved disposal. Return clean soils to void and return to natural terrain. | | |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. | | |

| | | | |
|--------------------------------------|--|--|----------------------------|
| Signature: <i>Brian Wall</i> | | OIL CONSERVATION DIVISION | |
| Printed Name: Brian Wall | | Approved by District Supervisor: <i>[Signature]</i> | |
| Title: Construction Foreman II | | Approval Date: <i>6/6/14</i> | Expiration Date: <i>NA</i> |
| E-mail Address: bwall@linnenergy.com | | Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION | |
| Date: 06/02/2014 Phone: 806-367-0645 | | Attached <input type="checkbox"/> | |

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:

7/6/14

2 RP-2327

Bratcher, Mike, EMNRD

From: McCracken, Theresa <TMcCracken@linnenergy.com>
Sent: Monday, June 02, 2014 8:42 AM
To: jvancure@blm.gov; Bratcher, Mike, EMNRD
Cc: Callahan, Terry; Moreno, Laura; Butters, Thomas; Gonzales, EL; Wall, Fred; Hickert, Aaron; hconder@rice-ecs.com; lweinheimer@rice-ecs.com; jkamplain@rice-ecs.com
Subject: Linn- HE West B #58 6-1-14
Attachments: West B # 58 6-1-14.pdf

Please find attached the initial C-141 for the above referenced location.

Thank you,



Theresa McCracken

Field Administrator

LINN Energy, LLC

2130 W Bender

Hobbs, NM 88240

T: 575-738-1739 / F: 575-738-1740

tmccracken@linnenergy.com

This electronic message, together with any attachments, contains information from LINN Energy that may be confidential and intended solely for the use of the addressee only. If you are not the intended recipient, please note that any disclosure, dissemination, distribution or copying of this message, or any attachment, is strictly prohibited. Also, please notify the original sender by return e-mail and delete the message, along with any attachments, from your computer. Finally, the recipient should check this email and any attachments for the presence of viruses. The organization accepts no liability for any damage caused by any virus transmitted by this email.


Bratcher, Mike, EMNRD

From: Wall, Fred <BWall@linnenergy.com>
Sent: Monday, June 02, 2014 8:16 AM
To: Briggs, Briklynd; Tarman, Barry; Akin, Bob; Frick, Daniel; Gordon, Debra; Hayes, Jess; Simpson, Judy; Hernandez, Joe; Charbonneau, Jennifer; Moreno, Laura; Butters, Thomas; McCracken, Theresa; Callahan, Terry; Willbanks, Lena; Rickman, Rick; Maier, John; Pena, Kristal; Gonzales, EL; Rodriguez, Leslie; Hickert, Aaron; Pugliese, Blaire
Cc: ngladden@diversifiedfsi.com; Michael Patterson (mpatterson@diversifiedfsi.com); jvancure@blm.gov; Bratcher, Mike, EMNRD
Subject: Spill Report West B #58
Attachments: West B #58 6-1-14 Spill.xls

All;
Attached is a reportable spill report for the West B #58.

30-015-27311

Brian Wall
Construction Foreman II
Office: (432) 363-9372
Cell: (806) 367-0645
Fax: (432) 366-1574
bwall@linnenergy.com



This electronic message, together with any attachments, contains information from LINN Energy that may be confidential and intended solely for the use of the addressee only. If you are not the intended recipient, please note that any disclosure, dissemination, distribution or copying of this message, or any attachment, is strictly prohibited. Also, please notify the original sender by return e-mail and delete the message, along with any attachments, from your computer. Finally, the recipient should check this email and any attachments for the presence of viruses. The organization accepts no liability for any damage caused by any virus transmitted by this email.

Spill / Release Report



Incident Date: 6/1/2014

Incident Time: 9:00:00 AM

Location Information

Completion
or Unit
Lease Code:

EH&S Rep: Only By An EH&S Rep.

Date:

| | | | |
|-------------|----------------|---------------------|--------------------------------|
| Division: | Houston Region | State: | New Mexico |
| Department: | Production | Lease Name & No: | H.E. West B #58 |
| Area: | Hobbs | Legal: | LC-029426-B, Sec 10 T17S, R31E |
| Rig Name: | | County: | |

Type and Location

| | | | |
|--|-------------|--------------------------|-------|
| Spill/Release Type: | Land | Inside Dike Area: | No |
| Latitude: | 0 " N | Longitude: | 0 " W |
| Facility: | Water Flood | Were There Any Injuries? | No |
| (If yes, must also fill out Injury Report) | | | |

| | | | |
|-------------------------|---|---------------------|--|
| Nearest City: | Loco Hills | | |
| Directions to Site: | From intersection US 82 and Eddy County 2221 north on 221 for 1.4 mi, turn right for .5 mi. to Y, stay right and follow road for .6 mi turn left and follow road for .5 mi, turn right follow road for 2 mi. turn right for .2 and left for .2, left for .1 and right for .1. | | |
| Source Type: | | | |
| Body of Water Impacted: | No | Name Body Of Water: | |

Description of Incident and Cause Analysis

Release was caused by failure in 2" HP fiberglass line. Split in line appears to be from deterioration of line due to age. Line is located at South East corner of location. Released fluid in a fine area measuring approximately 15x20 ft, and pooled in an area around line approximately 20x30 ft. Total fluid release is estimated at 20 BBL. Fluid could not be picked up due to absorption. Line was isolated and is scheduled to be fixed.

| | |
|--|-------------------|
| Company Name: if caused by contractor - contractor information | |
| Address | City, State, Zip: |
| Phone: | Contact Person: |

Personnel Information

| | | | |
|-----------------|--------------|--------|--------------|
| Lease Operator: | Matthew Vela | Phone: | 575-399-9837 |
| Remarks: | | | |
| Supervisor: | Rick Rickman | Phone: | 575-513-8825 |
| Remarks: | | | |

Containment/Clean Up

| |
|---|
| Cleaned Date: _____ Time: _____ By: _____ |
| Containment/Cleanup Description: |
| |
| Waste Handling Description: |
| Delineate site and turn in CAP to BLML and OCD. Reove contaminated soils and haul to approved disposal. Return clean soils to void and return to natural terrain. |
| Containment/Cleanup Costs: _____ Oil Loss Cost: _____ |

Weather

| |
|--|
| Wind Direction: <u>South</u> Wind Speed: <u>10</u> Wind Speed UOM: _____ |
| Temperature: <u>90</u> Fahrenheit Temperature UOM: _____ |
| Weather Conditions: <u>Clear</u> |

Substance

| | |
|---|---|
| Number Substances Were Released? <u>1</u> | |
| SUBSTANCE 1 | |
| Substance Released: <u>Crude Oil</u> | Volume Released: <u>0</u> Volume Recovered: <u>0</u> |
| Volume Type: <u>Select One</u> | Amount Lost: <u>0</u> |
| SUBSTANCE 2 | |
| Substance Released: <u>Produced Water</u> | Volume Released: <u>20</u> Volume Recovered: <u>0</u> |
| Volume Type: <u>Select One</u> | Amount Lost: <u>20</u> |
| SUBSTANCE 3 | |
| Substance Released: <u>Select One</u> | Volume Released: <u>0</u> Volume Recovered: <u>0</u> |
| Volume Type: <u>Select One</u> | Amount Lost: <u>0</u> |

| | |
|---------------------------|--|
| Slick Present: <u>Yes</u> | Was a CERCLA Hazardous substance Released? <u>No</u> |
|---------------------------|--|

| External Agency Name | Reported to | Reported By | Verbal / Written | Date / Time |
|----------------------|---------------------|-------------|------------------|-------------|
| 1 BLM | Jennifer Van Curren | Brian Wall | Written | 6-2-14 0815 |
| 2 OCD | Mike Bratcher | Brian Wall | Written | 6-2-14 0820 |
| 3 | | | | |

| | |
|--|---|
| Equipment Type: <u>Pipeline-FG</u> | Specific Cause: <u>Normal Degradation</u> |
| If not listed enter on line below: _____ | If not listed enter on line below: _____ |

| | |
|---|---------------------------------------|
| For EH&S Department Only | |
| Contributing Factors: <u>SELECT ONE</u> | Weather Conditions: <u>SELECT ONE</u> |