<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III
70 Rio Brazos Road, Aztec, NM 87410 Oct IV J. S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division Santa Fe, NM 87505

**Release Notification and Corrective Action** 

RECEIVED

Form C-141 Revised October 10, 2003 JUN 06 2014

Submit 2 Copies to appropriate

NMOCD ARTES A with Rule 116 on back
side of form

1220 South St. Francis Dr.

HMPIL						OPERATOR			Initial Report		
Name of Co		COG OPERA					Robert Mc				
ddress 600 West Illinois Avenue, Midland, TX 79701 acility Name Birdseye 32 State #001H						Telephone No. 432-230-0077					
acility Nam	B	Biraseye 32 S	tate #UU1F	1	Facility T	ype	Tank Batt	ery			
Surface Owner State Mineral Owner						Lease No. (API#) 30-015-38295					
				LOC	ATION OF R	ELEASE					
nit Letter O	Section 32	Township 19S	Range 31E	Feet from the	North/South Line	Feet from the	East/	West Line	County Eddy		
					_	tude 103.89014					
			······································	NA	TURE OF RE	<del>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</del>		1301			
ype of Release Produced water						Volume of Release 40bbls			Volume Recovered 40bbls		
ource of Rei						Date and Hour of Occurrence			Date and Hour of Discovery		
waterline						05-31-2014 05-			i-31-2014 1:30pm		
	e Notice Give	⊠ Ye	s 🗆 No	☐ Not Required		To Whom?		ratcher - NM0	000		
By Whom? Michelle Mullins						nd Hour 06-02-2014					
Nas a Watercourse Reached? ☐ Yes ☑ No					If YES,	Volume Impacting th	ne Waterco	urse.			
ş .					#						
a Watercour	se was Impac	ted, Describe F	ully.*	**************************************			***				
escribe Caus	e of Problem	ted, Describe F	Action Take		nks developed a h	eak. We replaced the	e 4" steèl li	ine with a new	v joint.		
escribe Caus 4" waterline	e of Problem	ted, Describe F	Action Take		nks developed a l	eak. We replaced the	e 4" steèl lí	ine with a new	v joint.		
escribe Caus 4" waterline escribe Area itially 40bbls ee fluid has b	e of Problem going from th Affected and of produced veen recovere	and Remedial e heater treater Cleanup Action	Action Take and the FV Taken.* ased. We w nated grave	VKO to the water tar	40bbls of produce	eak. We replaced the d water with a vacuu en steam cleaned an	um truck. Ti	he spill was o	contained inside the		
escribe Caus  4" waterline escribe Area tially 40bbls es fluid has be eation has be ereby certify erators are re e acceptance estigate and	going from the Affected and of produced ween recovered in that the information of a C-141 in remediate occurrence occurrenc	and Remedial Any contamino oils prior condition given all port and/or file creport by the Nitronal and Remedial and Remedi	Action Taken and the FV and the FV ased. We wanted grave tion.	ere able to recover all has been removed and complete to the se notifications and ked as "Final Report reat to ground water	40bbls of produce I, the liner has bed best of my know perform corrective does not relieve I, surface water, h	ed water with a vacuuren steam cleaned an ledge and understan e actions for release the operator of liabilituman health or the e	um truck. Ti nd we has r nd that purs s which ma lity should to environmer	he spill was or eplaced with suant to NMO ay endanger pather operation. In addition	contained inside the fresh gravel as ned CD rules and regul public health or the ns have failed to ac	ations all environment.	
escribe Caus  4" waterline escribe Area tially 40bbls es fluid has be eation has be ereby certify erators are re e acceptance estigate and	going from the Affected and of produced ween recovered in that the information of a C-141 in remediate occurrence occurrenc	and Remedial Any contamino oils prior condition given all port and/or file creport by the Nitronal and Remedial and Remedi	Action Taken and the FV and the FV ased. We wanted grave tion.	ere able to recover all has been removed and complete to the se notifications and ked as "Final Report reat to ground water	40bbls of produce I, the liner has bed best of my know perform corrective does not relieve I, surface water, h	ed water with a vacuu en steam cleaned an ledge and understan e actions for release the operator of liabil tuman health or the e ate, or local laws and	um truck. To nd we has r and that purs as which ma lity should to environmen d/or regulat	he spill was or eplaced with suant to NMO ay endanger pather operation. In addition	contained inside the fresh gravel as ned CD rules and regul public health or the ns have failed to accepta	ations all environment.	
escribe Caus  4" waterline escribe Area  tially 40bbls e fluid has be eation has be ereby certify erators are re e acceptance estigate and out does not	going from the Affected and of produced ween recovered in that the information of a C-141 in remediate	and Remedial and Remedial are heater treater Cleanup Action water were relead. Any contamino its prior condition given about and/or file coreport by the Nitontamination the perator of response.	Action Taken and the FV and the FV ased. We wanted grave tion.	ere able to recover all has been removed and complete to the se notifications and ked as "Final Report reat to ground water	40bbls of produce I, the liner has bed best of my know perform corrective does not relieve I, surface water, h	ed water with a vacuu en steam cleaned an ledge and understan e actions for release the operator of liabil tuman health or the e ate, or local laws and	um truck. To nd we has r and that purs as which ma lity should to environmen d/or regulat	he spill was of the spill was to the spill was to NMO ay endanger parties on the spill was to the spill was	contained inside the fresh gravel as ned CD rules and regul public health or the ns have failed to accepta	ations all environment.	
escribe Caus 4" waterline escribe Area tially 40bbls e fluid has be ereby certify erators are re e acceptance estigate and cort does not mature:	going from the Affected and of produced ween recovered in that the information of a C-141 in remediate	and Remedial and R	Action Taker and the FV Taken.*  ased. We wanted grave tion.  bove is true pertain released MOCD marked pose a the pose at the posibility for	ere able to recover all has been removed and complete to the se notifications and ked as "Final Report reat to ground water	40bbls of produce I, the liner has been best of my know perform corrective does not relieve r, surface water, hy other federal, st	ed water with a vacuu en steam cleaned an ledge and understan e actions for release the operator of liabil tuman health or the e ate, or local laws and	um truck. The distribution of that pursus which maility should the environmend or regular ONSER	he spill was of the spill was to the spill was to NMO ay endanger properation and the spill in additions.	contained inside the fresh gravel as ned CD rules and regul public health or the ns have failed to accepta	ations all environment.	
escribe Caus  4" waterline escribe Area tially 40bbls e fluid has be ereby certify erators are re e acceptance estigate and oort does not inature:  Inted Name:	going from the Affected and of produced ween recovered that the information of a C-141 in remediate control of the control of	and Remedial and Remedial are heater treater Cleanup Action water were relead. Any contamino its prior condition given about and/or file coreport by the Nitontamination the perator of response.	Action Taker and the FV Taken.*  ased. We wanted grave tion.  bove is true pertain released MOCD marked pose a thousibility for the bbs Jr.	ere able to recover all has been removed and complete to the se notifications and ked as "Final Report reat to ground water compliance with an	40bbls of produce I, the liner has been best of my know perform corrective does not relieve r, surface water, hy other federal, st	ed water with a vacuus en steam cleaned and ledge and understance actions for release the operator of liability and health or the eate, or local laws and OIL Corp.	um truck. To nd we has r and that purs as which ma lity should the environment d/or regulation	he spill was of the spill was to the spill was to NMO ay endanger properation and the spill in additions.	contained inside the fresh gravel as ned CD rules and regul public health or the ns have failed to ach, NMOCD accepta	ations all environment.	
escribe Caus  4" waterline escribe Area tially 40bbls es fluid has be eation has be ereby certify erators are re e acceptance estigate and	going from the Affected and of produced ween recovere that the informequired to repend a control of the control	and Remedial and R	Action Take and the FV Taken.*  ased. We wanted grave tion.  bove is true certain relea MOCD mark at pose a th onsibility for  bbs Jr.  at Coordina	ere able to recover all has been removed and complete to the se notifications and ked as "Final Report reat to ground water compliance with an	40bbls of produce I, the liner has been best of my know perform corrective does not relieve r, surface water, h y other federal, st  Approved to	ed water with a vacuus en steam cleaned and ledge and understance actions for release the operator of liability and health or the eate, or local laws and OIL Corp.	um truck. To nd we has r and that purs as which ma lity should the environment d/or regulation	he spill was of the spill was to the spill was to NMO ay endanger public in the spill in the spi	contained inside the fresh gravel as ned CD rules and regul public health or the ns have failed to ach, NMOCD accepta	ations all environment.	
escribe Caus 4" waterline escribe Area tially 40bbls ee fluid has be ereby certify erators are re e acceptance estigate and cort does not gnature: nted Name:	going from the Affected and of produced ween recovere the returned to required to required to reflex the control of the contro	and Remedial and Remedial are heater treater Cleanup Action vater were relead. Any contamino its prior condition given about and/or file creport by the Nitronamination the perator of response of the perator of	Action Take and the FV Taken.* Taken.*  ased. We wented grave tion.  bove is true ertain relea MOCD mark at pose a th onsibility for bbs Jr.  al Coordina ho.com	ere able to recover all has been removed and complete to the se notifications and ked as "Final Report reat to ground water compliance with an	40bbls of produce I, the liner has been best of my know perform corrective does not relieve r, surface water, h y other federal, st  Approved to	ed water with a vacuum en steam cleaned and ledge and understance actions for release the operator of liability and health or the eate, or local laws and OIL Computer of the control of the late.	um truck. To nd we has r and that purs as which ma lity should the environment d/or regulation	he spill was of the spill was to the spill was to NMO ay endanger public in the spill in the spi	contained inside the fresh gravel as need to be fresh gravel as need to be fresh gravel and reguloublic health or the ms have failed to acceptant to be fresh from the fresh f	ations all environment.	

## Bratcher, Mike, EMNRD

From:

Robert Grubbs < RGrubbs@concho.com>

Sent:

Friday, June 06, 2014 11:12 AM

To:

Bratcher, Mike, EMNRD

Cc:

Robert McNeill; Production Mail

Subject:

C-141 Initial/Final Report - Birdseye 32 State #001H (TB)

Attachments:

05-31-2014 Birdseye 32 State #001H (TB) Initial - Final.pdf

## Mr. Bratcher,

Please see attached the C-141 Initial/Final Report for a release that occurred at our Birdseye 32 State #001H (TB) on 05-31-2014 in Eddy County New Mexico. This is a lined facility.

## Thank you,

Robert Grubbs Jr. Sr. Environmental Coordinator 432.683.7443 (main) 432.818.2369 (direct) 432.661.6601 (cell) rgrubbs@concho.com Mailing Address: One Concho Center 600 W. Illinois Avenue Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.