HOBBS OCD

District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 JUN 2 7 2014 District III 1000 Rio Brazos Road, Aztec, NM 87410

District IV 1220 S. St. Francis Dr., Santa Fe, NM 875GEIVED State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

JUN 3 0 2014

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

					OPERATOR			☐ Initial Report ☐ Final Report					
Name of Company Devon Energy						Contact Kenny Kidd							
Address PO	Box 250	Artesia, NM		7	Telephone No. 575- 513-8545								
Facility Name Penny Packer 17 State 1H						Facility Type Oil							
Surface Ow	ner: State	of New Mex	wner: \$	State of New Mexico			API No. 30-025-40681						
				LOCA	TION	N OF REI	LEASE						
						n/South Line Feet from the East/West Line County							
О	O 17 21S 34E 330				S	DUTH 1980 East LEA				LEA			
Latitude: N32°28'21.06" Longitude: W103°29'23.50"													
NATURE OF RELEASE													
Type of Rele			Volume of Release 20bbls Volume Recovered 17.5bbls					3					
Source of Release: Crack on housing of the lact unit pump							lour of Occurrence	I .	Date and Hour of Discovery				
Was Immedia	ate Notice C	Given?	June 18, 2014 7:45 AM June 18, 2014 7:45 AM If YES, To Whom? If YES, To Whom?										
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required													
,						Lease Operator/Amancio Cruz-EHS/Roy White-Sr Production							
						Foreman/OCD-Voicemail							
By Whom? Zaul Alvarado							Date and Hour: June 18, 2014 7:45 AM						
Was a Water		ched?		If YES, Volume Impacting the Watercourse.									
] No										
If a Watercourse was Impacted, Describe Fully.* Depth to 9 1/20 -> 100 1													
100 / Start 10 19 100 /													
Describe Cause of Problem and Demedial Action Taken *At the Penny Deckor 17 State #1 the losse energtor discovered that the baseing on													
Describe Cause of Problem and Remedial Action Taken.*At the Penny Packer 17 State #1, the lease operator discovered that the housing on the lact unit pump cracked resulting in a 20 barrel oil release. The lease operator closed the valve to the lact unit and notified Basic													
				overed from the									
		and Cleanup A											
	ected withi	n the facility	was 88 fe	et wide by 22 feet	long.	Talon LPE v	vas contacted to	perform	the site as	ssessment a	ınd soil	sampling	
activities.													
I hereby certi	fy that the i	nformation gi	ven above	is true and compl	ete to th	ne best of my	knowledge and u	ınderstand	d that purs	uant to NM	OCD rt	iles and	
				nd/or file certain re									
				e of a C-141 report investigate and re									
				tance of a C-141 r									
		ws and/or regu						, , , , , , , , , , , , , , , , , , , ,		F			
G:				OIL CONSERVATION DIVISION									
Signature: Ghammy Ingram													
Printed Name: Shammy Ingram						Approved by Environmental Specialist:							
Title: Field A	dmin Suppo	rt		- 4	Approval Da	e: 6-17-14	E	xpiration I	Date: 8-2	2-/9			
E-mail Addre	ss: Shamn	ıy. Ingram@e			Conditions o	f Approval: c~	. e 1.						
					Conditions of Approval: Size Supples required. Attached [Peliniated muchastrum site 45 per mood 6-14-312]								
Date: June 2		F											
Attach Additional Sheets If Necessary 9vides. UC-141 dec by 8-21-14 0grid 6137												6137	
						Fi∿	•			N-	TO 14	7076 90	