District 1
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

* Attach Additional Sheets If Necessary

State of New Mexico Energy Minerals and Natural Resources

AUG 06 2014

RECEIVED

Form C-141 levised August 8, 2011

NMSubmire Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action **OPERATOR** Initial Report Final Report Contact 25575 Yates Petroleum Corporation Robert Asher Address Telephone No. 104 S. 4th Street 575-748-4217 Facility Name Facility Type Kent BSK #1H Battery Surface Owner Mineral Owner API No. Fee Fee 30-015-40161 LOCATION OF RELEASE East/West Line Unit Letter Feet from the North/South Line County Section Township Feet from the Range P 20 18**S** 26E 400 South 330 East Eddy Latitude 32.72711 Longitude 104.39612 NATURE OF RELEASE Type of Release Volume of Release Volume Recovered Produced Water 15 B/PW 13 B/PW Source of Release Date and Hour of Occurrence Date and Hour of Discovery Water tank 7/21/2014; AM 7/21/2014; AM Was Immediate Notice Given? If YES, To Whom? N/A By Whom? Date and Hour N/A Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. ☐ Yes 🛛 No If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* A water pump malfunction caused the tank to overflow. Vacuum trucks called Describe Area Affected and Cleanup Action Taken.* An approximate area of 20' X 50' was affected within the lined/bermed battery. Vacuum truck was called to recover produced water. The remaining produced water (2 bbl) was entrenched in the sand and gravel within the lined berm and left to evaporate. Depth to Ground Water: 50-90' (approximately 90', Section 20, T18S-R26E, per Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 10. Based on battery being lined/bermed and all produced water recovered, Yates Petroleum Corporation requests closure. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Approved by Environmentally, Printed Name: Robert Asher Title: NM Environmental Regulatory Supervisor **Expiration Date:** Conditions of Approval: E-mail Address: boba@yatespetroleum.com Attached Date: July 28, 2014 Phone: 575-748-4217

Bratcher, Mike, EMNRD

From:

Tanna Adams <TCAdams@yatespetroleum.com>

Sent:

Wednesday, August 06, 2014 9:01 AM

To:

Bratcher, Mike, EMNRD

Cc:

Patterson, Heather, EMNRD; Bob Asher

Subject:

Kent BSK #1H

Attachments:

Kent BSK 1.pdf; Kent BSK 1H.pdf

Mr. Bratcher,

Please find attached the signed C141 Initial/Final reports for the below listed location:

Kent BSK #1H 30-015-40161 Section 20, T18S-R26E 400' FSL & 330' FEL Eddy County, New Mexico

Thank you,

Tanna Adams

Yates Petroleum Corporation Environmental Tech Environmental Department TCAdams@yatespetroleum.com

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.