

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*NA 1424049543*

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company: COG Operating LLC	<i>229137</i>	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701		Telephone No. 432-230-0077	
Facility Name: Hambone Fee Com #1		Facility Type: Battery	

Surface Owner: Fee	Mineral Owner:	API No. 30-015-38980
--------------------	----------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	5	26S	29E	660'	South	330'	West	Eddy

Latitude N32°03.960 Longitude W104°00.830

**NATURE OF RELEASE**

Type of Release: Oil and Produced Water	Volume of Release: Oil: 5 bbls ; PW: 33 bbls	Volume Recovered: Oil: 4 bbls ; PW: 25 bbls
Source of Release: Fiberglass Tank	Date and Hour of Occurrence: 8-25-2014 6:30 pm	Date and Hour of Discovery: 8-25-2014 8:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

**NM OIL CONSERVATION**

If a Watercourse was Impacted, Describe Fully.\*

ARTESIA DISTRICT  
SEP 02 2014

Describe Cause of Problem and Remedial Action Taken.\*

RECEIVED

The release was caused by a newly set fiberglass water tank. As the water tank settled a crack formed causing the leak. A vacuum truck was dispatched to remove all standing fluids and a new tank set.

Describe Area Affected and Cleanup Action Taken.\*

The release occurred within the lined bermed facility. Gravel was excavated and replaced. All recovered fluids were disposed of at an NMOCD approved facility.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Senior Environmental Coordinator	Approval Date: <i>9/3/14</i>	Expiration Date: <i>N/A</i>
E-mail Address: <a href="mailto:atrujillo@concho.com">atrujillo@concho.com</a>	Conditions of Approval: <i>Final</i> — Attached <input type="checkbox"/>	
Date: August 29, 2014	Phone: 575-748-6940	

\* Attach Additional Sheets If Necessary

*2RP-2468*

## **Patterson, Heather, EMNRD**

---

**From:** Amanda Trujillo <ATrujillo@concho.com>  
**Sent:** Friday, August 29, 2014 2:29 PM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD  
**Subject:** (Notification/C-141 Initial-Final) Hambone Fee Com #1 (30-015-38980)

Mr. Bratcher,

COG Operating LLC is reporting a release at the **Hambone Fee Com #1 (30-015-38980)**.

Unit M Section 5 Township 26S Range 29E

The release occurred at 8:00 pm on 08/25/2014.

**Released:** 5 bbls Oil ; 33 bbls PW

**Recovered:** 4 bbls Oil ; 25 bbls PW

This release was caused by a crack in the fiberglass tank that formed as a result of settling. The release occurred in a lined facility. Attached is a C-141 Initial/Final for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

### **Amanda Trujillo**

Senior Environmental Coordinator

COG Operating LLC

Cell: 505.350.1336

Office: 575.748.6930

[atrujillo@concho.com](mailto:atrujillo@concho.com)

2208 W. Main St.

Artesia , NM 88210



**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.