

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

HOBBS OCD

SEP 22 2014

RECEIVED

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	CJ Summers
Address	1017 W. Stanolind Rd, Hobbs, NM	Telephone No.	(575) 397-8216
Facility Name	CE Lamunyon # 74	Facility Type	Well location
Surface Owner	Jimmy Weir	Mineral Owner	API No. 30-025-35060

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	27	23S	37E	1310	North	1515	West	Lea

Latitude N 32.27893° Longitude W 103.15399°

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	2 bbls oil, 8 bbls produced water	Volume Recovered	0 bbls
Source of Release	A piece of rubber was stuck in the back pressure valve which caused the stuffing box packing on the wellhead to blow out	Date and Hour of Occurrence	05/11/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey Leking, NMOCD		
By Whom?	Kathy Purvis, BBC International	Date and Hour	05/12/2014 @ 3:05 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A piece of rubber got stuck in the back pressure valve which caused the stuffing box packing to blow out on the well head and spill 2 bbls of oil and 8 bbls of produced water onto the ground. The piece of rubber was removed, the stuffing box packing was replaced, and no fluids were recovered.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 10' x 90' on location. Remediation will be completed in accordance a remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Chancey Summers	Approved by District Supervisor: <u>Chancey Summers</u>		
Title: HES Specialist	Approval Date: <u>9-22-14</u>	Expiration Date: <u>11-22-14</u>	
E-mail Address: Chancey.Summers@oxy.com	Conditions of Approval: <u>Site Supervisor required</u> <u>Relocate &amp; conduct new survey</u> <u>NMOCD g. only. Submit final</u> <u>C-141 by 11-22-14.</u>		Attached <input type="checkbox"/> <u>12P-13370</u> <u>09712 10696</u>
Date: <u>5-19-14</u> Phone: (575) 397-8216			

\* Attach Additional Sheets If Necessary

SEP 22 2014

NTD 1426 544121  
PTD 1426 544265