

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

HOBBS OGD

Form C-141  
Revised August 8, 2011

SEP 22 2014  
Submitting Company to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Manda B Tract C Tank Battery	Facility Type	Tank Battery

Surface Owner	BLM	Mineral Owner		API No.	30-025-25438
---------------	-----	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	28	22S	37E					Lea County, NM

Latitude N 32.36877° Longitude W 103.16985°

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	40 bbls mix	Volume Recovered	0 bbls
Source of Release	Water dump on separator malfunctioned and caused the oil tanks to overflow	Date and Hour of Occurrence	03/17/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey Leking, NMOCD and Jennifer VanCuren, BLM		
By Whom?	Kathy Purvis	Date and Hour	03/17/2014 @ 3:08 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The water dump on the separator malfunctioned and caused the oil tanks to overflow spilling 40 bbls of oil and produced water onto the ground. No fluids were recovered and the water dump issue was resolved.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 8' x 80' on location. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:

Printed Name: Chancey Summers

Title: HES Specialist

E-mail Address: Chancey.Summers@oxy.com

Date: 9-15-14 Phone: (575) 397-8216

OIL CONSERVATION DIVISION

Approved by Environmental Specialist:

Approval Date: 9-22-14

Expiration Date: 11-22-14

Conditions of Approval:

Site Specific report

Attached ☐

IRP-3344

\* Attach Additional Sheets If Necessary

Detected 2 inches area as per  
NMOCD guidance - Submit final  
C-141 by 11-22-14

ogrid 16696  
N70 1426 547353  
p 701426 547526

SEP 22 2014